

Plans wh. he treats timber -

for treatment -

Presses for timber -

David Glover

An internal Briefing

BACKGROUND	2
FIRE BRIGADE OBSERVATIONS	3
BUILDING REGULATIONS	4
Surface Flame Spread	4
Combustibility of Materials	4
Subdivision Of Cavities	4
Regulations in Scotland	5
Revisions to the Approved Document	5

Background

An elderly man (Alexander Linton, 55) died and five other people were slightly injured when fire spread through a 14-storey block of flats in Ayrshire. Nine floors of the building in Irvine were damaged in the fire, which broke out about 1245 on Friday 11 Jun 1999.

A turntable ladder was used to rescue four adults and a 15-month-old child. Eyewitnesses said the tower block ignited like matchwood, prompting concerns about materials used in the construction of the external windows and cladding.

North Ayrshire Council has been quoted as saying it has ordered the removal of plastic cladding and PVC window frames as a precaution "at whatever cost".

MPs on the Commons Environment Sub-Committee have asked for an investigation into the use of certain building materials in tower blocks following Mr. Linton's death.

Cladding free.

Knowsley Hts -
5.4.91 -

Estates Act in
canis cream - white free at
base spd up or behind -

Mercantile Ct.
3.5.91

- Oxid spd up behind glass curtain
walling.

Milton Keynes -
13.3.95 -

High Adre



BBC ONLINE NETWORK

HOMEPAGE | SITEMAP | SCHEDULES | BBC INFORMATION | BBC EDUCATION | BBC WORLD SERVICE

BBC NEWS

News in Audio

News in Video

Newyddion

Новости

Noticias

أخبار 國際新聞 粵語廣播

[Front Page](#)[World](#)[UK](#)[UK Politics](#)[Business](#)[Sci/Tech](#)[Health](#)[Education](#)[Sport](#)[Entertainment](#)[Talking Point](#)[In Depth](#)[On Air](#)[Archive](#)[Feedback](#)
[Low Graphics](#)
[Help](#)

Wednesday, June 16, 1999 Published at 18:25 GMT 19:25 UK

UK Politics

Tower block fire safety fears



The block of flats where the disabled man died

A council has ordered the removal of certain building materials from all its properties after a tower block fire in which an elderly disabled man died.

North Ayrshire Council says it has ordered the removal of plastic cladding and PVC window frames as a precaution "at whatever cost".

Alexander Linton, 55, died on Friday when fire swept through a 14-storey block of flats in Irvine.



**Chief Executive
Bernard Devine:**
"Tenants' safety is
our foremost
concern"

A turntable ladder was used to rescue four adults and a 15-month-old child. Eyewitnesses said the tower block ignited like matchwood, prompting concerns about materials used in the construction.

Strathclyde Fire Brigade is continuing its investigation into the cause of the blaze.

The council is commissioning independent consultants to investigate the safety of the building materials used in the construction of the flats.

Chief Executive Bernard Devine said it had now ordered the removal of the materials and the introduction of 24-hour security at its flats.

"We've put on 24-hour security and taken the decision, at whatever cost, to remove the cladding and put other cladding in its place."



Mr Devine stressed the council was taking the steps

UK Politics Contents

- [Talking Politics](#)
- [Parliament Live](#)
- [Diary](#)
- [People in Parliament](#)
- [A-Z of Parliament](#)
- [Political Links](#)
- [Despatch Box](#)
- [Westminster Live](#)

Relevant Stories

11 Jun 99 | UK

[Fire hits tower block](#)

Internet Links

[House of Commons](#)[East Ayrshire Council](#)

The BBC is not responsible for the content of external internet sites.

In this section

[Brown: We've only just begun](#)[Farmers target Blair](#)[Gays win military legal battle](#)[Lamont blames Major for 'Black Wednesday'](#)[Reid defends lobby row son](#)[Michael to tell conference of 'new Wales'](#)[Row over drug crimes crackdown](#)[Davies spells out Assembly's 'crucial test'](#)[Blair sets sights on second term](#)[Labour unveils its new star](#)[Blair denies interest in GM](#)[Unionist rules out policy change](#)[Protests greet Labour in](#)



to allay concerns of tenants and said it had not been established that the cladding was to blame for the fatal fire.

But he said the council could not wait for the results of the fire brigade investigation and its own research findings.

Brian Donohoe: Welcomed investigation

"We've not got time to wait for that to come through, we've had to act and we've acted today in order to reassure tenants that their safety is our foremost concern.

"We will take action even if it turns out to be wrong and it may very well be."

MPs on the Commons Environment Sub-Committee have asked for an investigation into the use of certain building materials in tower blocks following Mr Linton's death.



Brian Donohoe MP:
"If there is a risk it's
got to be dealt with"

They want to know if there have been similar fire incidents in other high-rise buildings.

Welcoming the move, Cunninghamham South MP Brian Donohoe said: "Clearly on the basis of the evidence that I saw at first hand it would give the impression that there is something quite wrong in the use of this cladding."

"But it's far too early to speculate and I wouldn't want to raise fears in anybody's minds in terms of the use of this cladding and whether or not it's dangerous."

Search

Advanced options | Search tips

[Back to top](#) | [BBC News Home](#) | [BBC Homepage](#) | ©



Morgan, Penny

From: stephen.whitmore@lfcda.org.uk

Sent: 24 June 1999 13:07

To: andrew.barnett@lfcda.org.uk; mick.beasley@lfcda.org.uk; mick.bell@lfcda.org.uk;
CRAIG.BOWDEN@lfcda.org.uk; norman.brice@lfcda.org.uk; keith.brown@lfcda.org.uk;
dennis.burke@lfcda.org.uk; n.carey@lfcda.org.uk; john.crowley@lfcda.org.uk;
nigel.davison@lfcda.org.uk; MAXIM.DISSANAYAKE@lfcda.org.uk; john.gaffney@lfcda.org.uk;
JOHN.GALVIN@lfcda.org.uk; mick.hetherington@lfcda.org.uk; terry.hodgens@lfcda.org.uk;
steve.janes@lfcda.org.uk; roy.jarrett@lfcda.org.uk; anthony.laver@lfcda.org.uk;
alan.lowe@lfcda.org.uk; pat.lyon@lfcda.org.uk; mick.maddox@lfcda.org.uk;
john.marshall@lfcda.org.uk; JASON.MARSHALL-SMITH@lfcda.org.uk;
barry.pilkington@lfcda.org.uk; RICHARDSONJ@lfcda.org.uk; gordon.rolfe@lfcda.org.uk;
keith.sefton@lfcda.org.uk; bob.shefford@lfcda.org.uk; ian.smith@lfcda.org.uk;
paul.spencer@lfcda.org.uk; dave.townsend@lfcda.org.uk; steve.treadaway@lfcda.org.uk;
anthony.tribe@lfcda.org.uk; andrew.vaughandavies@lfcda.org.uk; sam.winder@lfcda.org.uk

Cc: morganp@bre.co.uk

Subject: fire spread

Penny has asked if any of you have attended a fire where PVC window/door frames or PVC cladding has been instrumental in spreading fire up a high rise building.

Penny is looking at this matter for the DTI and would appreciate any help you can give her.

Please phone her on [REDACTED] or email her at morganp@bre.co.uk

stephen whitmore

cc: Clapham by faxmail.

Morgan, Penny

From: Morgan, Penny
Sent: 24 June 1999 16:24
To: 'AnthonyBurd@dettr.gsi.gov.uk'
Cc: Shipp, Martin
Subject: Cladding fires

Brian,

Knowsley Heights, Liverpool 5.4.91 Deliberate fire outside building spread up and behind rainscreen cladding and in at all 11 floors - Estates Action refurb.scheme.

[Mercantile Credit building Basingstoke 3.5.91 Fire on 8th floor spread up building behind glass curtain walling]

Three storey block with add on roof in Milton Keynes 13.3.95 Fire in middle floor spread up into add-on roof which was destroyed by fire.

Alpha House Coventry 31.1.97 flames travelled up the outside of the block from the 13th to 17th floor. No penetration of flats above - wind assisted fire penetration of adjacent flat ie horizontal spread. No mention of cladding.

Butler House Grays Essex 14.7.97 Fire on top floor flat of 14-storey No Fines concrete block caused uPVC window frames to melt and drip causing some damage to cladding. Building undergoing refurb - huge concerns that cladding had assisted spread. It did not.

That's all I have. Requests for info are currently with major brigades known for high rises. Reactions are to the effect that yes they get smoke penetration up the block but fire/ flame very rare or not at all. London, Mersyside, Tyne and Wear, Greater Manchester and West Mids all contacted.

Chic Stirling of Scotlab recalls one in Royston, Glasgow but damage to cladding was only local to the window of the fire flat. He was talking to a cladding man recently who recalls not getting the job to upgrade the Irvine block. Firm called Sunlight (sic) got it. Chic suspects that the block is No Fines concrete. This could mean that attaching cladding to the building would have been difficult as the material is notoriously awkward to drill.

Dougal Drysdale has visited on behalf of the Procurator Fiscal and is sending me some photos. He tells me that the cladding at Irvine appeared to overlap the window pod so any flames may have acted on both sides of the exposed edge of the cladding.

Home Office stats here at Garston have been asked to do a search - John Gamble is in tomorrow and believe that Des rang you about it earlier today.

regards

P.

Fire Brigade Observations

Notes on a conversation with Div Officer John Russell, Strathclyde Fire Service. (B martin FRS. 24/06/99 22/06/99)

DO Russell attended the fire as an observer his comments relate to his initial impressions of the incident and subsequent discussions with fire fighters on the scene.

1. The fire started by the Living Room window of a fifth floor flat. One fatality occurred within the room (now the subject of an inquiry).
2. The Fire broke out through the window.
3. The windows of the flats are one above the other constructed from UPVC. Between each window is a GRP (or similar) decorative panel. in effect a continuous column of GRP & PVC extended up the height of the block.
4. Flame spread rapidly up the face of the cladding and several of the rooms above the flat of origin caught fire. Fire fighters had to be committed at several floors simultaneously (this is unusual)
5. Before the fire was brought under control it had spread form the 5th floor to the top (13th) floor where it was particularly severe. It was noted that the fire had hit the top of the building and turned in.
6. A turntable ladder was used to rescue four adults and a 15-month-old Child.
7. more than 60 firefighters were involved and the fire took about two hours to bring under control.
8. The reasons for the fire finding its way back into the block have not been established but they could be linked to the following factors
 - many of the windows were open (it was a warm day)
 - the UPVC frames had softened and created a path for fire spread.
 - The detailing of the junction between cladding & windows created a path for fire spread.
9. Investigations by the local authority & the fire service are ongoing.

Building Regulations

A review of Current Guidance in Approved Document B with regard to the control of materials used for cladding tall buildings.

The Guidance in approved document B recognizes the problems associated with the use of combustible cladding & insulation materials. As such provisions are included in the document to control these materials, these are summarized below;

Surface Flame Spread

The speed of flame spread across the surface of materials used on the external face of buildings exceeding 20m high is restricted. (B4 -12.5)

This requirement becomes more onerous where the building is close to its boundary (& therefore other buildings)

The speed of flame spread across the surface of materials used on the internal face of a ventilated cavity for buildings exceeding 20m high is restricted. (B4 -12.6)

Combustibility of Materials

Except in the case of masonry cavity walls designed to prevent fire entering or escaping from the cavity. The combustibility of insulation materials contained in the external walls of buildings exceeding 20m high (in a ventilated cavity or otherwise) is restricted. (B4 12.7)

Subdivision Of Cavities

In flats, maisonettes and certain institutional buildings cavity barriers designed to prevent the passage of fire through continuous voids in the cladding are required (B3 9.2 - 9.11)

In buildings of less than 20m in height combustible materials are permitted subject to the provision of barriers as described above.

Looking for property
near
Cudding for property

Binu Mathu
to visit
Bany 13.0.2



H
Do Jan
attended for
Dore

~~Proctor~~

Proctor
Fiscal

McLENNAN



Proctor
Fiscal
concern
Black & White
Cuddling BSL fairy

~~Proctor~~

✓ for Seade

+ Brian / Martin

+ Proctor fiscal

30 June.

Will call BARRY in to ask
about fri. Same him unemployed
artist - fatality in view of injury.
Syd old regular. PC under + call pod of
view current work - cosmetic.
Not aware of any mutation.

Morgan, Penny

From: Morgan, Penny
Sent: 30 June 1999 16:48
To: Stirling, Charles
Subject: FW: not protectively marked - cladding fire



CLAD.DOC

Chic,

May I formally request your assistance in gathering information on the fatal fire at Irvine on 11 June at 12.45 h. Please contact Hugh Adie on [REDACTED] Strathclyde Fire Brigade, he was kind enough to get DO John Russell to brief Brian Martin, new man at FRS. (Brian is currently standing in for Anthony Burd, our DETR customer. He is using his desk and email, the summary of info he got is attached to this note)

My other brigade contact is Ian Scade Head of Fire Investigation on [REDACTED] but he may be at a conference this week. The general number for the brigade is [REDACTED] - I'll contact them as well.

Please use FG2824 which is my project on Fire Investigation.

I received copies of photos that Dougal Drysdale, Prof at Edinburgh sent to the Procurator Fiscal which I believe you have got too from Sarah Colwell..

Many thanks

Penny

-----Original Message-----

From: ANTHONY BURD [mailto:Anthony_Burd@detr.gsi.gov.uk]
Sent: 24 June 1999 11:25
To: morganp@bre.co.uk
Subject: not protectively marked - cladding fire

Penny

My notes so far

Department of the Environment, Transport & Regions

This email and any files transmitted with it are private and intended solely for the use of the individual or entity to whom they are addressed.

This email does not constitute a commitment by DETR.

Morgan, Penny

From: Morgan, Penny
Sent: 30 June 1999 17:14
To: Stirling, Charles
Subject: Irvine fire

Chic,

no sooner had I sent you my last email than Martin Shipp was on the phone to ask me to contact the Procurator Fiscal, Mr McGlennan. He's on [REDACTED]. He will contact you tomorrow, Thursday and organise the police to take you round the building. He appreciates our interest is in the B Regs context and has asked that any report is copied to him. As the fire may result in a Fatal Accident Inquiry he has asked that you be willing to present your findings to the inquiry. Is this OK with you?

Mr McGlennan is delighted that we will not be charging him for our work as DETR are paying. I stressed that our interest is in how the fire spread vertically and less in the particulars of the fatal fire itself. From the photos we suspect that the timber studding if that is what it is may have played a crucial role in promoting the spread. He confirmed that there are 5 blocks.

I have left a message for Hugh Adie saying that you will be going to look and that Mr McGlennan is arranging it. I'll try and talk to him in the morning.

Penny

1/7

Strathclyde

Hugh. Adre, - he's going on leave
rem. dec. paneling
extⁿ of Sm. detⁿ

Dr. John Russell - can answer
any further ?'s - -

Tom Orr is the Dist
of Propⁿ of Services
for North Ayrshire

2/7

Chie

Been & had an official look.

- the around all the window parts -
JS stand Ferguson - v helpful & co-ord'g the
repairs - Dargal asking for same info as US.
Dargal wants to check stuff he's left behind.
Tom on very edgy re interest - happy to
give - g. contact police -
Plat's details - official request

Took new photo -

Masonry inspected -

g window panels - not a familiar -
went'd over behind window water for

but a loose cladding -

- can't see any drip marks.

= he'll go & take m. photos. JS a Hg Pan
Markie - 2 msh to room which not
much there - min mod. so
to be squared in.

✓ safety - a gap to the side.

? note -

many contents etc.

(Whimie vfo above IRVINE)
Switched -

living room @ end of hallway near front door.

Why the nerves

DS. convergence system being put in -

purely cosmetic

masonry panel panel below the window

- to put the getting out -

a note was outside -

→ window of any in

Yang -

Material allocation

Still need to comb over a certain lot.

Class 0: Can't banner

looked 135 - every other floor.

But not in PV L doc. avoiding

rich material in submission to

other.

* Flag. many need to look at 135

needs updating. -

→ He will write after the enquiry.

Not was SRF anti.

Any ans? of 1st can't

Where was she stopping

Submission have gone to Minister
O shd go to office -
tell me if same one of me or
attend - Paul Everett - or
John Holson.

Tom Orr

Director of Pop² Services

N Augustine Camer
Channingham Haze

FRVINC

KA 12 - 855

fax - AC

Pre-fiscal


20th

1. Dave Townsend - VNC window -
- Came to see me Monday am.

Don't Tonsens

AKC.

West High Ltd
1-13 Span R6
SE16. 3RB.



He did a visit - at least one
proper anchoring into the work-
much has been of infilled.

Dave T / 2pm

16.03.96

36 Glasgow House, Wanda Vale W9.

C25171/8.

25168/9

~~1/1~~

1/5

1/21

1/7

1/5

1/1 ex view

1/9

1/20

1/7

1 of 8 hand door
windows & dis. int. can be seen
5 min. all windows blocked.
y:-

1 Day

1. St off. Garden Roffe East Ham.

ref —————→


① Fspd ↓wards- 2 storey old people's home
bottom panels acrylic & foam infill
9 that spd the downwind. ^{mother used.}
chipped or smeared.

② Flat fire in flat - came out &
outside over concrete. PVC vent upwards.
Green tube - Double glazing meant
needed retro-fitted 4" tube -
or spd into loam - smoke into flat -
closed windows - or fire into chori
Chingford 2 yrs ago -

Dargal -

Ivrai - policeman should inspect the remains
of the window-frame.

BRE



BRE Scottish Laboratory, Kelvin Road, East Kilbride, Glasgow G75 0RZ

Telephone: [REDACTED] Fax: [REDACTED]

Direct Telephone

Local Fax

E-mail

3/1/99

Penny

hard copy + photos.

Regards


Chic

With Compliments

Introduction

Observations

- Garnock Court is one of five, fourteen storey blocks situated close to the River Irvine, in Irvine town centre. In appearance they look similar to 1970's no-fines blocks common across the central belt of Scotland. A considerable amount of no-fines construction was undertaken in Irvine (New Town) during the 1970 – 80's. The blocks have an almost north, south line, with the fire affected façade having a south, south westerly aspect.
- The 'plastics' pod or cladding to the upvc windows appears to have been applied in two parts : around the window and to the spandrel panel. We understand this was carried out as part of the window refurbishment (8 years ago). The cladding is mechanically fixed back to the masonry substrate (exact details are unclear) and is sealed to the masonry and to adjoining panels by mastic. There is no obvious ventilation up behind the cladding, however, at some horizontal joints there are obvious small (5-10mm) gaps.
- From the observed fire damage (sooting to the masonry) it is clear that the fire having exited from the source window spread vertically a further eight floors. From the surface sooting it would appear that the fire spread up behind the cladding. There are no obvious areas which are 'unsooted' and which may have been protected by (say) mineral wool insulation or timber battens. Horizontal spread of the sooting is limited suggesting the fire spread rapidly up the building face. In only two instances is there soot staining above windows not directly above the fire window, ie on the second top floor above an adjacent window and on an adjacent elevation on the same floor as the fire source flat. There is a distinctive line below which there is no sooting, this line corresponds to the window sill of the fire source window. There is no obvious fire damage to this sill and there is no obvious indication of molten plastics material(s) having dripped onto the windows or walling below this fire source window.
- Some remedial works have been carried out, ie the windows openings have been temporarily framed and boarded out, however, there is no evidence of any of the original, undamaged cladding left attached to the building. There are severely burnt remains, of what appears to be pod or panel surrounds, at the head of windows and around spandrel panels.



BRE00035379/32

BRE00035379_0032




Photograph 1. South Elevation of Garnock Court, showing the external fire damage on the SW side. The lowest level of damage is the fifth floor.



Photograph 2. Detail of the windows on 2nd and 3rd floors, directly below the fire damaged section. Note the open window, and the overlapping panel just above the second floor window.



Photograph 3. The living room window of Flat 1. Note the white sealant which has been used to fill the gap at the overlap.



Photograph 4. The living room window of Flat 2. The overlap of the two panels is open with a gap of a few millimeters.







As discussed

Cataly - disabled in wheel chair

Double glazed units

caused fire
smoking -

Corner vertical row
of windows

carpet
burning

Moulded ASP around each
window

On fare between windows
moulded pieces

they - over lap -
not recalled

test
panels?

fire gone up - caught on
exposed edge

Short report

Morgan, Penny

From: Tony Edwards [Tony_Edwards@detr.gsi.gov.uk]
Sent: 08 July 1999 11:44
To: FieldP@bre.co.uk
Cc: ColwellS@bre.co.uk; MorganP@bre.co.uk; ShawMR@bre.co.uk; ShippM@bre.co.uk; SmithDA@bre.co.uk; SmithiesJN@bre.co.uk
Subject: ENVIRONMENT SUB COMMITTEE INQUIRY not protectively marked

Peter

Thanks, I think this is the right approach.
Brian is at FRS tomorrow (Friday) and I will give him a copy to pass on to you of my final submission that has now been agreed with the Minister.

Tony

>>> "Field, Peter" <FieldP@bre.co.uk> 07/07 3:09 pm >>>
TONY

I was contacted again today by the Secretary of the Environment Sub Committee Inquiry. He asked if BRE intended to submit evidence.

I told him that we had been in discussion with yourselves and that it was our view that there would be nothing of substance, relevant to the committee, that we would wish to add to the evidence that you proposed to give.

He was content with that position.

Please let me know of any developments so that we can avoid potential conflicts of interest.

Regards

Peter

Department of the Environment, Transport & Regions

This email and any files transmitted with it are private and intended solely for the use of the individual or entity to whom they are addressed.

This email does not constitute a commitment by DETR.

Penny Morgan



DEPARTMENT OF THE ENVIRONMENT,
TRANSPORT AND THE REGIONS

FLOOR
ELAND HOUSE
BRESSENDEN PLACE
LONDON SW1E 5DU

TEL
FAX
GTN



Peter.
Further to your 'E' mail.
copy of the final version, now
agreed by the Minister, of my
submission to the Select Com.

Tony
8/7/99.

2

WITH COMPLIMENTS

height of the building. If the side of a building is sufficiently removed from the boundary then it need not have any fire resistance. Conversely, where the wall is on or very close to the boundary, then most or all of the wall will need to be fire-resisting.

1.2 Flammability at external wall surfaces

In addition to fire resistance, it is necessary to consider the outside face of the wall in terms of its susceptibility to ignition and subsequent flame spread over its surface.

Typically, sources of ignition could be flames issuing out of windows or other openings caused by a fire within the building or alternatively from an external fire source. External fire spread to the cladding can be caused by fire radiation from another building or from a source immediately adjacent to the cladding such as the ignition of refuse caused by arson. The standard of fire precautions that are necessary is affected by:

- a) the distance to the boundary;
- b) the height of the building, and
- c) the use of the building.

Where external fire fighting might be difficult, high standards of performance against fire propagation and spread of flame are needed. Therefore where the external wall of a building is on or very close to a boundary these standards apply. Because of this difficulty in fighting external fire spread in the upper parts of high buildings it is necessary to apply higher standards of fire performance to the upper parts of such buildings regardless of the distance to the boundary. Where a low building is not close to a boundary, there is no restriction on the flammability of external wall claddings. Also a lesser standard of performance is acceptable for the lower parts of a high building unless it is on or close to the boundary.

1.3 Materials of limited combustibility

In high buildings the risk from fire spread is such that the combustibility of materials used in the construction of external walls, including thermal insulation materials, needs to be limited. The exception to this is where both leaves of the cladding are of masonry construction, such as brick or block, in which case the insulating material

need not be of limited combustibility. A material of limited combustibility is a material with a performance specification: this includes non-combustible materials or materials that are defined by reference to a method of test. Typically, plasterboard would be considered as a material of limited combustibility.

1.4 Cavities

Hidden voids in construction can provide a route for fire spread throughout or around the building and this can be particularly relevant in the context of external cladding systems. Any void between the new cladding and the existing building should be closed at regular intervals or at the line of compartmentation. Typically the floor of each flat will form the line of compartmentation, an issue covered in paragraph 3.1.

1.5 Surface Flame Spread

Construction materials and their behaviour in relation to fire are classified using a number of standard tests such that the performance of particular elements of buildings can be specified without reference to specific materials.

The provisions necessary to reduce the spread of flame over the surface of a material are based on the comparison of the results of small scale fire tests with larger scale fire research and experience of real fires. Any guidance that is given must be sufficient to provide a satisfactory level of safety whilst being practical in its application.

The surfaces of materials (including cladding systems) are classified by reference to two British Standard test methods. These are the spread of flame test which measures the distance a flame will spread across the surface of a sample and the fire propagation test which assesses the contribution that the sample makes to fire development. The spread of flame test has 4 classes. These are class 1 to class 4, with 1 being the highest performance rating. Class 'O' is a further class, defined for the purposes of the Building Regulations, that is used for critical situations where a higher standard of performance than that of Class 1 is appropriate. The Building Regulation issues relating to flame spread are covered in paragraph 3.1.

Whilst non-combustible materials are inherently of the Class 'O' referred to above, many materials that are by definition combustible will also achieve this classification. The intent of this methodology is to identify materials that will have a low risk of fire spread.

2. The extent of the use of external cladding systems

2.1 The Department does not collect statistics on the use of cladding systems but it is believed that external cladding systems are widely used.

2.2 The Department has a call-off contract with the Fire Research Station to investigate real fires and this highlights any areas of concern that affect Building Regulations. The following are fires notified to the Department that involved external fire spread but were not necessarily attributed to the cladding system:

Knowsley Heights, Liverpool, 1991. Deliberate fire spread up and behind rainscreen cladding, extended over 11 floors. Building Regulations were changed as a result of this.

Mercantile credit building, Basingstoke, 1991. Fire on 8th floor spread up the building behind glass curtain walling.

Three storey block in Milton Keynes, 1995. Roof destroyed.

Alpha House Coventry, 1997. Flames travelled up the outside of the block from 13th to 17 floor. No fire penetration of the flats.

Butler House, Grays, Essex, 1997. Fire in top flat of 14 storey block caused uPVC window frames to melt and drip, which in turn caused some damage to cladding.

3. The adequacy of the Regulations pertaining to their use

3.1 In England and Wales (Scotland has a different set of Building Regulations) where new buildings are erected, or existing buildings materially altered, or in certain cases where there is a material change of use, then the work is required to comply with the Building Regulations 1991. As far as fire is concerned, the purpose of the Regulations is to secure reasonable standards of health and safety for persons in or about buildings (and any others who may be affected by buildings, or matters connected with buildings). Schedule 1 of the Regulations contains the functional requirements and Requirement B4 (1), which has particular relevance to cladding systems, is given in paragraph 1.

Guidance on how to comply with the functional Requirements of Part B is given in Approved Document B (fire safety). Approved Document B includes several provisions to restrict the materials used in external walls and cladding by reference to the surface spread of flame rating. These provisions are as follows:

The external surfaces of walls of any building closer than 1 metre to its boundary (and therefore close to other buildings) should be class 'O' in order to reduce the risk of external fire spread from one building to another.

Where a building is 20 metres or more in height, the external surfaces of walls more than 20 metres from ground level should achieve a class 'O' surface spread of flame rating. Below this height timber cladding at least 9mm thick, or some other materials that are less restrictive than class 'O' materials, could be used. This is to reduce the risk of fire spread over the walls of tall buildings whilst allowing certain commonly used materials to be retained in positions where fire fighting operations from the ground could be effective.

In the case of the outer cladding of a wall of 'rainscreen construction', which has a drained and ventilated cavity, the surface of the outer cladding which faces the cavity should also satisfy the provisions detailed above. This is to take account of the specific problems associated with this type of construction.

Approved Document B states that the external envelope of the building should not provide a medium for fire spread if it is likely to be a risk to health or safety. The Document also points out that the use of combustible materials for a cladding framework, or of combustible thermal insulation, may present a risk in tall buildings. Therefore in a building with a storey at more than 20m above ground level any insulation material used in the external wall construction should be a material of limited combustibility.

With regard to fire stopping Approved Document B suggests that a cavity barrier should be provided at the junctions between an external cavity wall that is not of masonry construction and every compartment floor. The BRE guidance on avoiding risks with thermal insulation, which is referenced in the Approved Document that deals with energy efficiency, recommends that to prevent fire spread, cavity barriers should be provided at every floor level. We have asked the Fire Research Station to review and update their report on the fire performance of external thermal insulation for walls of multi-storey buildings, referred to in Approved Document B.

The current Approved Document B is being reviewed but there are no changes proposed that will affect cladding systems other than the 20m height mentioned above is being reduced to 18m to fall in line with other height dimensions relating to fire fighting. In general it is considered that the risk of serious fire spread via external cladding will be minimal if the guidance given in Approved Document B is followed.

The Fire Precautions (Places of Work) Regulations may have a bearing on cladding issues but these Regulations are the responsibility of the Home Office.

4. What action may be necessary to counter any risks posed in existing buildings and to avoid any risks in new buildings or alterations to existing buildings

4.1 The Building Regulations in England and Wales only apply to new building work, and thus cannot be used to require any alterations to existing buildings although the Department is reviewing this in respect of the conservation of energy. The provisions of the Building Regulations as set out in the preceding section do, however, apply when new buildings are erected and thus such work is covered.

The Building Regulations also apply to building work that is classified as a material alteration. An alteration is material if, at any stage of the work, it would result in the building not complying with certain requirements of the Regulations where it previously did. The most pertinent requirement with regard to cladding is external fire spread, but structural requirements could also be an issue.

Thus with regard to the alteration (or replacement) of cladding, if this was the only work being carried out, and if it at no time made the external fire spread or structure any worse than it was already, the work would not be controlled by the Building Regulations. There is therefore the possibility that external cladding installed some time ago, and thus not complying with the current Building Regulations, could be replaced without being controlled by the Regulations as long as the building was not made any worse with regard to these particular requirements in the process. This is a possible problem area and one that the Department may need to review.

The Building Regulations would need amendment to ensure that all such work was covered. It is possible that the Building Act might also need to be extended to support this. Any such amendment would need careful drafting to ensure that an undue burden

was not inadvertently imposed on replacement and repair work. However a balance needs to be struck between construction costs and safety.

5. Other matters which may arise in the course of questioning

5.1 The Department has funded the Fire Research Station (BRE) to produce a method of test for '*Assessing the fire performance of external cladding systems*'. This report will be referenced in the revised Approved Document B and it is proposed that it will become a British Standard.

5.2 Review of Building Research Establishment Report 135 - 1988 'Fire performance of external thermal insulation for walls of multi-storey buildings'. This review is required to give better design guidance for cladding systems, particularly with regard to cavity barriers.