











## 2 Findings

There have been a relatively low number, yet high profile fires in high-rise buildings over the recent years involving domestic apartment/residential buildings and commercial office buildings. There are approximately 3500 residential tower blocks of greater than ten storeys in height in the UK with approximately 500 of these fitted with external cladding <sup>(1)</sup>.

The fire mechanisms by which exterior cladding systems may ignite and contribute to vertical fire spread include:

- ◆ Flames projecting from broken windows in the room of origin, exposing the façade and any windows above, thus allowing for the upper windows to fail and allow flames & hot gases to enter the floor above
- ◆ Inadequate fire stopping of the gap between the edge of the floor slab and the exterior wall allowing for flames and hot gases to pass directly to the floor above. This is especially notable with curtain wall construction.
- ◆ Heat induced distortion of supporting frameworks causing the fire-stopping to become inadequate or collapse
- ◆ Direct contribution of the external cladding material to vertical fire spread. Ignition may occur following exposure to flames projecting from window openings.

Some of the more notable and international fire incidents include:

- ◆ a 31-storey department store and office building – Andraus Building, Sao Paulo, Brazil 1972 – *no fatalities*
- ◆ a 25-storey office building – Joelma Building, Sao Paulo, Brazil 1974 – *179 deaths*
- ◆ a 30-storey hotel – Las Vegas Hilton Hotel, 1981 – *eight deaths in various locations*
- ◆ 62-storey tower – First Interstate Bank Building, Los Angeles, California 1988 – *no fatalities*
- ◆ a 12-storey office block – Mercantile Credit Building, Basingstoke 1991 – *no fatalities*
- ◆ a 38-storey bank building – One Meridian Plaza Building, Philadelphia 1991 – *no fatalities*
- ◆ a 11-storey residential tower block, Knowsley Heights, Liverpool, 1991 – *no fatalities*
- ◆ a 37-storey retail, commercial office and hotel development - President Tower, Bangkok 1997 – *no fatalities* , and
- ◆ 13-storey residential tower block, Irvine, Scotland, 1999 – *one death in the flat of fire origin*

All those incidents mentioned above directly involved exterior fire spread via the curtain walling façade or non-combustible spandrel material. None of the buildings had sprinklers installed and/or available and they were difficult to extinguish. Fire fighters were forced to tackle the fires on the upper floor levels from outside the building, as it was unsafe for them to enter floors above the fire zone.







The Acceptable Solution C3/AS1 of the New Zealand Building Industry Authority (BIA 1992) Approved Documents, provides one approved means of complying with this clause. C3/AS1 seeks to reduce the likelihood of fire propagating vertically up a combustible façade either as a result of direct flame impingement from an adjacent building on fire, or as a result of flames projecting through openings at a lower level in the same building and igniting the façade in the vicinity of the opening. The requirements seek to control either the ignitability or the contribution of the cladding to fire development and thereby indirectly influence the rate of vertical flame spread, by use of standard test methods.

For external walls, the acceptable properties of exterior surface finishes depend on the purpose groups exposed to the fire hazard, the building height and distance from the relevant boundary.

New Zealand currently has requirements for aprons of 0.6m wide or spandrels of 2.5m high to be provided in unsprinklered buildings containing sleeping accommodation on upper floors. However, the minimum spandrel height is likely to be reduced to 1.5m. There are no requirements for aprons or spandrels in office buildings (sprinklers are required when the building height is above 25m).

### 2.1.5 Sweden

There are two documents available relating to building construction and fire spread.

The Swedish Building Code SBN 1980, Chapter 37, Fire Protection deals with external walls in Section 423. However, this is limited to specifying that external walls in fire resistant buildings shall be constructed in such a way that the risk of fire spread along or through the walls is limited and constructed of incombustible materials. There is no specific guidance to fire spread via windows here.

An alternative document is the Swedish Regulations for New Construction <sup>(6)</sup>, which makes reference to the problems of external fire, spread via windows. Section 8.43 states that for external walls and windows, the materials used in the façade cladding shall have a very high ignition temperature. The external walls themselves shall be constructed so that 'the risk of fire spread via windows is limited' but does not quantify that statement.

However, it does venture further to state 'between windows in different fire compartments, the vertical distance should not be less than 1.2m unless the windows inside this distance are constructed to not less than Class F15'.

### 2.1.6 Malaysia

Guidance presented in the Uniform Building By-Laws <sup>(7)</sup> is minimal, however Section 149 of the document makes specific reference to protection of openings in an external wall:

**Horizontal and vertical barriers of the external wall:**

Openings in external walls located vertically above one another shall be protected by approved flame barriers either extending 750mm beyond the exterior wall in the plane of the floor or by vertical panels not less than 90mm in height.

(It should be noted here that it is the author's belief that the 90mm-height requirement stated above should read 900mm, and is a translation error in the original text.)

Section 142 Part 3 requires the external wall of a building, which exceeds 15m in height to be constructed wholly of non-combustible material. The test methods stated for evaluation are generally not deemed adequate for evaluation of the end-use performance of exterior cladding materials and systems.

Countries such as Malaysia tend to look towards USA and Europe and readily adopt controls and test methods developed and tested there.

## 2.2 Analysis of the findings

It is clear from the earlier reports (Nos. 203130 and 203132), and from that stated above, that the guidance provided by national regulation within England and Wales, or codes of practice does not effectively address the particular problems of fire spread via windows.

Out of the nine international countries reviewed here and previously, over half (Canada, USA, Australia, New Zealand and Malaysia), offer guidance on use of both spandrel or apron applications, although the restrictions to building occupancy type and height do vary across the board. Hong Kong makes reference to spandrel height only. Only three countries Canada, USA and Australia state that requirements for spandrel height and/or apron projections can be waived if the building is sprinklered throughout. The UK regulations notably lack guidance on either, however it does have a requirement for sprinkler protection in buildings over 30m in height, however this would not apply to any Purpose Group 1(a) (flats) part of a mixed use building.

International research has shown that the requirements for setting minimal spandrel heights (set out by those countries that attempt to address this problem), is an option that remains largely ineffective. Research, particularly that carried out by the National Research Council of Canada, has shown that spandrel walls need to be of an impractical height (>2.5m) to be effective for controlling vertical fire spread. The Canadian results show that by using an 1100mm wide apron, the exposure to the wall face was reduced to approximately 10% of that experienced by the 900mm spandrel height.

In order to overcome the problem of excessive spandrel height, consideration could be offered to the use of staggered window positions within a façade. This would serve to increase the spandrel height without having an implication on the slab to slab distances per storey. Careful planning of residential tower blocks could position window openings to accommodate the suggested 2.5m separation distance.

Igor Oleszkiewicz from the National Fire Laboratory, National Research Council, Canada carried out a substantial amount of research work into this area including vertical



Another factor found to influence the window fire plume, is the shape of the façade. Features such as 'sun shades' and deep mullions can either protect the façade from the plume, or cause greater fire exposure.

A test carried out using vertical projections channelled the flame plume up and caused a 50% increase in the heat intensity measured above the window opening. This means that locating windows in a vertical recess or providing vertical shades or privacy screens would increase the fire exposure to the wall above the venting window as well as to the window in the storey above.

Certain combustible claddings can support unlimited vertical flame spread. However, some do not, if the combustibility of the cladding is not significant. Factors such as the amount of combustibles per unit area, their heat of combustion, the ignition temperature of the combustible components, composition of the cladding and preservation of integrity when exposed to fire determine the propensity for vertical flame spread and hence its contribution to the window flame plume.

It is very difficult to identify whether a façade fire directly influences the occurrence of casualties during the incident. Information from various databases is limited, as was seen in the previous reports, and the ability to decipher the recorded statistics is somewhat masked by the method of reporting on the UK FDR1 fire reports. Information has been taken from the FDR1 statistics for the year 1998 and is shown below in Tables 1 –5. The data below refers to the number of fires in buildings by total number of floors in the building, number and type of casualty. The data also only relates to the classification of 'Other Buildings' and hence does not include for domestic fires in homes. Although generally based on a weighted sample of 20% of UK incidents, all fires are recorded where a fatality has occurred. The number of casualties also includes the Brigade personnel. In 1998, there were 681 non-fatal Brigade casualties, but no fatalities.

Tables 1 – 4 look at the casualties over a range of building heights. This data does not identify which floor is the floor of 'fire origin', merely the total number of floors in any particular building. It does, however, highlight the location of the casualty with respect to the fire location. It can be seen that the majority of casualties are found in the room of fire origin and as such, cannot be directly attributed to the effects of external fire spread.

**Table 1** Fatal casualties injured by burns an/or scalds and location of casualty relative to fire

Total number of floors in building	Number of Fatalities – Burns and/or Scalds					
	Room of origin	Floor of origin	Floor +1	≥ Floor + 2	Floor - 1	≥ Floor - 2
1	18	1				
2	52	5	1			
3	16	1	1			
4	2					
5	2					
6-10	3					

11-15						
16-20	1	1				
21+	1					

**Table 2** Non-fatal casualties injured by burns an/or scalds and location of casualty relative to fire

Total number of floors in building	Number of Non-Fatal Injuries – Burns and/or Scalds					
	Room of origin	Floor of origin	Floor +1	≥ Floor + 2	Floor - 1	≥ Floor - 2
1	241	20			1	
2	844	114	32		17	
3	228	34	10	1	5	1
4	62	9	1	1		
5	15	3		3		
6-10	22	1			1	
11-15	19	9	1			
16-20	6	2				
21+	1					

Comparing the range of injury type, it is clear that there are a greater number of injuries caused by inhalation of smoke and toxic fumes than actual burns or scalds. As the spread is also wider for the non-fatal injury (Table 4), this can be attributed to smoke spread through the building compartments and floors. Surprisingly, we also see a number exposed to smoke spread on floors below the floor of fire origin.

**Table 3** Fatal casualties injured by smoke and/or gas inhalation and location of casualty relative to fire

Total number of floors in building	Number of Fatalities – Smoke and/or gas					
	Room of origin	Floor of origin	Floor +1	≥ Floor + 2	Floor - 1	≥ Floor - 2
1	15	12	1			
2	75	48	45		4	
3	20	21	13	1		
4	5	2	4			
5		4				
6-10	3	4				
11-15	2		2			
16-20		1				
21+		2				



9	19.9	3.6	9	38.3	8.1
10	16.3	3.0			
11	48.6	8.9			
<b>Total</b>	<b>545</b>	<b>100 %</b>	<b>Total</b>	<b>433.1</b>	<b>100 %</b>

### 2.3 Assessment of risk

There are relatively few documented cases of extensive external vertical fire spread involving combustible claddings or glazed facades, and there are even fewer cases where such spread has significantly compromised life safety.

Façade fires do not generally threaten building occupants, but the concern is that fire spread through the openings into upper levels may result in secondary fires, which can threaten occupants. It has been suggested that 'sterile zones' could be employed in regions close to windows, with managed policies of no combustibles near windows. This however is difficult to enforce in a domestic (or indeed many other) installations.

The UK guidance given in Approved Document B Fire Safety, deals with the issue of life safety for different occupancies by application of building construction and limits on performance of material. It is the Insurance Industry which is leading the risk assessment of buildings with fully or partially glazed installations, however this is with a view to effects of business interruption and replacement costs.

Building fires result in damage to the fabric and contents of the building and often extensive business interruption. The impact of fire, flame smoke and extinguishing water on a building is dependent upon the fire severity. In 90% of fires, damage is limited to a single compartment or room. However, this means that in 10% of fires, they continue to spread and hence fire damage goes beyond the original enclosure. As a result of experimental work carried out by the Loss Prevention Council, the Association of British Insurers (ABI) published guidance for their members, concerning the estimated maximum loss (EML) in high-rise and multi-storey buildings. Here a fire risk assessment was made of the façade<sup>(10)</sup> to determine the

- ◆ associated fire hazards (occupancy, building design and construction)
- ◆ fire protection ( management, sprinklers, fire brigade operations)
- ◆ type of façade employed (design, key features and construction materials)

The Fire Risk Assessment Form<sup>(10)</sup> looks at the construction of the façade including types of structure, fixings, window, cavity etc. Information is given as to the design and material performance with an assessment as to the relative fire performance on a scale of 0 to 2. An example of such for cladding panels would be:

- ◆ 0 non-combustible and fire resistant or adequately protected eg. By an approved drencher system;
- ◆ 1 limited combustibility (Class O and full-scale testing), some inherent strength and/or obstruction preventing direct flame impingement on susceptible parts;
- ◆ 2 combustible, poor fire resistance and exposed to direct flame impingement







1100mm wide apron, the exposure to the wall face was reduced to approximately 10% of that experienced by the 900mm spandrel height.

Curtain wall constructions have particular problems of fire spread via the void junctions between the floor slab edge and the façade itself. Distortion of the wall panels can lead to collapse of the passive protection at the floor slab.

Horizontal applications would be incompatible with curtain wall constructions. Here, the only real means of limiting or preventing the risk of vertical fire spread would be the use of sprinkler systems or fire resistant glazing. Work undertaken by the LPC has shown that a fire resisting façade was able to survive elevated temperatures during a fire and prevent breakout and subsequent spread up the system.

A number of mitigatory or protective measures have been identified within the body of this report and include:

- ◆ *Spandrel panels* – although not always an appropriate solution, they still perform an important task and could be critical in some buildings and occupancies. Buildings of particular concern are the high-rise buildings with slow evacuation times such as apartment blocks, hospitals, or where phased evacuation is undertaken.
- ◆ *Horizontal projections* – more effective than spandrel panel system in reducing the heat exposure to the upper floor level. Does have an aesthetic implication for building design. Impractical for large glazed areas.
- ◆ *Window orientation and size* – the heat exposure can be influenced and to a point controlled by the use of tall and thin window dimension, low and wide orientation results in a much higher heat intensity on the above façade.
- ◆ *Sprinklers* – the most effective and accessible control method. Reduces the gas temperature to levels that are not threatening to the non-fire resisting façade. Especially useful with curtain walling systems. Favoured by the international community over the use of spandrel and/or apron projection.
- ◆ *Limited combustibility of claddings* – submit all cladding materials to appropriate test methods available. BRE cladding test – Fire Note 9 outlines such a test. Additional full size testing should be carried out for applications of glazed façades.
- ◆ *Fire resistant glazing and facades* – windows or openings introduce a weakness to the façade. Use of fire resistant materials provides improved integrity of glazed systems. Full scale tests allow for assessment of the whole system performance.
- ◆ *Sterile zones* – for combustible products so use non-combustible curtains, blinds etc. Limits fire load adjacent to window openings and hence the risk of exposure from external flaming.
- ◆ *Staggering the window layouts* – to increase spandrel height in a façade.

The relatively low number of deaths or injuries is supported by the Brigade statistics identified here. It has not been possible to identify any incidents in the UK where death or injury has resulted from fire spread up the outside of a building where the fire has broken out of one window and re-entered at another. Indeed, very few people are killed or injured from fire who are elsewhere than on the fire floor. Most deaths or injuries on floors other than the fire floor are as a result of smoke.

It therefore may be concluded that fire spread up the outside of buildings via the windows is not a significant threat to life compared with the other risks from fire in tall









## Analysis of the findings

- ◆ Flames contacted the plate glass windows. It is believed that the triangular shape of the spandrels and recessed plate glass caused additional turbulence, which rolled the flames onto the windows resulting in early failure.

There were eighth deaths in this fire. Three were in the eighth floor lift lobby, one by jumping/falling from the 12<sup>th</sup> floor and four in hotel rooms in the East tower. The doors to the hotel rooms where the deaths occurred were open or had been opened during the fire. There were no fatalities in rooms where the door had been kept closed. This suggests that internal rather than external fire spread was the main reason for the deaths.

### **4. First Interstate Bank Building, Los Angeles, California 1988** <sup>(5)</sup>

The bank was a 62-storey tower with sprinkler protection only in the basement, garage and underground pedestrian tunnel. An automatic sprinkler system was being installed in the building at the time of the fire. The building had a structural steel frame with spray-on fire proofing with steel floor pans and lightweight concrete decking. The exterior curtain walls were glass and aluminium with a 100mm gap between the curtain wall and the floor slab, where the fire stopping, comprised 15mm gypsum board and fibreglass caulking. The fire started on the 12<sup>th</sup> floor and extended to the floors above primarily via the outer walls of the building. Flames also penetrated behind the spandrel panels around the ends of the floor slab where there was sufficient deformation of the aluminium mullions to weaken the fire stopping, allowing the flames to pass through even before the windows and mullions had failed. Flames were estimated to be lapping 9m up the face of the building. The curtain walls including windows, spandrel panels and mullions were almost completely destroyed by the fire. The upward extension stopped at the 26<sup>th</sup> floor level.

### **5. Mercantile Credit Building, Basingstoke 1991** <sup>(5)</sup>

This was a 12-storey office block. Fire on the eighth floor spread up the building and broke out on the eighth floor. Flame spread externally behind glass curtain walling to the tenth floor, fanned by strong winds.

### **6. One Meridian Plaza Building, Philadelphia 1991** <sup>(5)</sup>

This fire occurred on the 22<sup>nd</sup> floor of a 38-storey bank building. The building frame was structural steel with concrete floors poured over metal decks and protected with spray-on fireproofing materials. The exterior of the building was covered by granite curtain wall panels with glass windows attached to perimeter floor girders and spandrels. At the time of construction only the below ground service floors were fitted with sprinklers and since then they had been added to the 30<sup>th</sup>, 31<sup>st</sup>, 34<sup>th</sup> and 35<sup>th</sup> floors and parts of floors 11 to 15. Fire broke through windows on the 22<sup>nd</sup> floor and heat exposure from the window plumes ignited items on the floor above. The fire was stopped when it reached the 30<sup>th</sup> floor which was sprinklered.

### **7. Knowsley Heights, Liverpool, 1991** <sup>(5)</sup>

This was an 11-storey residential tower block. The fire was started deliberately in the rubbish compound outside the building. Fire spread up through a 90mm gap between the

building's rubberised paint-covered concrete outer wall and a recently installed rain screen cladding. The rapid spread of fire was thought to have been caused by the lack of fire barriers in the cavity gap passing all eleven floors and providing a flue for hot gases to rise. The fire destroyed the rubbish compound and severely damaged the ground floor lobby, outer walls and windows of all the upper floors. No smoke or fire penetrated into the flats and the building was reoccupied by tenants later the same day. The rain screen cladding material was a Class 0 rated product. Building Regulations were changed as a result of this fire.

#### **8. President Tower, Bangkok 1997 <sup>(5)</sup>**

This was a 37-storey retail, commercial office and hotel development. A sprinkler system was not yet operational as the interior fire out was not fully completed. An explosion and fire started on level seven causing the destruction of the aluminium framed curtain walling system. The effectiveness of fire stopping at the floor edge was compromised by floor to floor cabling. Window and spandrel glass shattered and collapsed before structural silicone sealant bonds between the glass and aluminium were destroyed. Many heat strengthened glass panels sustained elevated temperatures but fractured and collapsed as they cooled. The vertical fire spread extended up to level ten.

#### **9. Residential tower block, Irvine, Scotland, 1999 <sup>(5)</sup>**

The fire, which started in a flat on the fifth floor of a 13-storey block of flats, broke out through the window and quickly spread vertically up the exterior face of the building, engulfing the upper nine floors within minutes. The building was of concrete construction but had full height composite window units comprising a GRP panel below the window and u-PVC window frames. The fire ignited the GRP panels and spread vertically.

There was one death in the incident and that was in the flat of fire origin. Therefore the combustible window components were unlikely to have contributed to the death.