







Composite Panels – PUR 25-09-01






Panel joint penetrated 12:00 - Test terminated 13:30.

Composite Panels – PIR 25-09-01






Panel joint penetrated 14:15 - Test terminated 28:50

Composite Panels – Mineral Wool 25-09-01






No Panel joint penetration - Test terminated 35:00

Composite Panels – EPS 14-11-01






Panel joint penetrated 9:45 - Test terminated 35:00

Rainscreen1 - Resoplan + Rockwool on timber no FB 31-05-01






Test terminated 35:00

Rainscreen2 - Rockclad + Rockwool on timber no FB 31-05-01




Test terminated 35:00

Rainscreen3 - Aluminium + Isowool on metal no FB 18-07-01






Test terminated 12:00

Rainscreen 4 - Rockclad + Isowool on metal no FB 18-07-01






Test terminated 35:00

Rainscreen 5 - Resoplan + Isowool on metal + FB 18-07-01






Test terminated 35:00

Render 1 - Rockwool 03-09-01






Test terminated 40:00

Render 2 - Phenolic 03-09-01






Test terminated 40:00

Render 3 - PUR 03-09-01






Test terminated 50:00

Render 4 - EPS 06-09-01



Test terminated 20:00

Render 5 - EPS with FB 06-09-01



Test terminated 37:00