



### **Exhibit JAH13**

1. The 4 x BIVs located at high level on the original 4" steel service pipe laid in 1974
2. The 3" IIV on the new 90mm Polyethylene (PE) gas service pipe
3. The ECV on the 10" steel gas service pipe

#### **1. The 4 x BIVs located on the original 4" steel service pipe laid in 1974**



**2. The 3" IIV on the new 90mm Polyethylene (PE) gas service pipe**

Figure K18 from Dr Lane's report Appendix K





