

LIFT H091 – CABLE FAULT

We apologise for lift H091 not being in service. This is owing to a cable fault which needs to be renewed. The new cable has been ordered and the work is due to be carried out on 28/03/17. This should resolve the problem.

KCTMO apologise for the inconvenience caused.

Any questions, please do not hesitate to contact the Latimer estate office on: [REDACTED]
[REDACTED]



SA/112