

Description

DescriptionFrom: Express Environmental Solutions Ltd [mailto:info@expressltd.net] Sent: 18 January 2017 16:26 To: Mark Meosa <mmeosa@repairsdirect.co.uk> Cc: Repairs Direct Planners <repairsdirectplanners@repairsdirect.co.uk>; s.monteith-knight@expressltd.net Subject: Re: Fwd: RE: 31 Grenfell Tower Hi Mark, These areas are safe in regards to the asbestos removal and can be used by tenant. The hall ceiling is 4m2 and bedroom is 12m2 approx. If you require any further information, please contact me. Kind Regards, Tony Pearce, Express Environmental Solutions Ltd T: [REDACTED] W: www.expressltd.net On 18/01/2017 16:19, Mark Meosa wrote: Hi Tony From your previous e-mail I understand that the parts of the property that you were advised to inspect can be described as being safe for habitation. Please can you also provide the square meter of the areas affected as this information will be useful for us in our plastering works. Can you elaborate if necessary. Kind regards Mark Meosa From: Express Environmental Solutions Ltd [mailto:info@expressltd.net] Sent: 18 January 2017 15:54 To: Mark Meosa <mmeosa@repairsdirect.co.uk> Cc: Repairs Direct Planners <repairsdirectplanners@repairsdirect.co.uk>; s.monteith-knight@expressltd.net Subject: Re: Fwd: RE: 31 Grenfell Tower Hi Mark, The textured coatings to the hall and bedroom have been removed. Plastering and any other remedial works are carried out by others (If required by KCTMO) All other area were in good condition, so following KCTMO procedures no further works required. If you require any further information, please contact me. Kind Regards, Tony Pearce, Express Environmental Solutions Ltd [REDACTED] W: www.expressltd.net On 18/01/2017 15:43, Sara Monteith-Kinght wrote: ----- Forwarded Message ----- Subject: RE: 31 Grenfell Tower Date: Wed, 18 Jan 2017 15:40:26 +0000 From: Mark Meosa <mmeosa@repairsdirect.co.uk> To: 'Sara Monteith-Kinght' <s.monteith-knight@expressltd.net> Hi Sara Thank you for your kind assistance. I tried contacting you however your line was continually busy. Would it be possible for works to be carried out to have this removed? Please can you advise as to what steps would be best. Can you also inform Tony Pearce in this audit trail and if he could respond to me accordingly. I await your reply. Kind regards Mark Meosa -----Original Message----- From: Sara Monteith-Kinght [mailto:s.monteith-knight@expressltd.net] Sent: 18 January 2017 14:48 To: Mark Meosa <mmeosa@repairsdirect.co.uk> Subject: Re: 31 Grenfell Tower Hi, These are asbestos containing materials if you require further information please can you contact Tony Pearce at info@expressltd.net who will be able to help you. Thanks Sara On 18-Jan-17 2:43 PM, Mark Meosa wrote: > Hi Samantha > > Thank you for this information, please can you elaborate as to what > these materials are that you have found as mentioned in the report: > chrysotile & amosite chrysotile > > Kind regards > > > Mark Meosa > > > -----Original Message----- > From: Sara [mailto:s.pearce@expressltd.net] > Sent: 18 January 2017 14:29 > To: Mark Meosa <mmeosa@repairsdirect.co.uk> > Subject: 31 Grenfell Tower > > Afternoon, > > Please find attached sample result for the above property. > > Kind regards > -- Sara Monteith-Knight From: Express Environmental Solutions Ltd [mailto:info@expressltd.net] Sent: 18 January 2017 16:26 To: Mark Meosa <mmeosa@repairsdirect.co.uk> Cc: Repairs Direct Planners <repairsdirectplanners@repairsdirect.co.uk>; s.monteith-knight@expressltd.net Subject: Re: Fwd: RE: 31 Grenfell Tower

Hi Mark,



These areas are safe in regards to the asbestos removal and can be used by tenant.

The hall ceiling is 4m2 and bedroom is 12m2 approx.

If you require any further information, please contact me.

Kind Regards,

Tony Pearce,

Express Environmental Solutions Ltd

W: [www.expressltd.net](http://www.expressltd.net)

On 18/01/2017 16:19, Mark Meosa wrote:

Hi Tony

From your previous e-mail I understand that the parts of the property that you were advised to inspect can be described as being safe for habitation.

Please can you also provide the square meter of the areas affected as this information will be useful for us in our plastering works. Can you elaborate if necessary.

Kind regards

Mark Meosa

From: Express Environmental Solutions Ltd [<mailto:info@expressltd.net>]

Sent: 18 January 2017 15:54

To: Mark Meosa <[mmeosa@repairsdirect.co.uk](mailto:mmeosa@repairsdirect.co.uk)>

Cc: Repairs Direct Planners <[repairsdirectplanners@repairsdirect.co.uk](mailto:repairsdirectplanners@repairsdirect.co.uk)>; [s.monteith-knight@expressltd.net](mailto:s.monteith-knight@expressltd.net)

Subject: Re: Fwd: RE: 31 Grenfell Tower

Hi Mark,

The textured coatings to the hall and bedroom have been removed. Plastering and any other remedial works are carried out by others (If required by KCTMO)

All other area were in good condition, so following KCTMO procedures no further works required.

If you require any further information, please contact me.

Kind Regards,

Tony Pearce,

Express Environmental Solutions Ltd

W: [www.expressltd.net](http://www.expressltd.net)

On 18/01/2017 15:43, Sara Monteith-Kinght wrote:

----- Forwarded Message -----

Subject: RE: 31 Grenfell Tower

Date: Wed, 18 Jan 2017 15:40:26 +0000

From: Mark Meosa <mmeosa@repairsdirect.co.uk>

To: 'Sara Monteith-Kinght' <s.monteith-knight@expressltd.net>

Hi Sara

Thank you for your kind assistance. I tried contacting you however your line was continually busy. Would it be possible for works to be carried out to have this removed?

Please can you advise as to what steps would be best. Can you also inform Tony Pearce in this audit trail and if he could respond to me accordingly.



I await your reply.

Kind regards

Mark Meosa

-----Original Message-----

From: Sara Monteith-Kinght [mailto:s.monteith-knight@expressltd.net]

Sent: 18 January 2017 14:48

To: Mark Meosa <mmeosa@repairsdirect.co.uk>

Subject: Re: 31 Grenfell Tower

Hi,

These are asbestos containing materials if you require further information please can you contact Tony Pearce at info@expressltd.net who will be able to help you.

Thanks

Sara

On 18-Jan-17 2:43 PM, Mark Meosa wrote:

> Hi Samantha

>

> Thank you for this information, please can you elaborate as to what

> these materials are that you have found as mentioned in the report:

> chrysotile & amosite chrysotile

>

> Kind regards

>

>

> Mark Meosa

>

>  
>  
>

> -----Original Message-----

> From: Sara [mailto:s.pearce@expressltd.net]

> Sent: 18 January 2017 14:29

> To: Mark Meosa <mmeosa@repairsdirect.co.uk>

> Subject: 31 Grenfell Tower

>

> Afternoon,

>

> Please find attached sample result for the above property.

>

> Kind regards

>

--

Sara Monteith-Knight

Regarding

Regarding Bedroom leak

Bedroom leak

