






# THE GRENFELL TOWER INQUIRY

---

## EXHIBIT TNG/2

---

This is the Exhibit marked “TNG/2”  
referred to in the witness statement  
of Tobias Neville Guise

Grenfell Tower 9497						GREEN HIGHLIGHT - VERY GOOD STANDARD	YELLOW HIGHLIGHT - NOT YET ACTIONED						CALL OUT RISK			POTENTIAL COST OF CALL			DATE RECTIFIED	COMMENTS
No of inspections	Item Number	DATE OF INSPECTION	BLOCK / FLOOR / PLOT	LOCATION	ISSUE DESCRIPTION / STANDARD	PICTURE	JSW / SUB CONTRACTOR	STATUS	SNAGGED Y / N	COMMISSIONED	HANDED OVER	GOOD PRACTICE	LOW	MEDIUM	HIGH	LOW	MEDIUM	HIGH		
2	1	17/02/2015	15th floor	Corridor distribution	Geberit Mapress carbon pipework has been crimped on a angle (please cut out)		JSW	1st fix	N	N	N				1			1		
2	2	17/02/2015	10th floor	Corridor distribution	Geberit Mapress carbon pipework has written on it <b>might leak</b> (Richard can you find who has written this on the pipe and why please)		JSW	1st fix	N	N	N				1			1		
2	3	17/02/2015	10th floor	Corridor distribution	Geberit Mapress copper pipework has not been fully inserted into the fitting (please remove IV valve and check fitting has been fully inserted)		JSW	1st fix	N	N	N				1			1		
2	4	17/02/2015	6th floor	Corridor distribution	Geberit Mapress copper pipework excellent making and initialling		JSW	1st fix	N	N	N	1								
2	5	17/02/2015	5th floor	Corridor distribution	Geberit Mapress carbon pipework excellent making and initialling		JSW	1st fix	N	N	N	1								
2		17/02/2015	Summary									2	0	0	3	0	0	3		