

From Basement to 4th floor

NW(3)	N	NE(4)	New 1 SE Old
W		E	
SW(2)	S	SE(1)	

From 4th Floor to 23rd floor

Flat 5	NW(4)	N	NE(5)	Flat 6
Flat 4	W(3)		E(6)	Flat 1
Flat 3	SW(2)	S	SE(1)	Flat 2

Key

GSIUR	Gas Safety (Installation & Use) Regulations
GIUSP	Gas Industry Unsafe Situations Procedure
ECV	Emergency Control Valve
IIV	Installation Isolation Valve
PIV	Property Isolation Valve
ST	ST
ID	Immediately Dangerous

Grenfell Tower Daily Log								NE (5)
Auditors								
Date	CTS	CTS	CTS	Floor No	Flat No or area	Riser	Findings;	Photo ref
16/01/2018	CJ	TB		4	6	NE(5)	2inch ST riser in water tank cupboard off hallway. Sleeve & seal not visible at entry /exit points due to no access.	2633562
16/01/2018	CJ	TB		4	6	NE(5)	ECV in On position, with spinning cap	2633562
16/01/2018	CJ	TB		5	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Concreted in entry and exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		5	6	NE(5)	ECV in On position	2633562
16/01/2018	CJ	TB		5	6	NE(5)	Meter E6 suspended on bracket, regulator partially melted, open end (ID)	2633562
16/01/2018	CJ	TB		6	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Concreted in entry and exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		6	6	NE(5)	ECV in On position. Handle bent	2633562
16/01/2018	CJ	TB		6	6	NE(5)	Meter U6 smoke damaged	2633562
16/01/2018	CJ	TB		6	6	NE(5)	Cooker evident smoke damaged	2633562
16/01/2018	CJ	TB		7	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Concreted in entry and exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		7	6	NE(5)	ECV in On position. Handle bent	2633562
16/01/2018	CJ	TB		7	6	NE(5)	No meter, regulator partially melted, (ID)	2633562
16/01/2018	CJ	TB		7	6	NE(5)	Cooker evident severely fire damaged	2633562
16/01/2018	CJ	TB		8	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Concreted in entry and exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		8	6	NE(5)	ECV in On position.	2633562
16/01/2018	CJ	TB		8	6	NE(5)	Meter U6 suspended on pipe, regulator melted leaving open end (ID)	2633562
16/01/2018	CJ	TB		9	6	NE(5)	2inch riser exposed rear of water tanks due to severe fire damage. Concreted exit points no signs of sleeve.	2633562
16/01/2018	CJ	TB		9	6	NE(5)	ECV in Off position	2633562
16/01/2018	CJ	TB		9	6	NE(5)	No meter evident, regulator holed and top melted	2633562
16/01/2018	CJ	TB		10	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Riser warped. Concreted exit points no signs of sleeves. ECV fitted Off position evidence of regulator melted. Meter not evident.	2633562
16/01/2018	CJ	TB		10	6	NE(5)	ECV in Off position.	2633562
16/01/2018	CJ	TB		10	6	NE(5)	No meter evident, regulator melted	2633562

16/01/2018	CJ	TB		11	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Riser warped. Concreted entry & exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		11	6	NE(5)	ECV in Off position.	2633562
16/01/2018	CJ	TB		11	6	NE(5)	Meter U6 suspended on pipe, regulator melted.	2633562
16/01/2018	CJ	TB		12	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Concreted entry & exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		12	6	NE(5)	ECV in Off position.	2633562
16/01/2018	CJ	TB		12	6	NE(5)	Meter U6 suspended on pipes, top of regulator melted.	2633562
16/01/2018	CJ	TB		13	6	NE(5)	2inch ST riser exposed rear of water tanks due to severe fire damage. Concreted exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		13	6	NE(5)	ECV in Off position capped	2633562
16/01/2018	CJ	TB		13	6	NE(5)	No meter evident	2633562
16/01/2018	CJ	TB		14	6	NE(5)	2inch ST riser reducing to 1 1/2 inch exposed rear of water tanks due to severe fire damage. Concreted in entry and exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		14	6	NE(5)	ECV in On position.	2633562
16/01/2018	CJ	TB		14	6	NE(5)	Meter U6 not in situ, fire damaged, Regulator evidence of melting (ID)	2633562
16/01/2018	CJ	TB		14	6	NE(5)	Cooker evident fire destroyed	2633562
16/01/2018	CJ	TB		15	6	NE(5)	1 1/2 inch riser exposed rear of water tanks due to severe fire damage. Riser warped/bent. Concreted exit points no signs of sleeve.	2633562
16/01/2018	CJ	TB		15	6	NE(5)	ECV position unable to view due to materials in way	2633562
16/01/2018	CJ	TB		15	6	NE(5)	Meter U6, regulator holed attached to meter (ID)	2633562
16/01/2018	CJ	TB		16	6	NE(5)	1 1/2 inch ST riser exposed rear of water tanks. Entry not identified rear of panel . Concreted exit points no signs of sleeves.	2633562
16/01/2018	CJ	TB		16	6	NE(5)	ECV in On position.	2633562
16/01/2018	CJ	TB		16	6	NE(5)	Meter U6 suspended on pipework, regulator meted on top of meter	2633562
18/01/2018	TB	MD		17	6	NE(5)	2inch ST riser. Concreted at high & low level no evident sleeve or seal. Signs of corrosion & fire damage.1" lateral-	2596689
18/01/2018	TB	MD		17	6	NE(5)	ECV in On position.	2596689
18/01/2018	TB	MD		17	6	NE(5)	Meter U6 on bracket, bonding evident, open ended-governor melted (ID)	2596689
18/01/2018	TB	MD		17	6	NE(5)	1"-3/4" ST pipework left open ended at cooker point, copper ripped off (ID). Cooker in Debris.	2596689
18/01/2018	TB	MD		18	6	NE(5)	Suspect reduction of riser from 2inch - 1 1/2inch.Concreted in at high level no evident sleeve or seal. Signs of fire damage and corrosion. Laterals not visible.	2596689
18/01/2018	TB	MD		18	6	NE(5)	ECV not evident	2596689
18/01/2018	TB	MD		18	6	NE(5)	Meter and regulator not evident	2596689
18/01/2018	TB	MD		18	6	NE(5)	Cooker point - bayonet on carcass with cooker hose ripped off at ferrule. Cooker in debris.	2596689
18/01/2018	TB	MD		19	6	NE(5)	1 1/2inch ST riser. Concreted at high & low level no evident sleeve or seal. Signs of corrosion & fire damage. 1" lateral-	2596689
18/01/2018	TB	MD		19	6	NE(5)	ECV in Off position. Open end (ID)	2596689
18/01/2018	TB	MD		19	6	NE(5)	Meter and regulator not evident	2596689
18/01/2018	TB	MD		19	6	NE(5)	Bonding evident no meter present. 1 " - 3/4" carcass open ended at meter union.	2596689
18/01/2018	TB	MD		20	6	NE(5)	1 1/2inch ST riser. Concreted at high & low level no evident sleeve or seal. Signs of corrosion & fire damage. 1" lateral.	2596689
18/01/2018	TB	MD		20	6	NE(5)	ECV in On position.	2596689
18/01/2018	TB	MD		20	6	NE(5)	Meter U6 bracket present but not secured. Regulator melted. (ID)	2596689

18/01/2018	TB	MD		20	6	NE(5)	1"-3/4" ST pipework bayonet with cooker hose ripped off at ferrule. Cooker in debris.	2596689
18/01/2018	TB	MD		21	6	NE(5)	1" ST riser ,warped and fire damaged. Concreted in at low level not sleeve or seal evident.to much debris to ascertain anything else.	2596689
18/01/2018	TB	MD		21	6	NE(5)	ECV not evident	2596689
18/01/2018	TB	MD		21	6	NE(5)	Meter and regulator not evident	2596689
18/01/2018	TB	MD		21	6	NE(5)	internal pipework unable to inspect	2596689
18/01/2018	TB	MD		22	6	NE(5)	1" ST riser .Concreted in at low & High level no sleeve or seal evident. Signs of corrosion & fire damage.	2596689
18/01/2018	TB	MD		22	6	NE(5)	ECV in On position.	2596689
18/01/2018	TB	MD		22	6	NE(5)	Meter U6 unsupported and regulator melted, bonding evident. (ID)	2596689
18/01/2018	TB	MD		22	6	NE(5)	1"-3/4" ST carcass. Open ended at cooker point were copper has been ripped off.	2596689
18/01/2018	TB	MD		23	6	NE(5)	1"-3/4" ST carcass with bayonet at cooker point.	2596689
18/01/2018	TB	MD		23	6	NE(5)	Meter E6 not supported, heavy fire damage and regulator governor melted (ID). Bonding evident.	2596689
18/01/2018	TB	MD		23	6	NE(5)	ECV in On position.	2596689
18/01/2018	TB	MD		23	6	NE(5)	1" ST riser .Concreted in at low level no sleeve or seal evident. Signs of corrosion & fire damage .1" lateral	2596689