From: David Hughes

Sent: 24 March 2016 12:43

To: Terry Ashton

Subject: RE: Grenfell Tower - fire alarm to the hub room

Thank you Terry

Enjoy your retirement !!

Kind regards

Dave

David Hughes

Site Manager

M M

From: Terry Ashton [mailto:Terry.Ashton@Exova.com]

Sent: 24 March 2016 12:34

To: Batty, Tony

Cc: David Hughes; M.Smith@maxfordham.com; Mike Brown; alanwhyte@jswright.co.uk; andy@rjelectrics.co.uk

Subject: Re: Grenfell Tower - fire alarm to the hub room

Yes

Sent from my iPhone

On 24 Mar 2016, at 12:17, Batty, Tony <tbatty@silcockdawson.co.uk> wrote:

Terry,

I assume this is the same for the tank room?

Regards, TonyB.

From: Terry Ashton [mailto:Terry.Ashton@Exova.com]

Sent: 24 March 2016 12:14

To: David Hughes

Cc: M.Smith@maxfordham.com; Mike Brown; alanwhyte@jswright.co.uk; andy@rjelectrics.co.uk;

Batty, Tony

Subject: Re: Grenfell Tower - fire alarm to the hub room

Dave

I confirm that I do not believe it to be necessary to provide a fire alarm in the hub room. I also confirm that it would only be necessary to monitor the fire alarm system in the nursery in the interests of property protection as I do not believe that it is a life safety issue. With regard to the basement, I do not see any point in linking the fire alarm to the main panel as there will not be anyone on site to respond to it

Kind regards

Terry

On 23 Mar 2016, at 08:39, David Hughes < dhughes@rydon.co.uk> wrote:

Hi Terry

I'm the site manager looking after Grenfell Tower and was wondering if you could help with a couple of queries which have been raised by the client team recently.

Please could you confirm the following:

- 1. Following the omission of the 24hr concierge service should there be a fire alarm in the hub room? (see attached drawing showing installed equipment)
- 2. As there are roller shutters on the outside of the new nursery windows should the stand alone fire detection system be remotely monitored in case there is a fire outside opening hours?
- 3. Tank room fire detection (existing) should this be linked to the new system?
- 4. Basement fire detection (existing) should this be linked to the new system?

Feel free to call me on to discuss

Kind regards

Dave

David Hughes Site Manager T

From: Batty, Tony [mailto:tbatty@silcockdawson.co.uk]

Sent: 23 March 2016 08:13

To: David Hughes

Cc: <u>neil.reed@uk.arteliagroup.com</u>; <u>M.Smith@maxfordham.com</u>;

andrew.malcolm@uk.arteliagroup.com; jwhite@jrp.co.uk; clwilliams@kctmo.org.uk;

Dave,

After reading the email trail, there is no mention of the Hub Room but "You state that there is only one level of community space but there are two areas: one at ground floor level; and one at mezzanine level. Given that the occupants of the latter would need to know about an outbreak of fire at ground floor level, I believe that a linked fire alarm should be provided to both areas."

Therefore, I believe that you should seek clarification from Terry Ashton before we can close this matter out, there is also the matter of the following items:

- 1) Nursery fire detection
- 2) Tank room fire detection (existing) should this be linked to the new system?
- 3) Basement fire detection (existing) should this be linked to the new system?

From: David Hughes [mailto:dhughes@rydon.co.uk]

Sent: 23 March 2016 07:18

To: Batty, Tony

Cc: Neil Reed (neil.reed@uk.arteliagroup.com); M.Smith@maxfordham.com; MALCOLM Andrew (andrew.malcolm@uk.arteliagroup.com); 'Jon White' (jwhite@jrp.co.uk); 'Claire Williams' (clwilliams@kctmo.org.uk); Mike Brown;

alanwhyte@jswright.co.uk; andy@rjelectrics.co.uk

Subject: FW: Grenfell Tower - fire alarm to the hub room

Hi Tony

Please see e-mail trail below regarding amendments to the fire strategy following the omission of the concierge

There is no mention of the need for a smoke alarm to the hub room.

We will not be fitting a fire alarm to the hub room unless instructed to do so.

Kind regards

Dave

David Hughes Site Manager

T M

М

From: Andy Bridges [mailto:andy@rjelectrics.co.uk]

Sent: 23 December 2015 14:20 **To:** 'Terry Ashton'; 'Tony Pearson'

Cc: alanwhyte@jswright.co.uk; JonathonEarl@jswright.co.uk; Steve Blake;

M.Smith@maxfordham.com; David Hughes

Subject: RE: Grenfell Tower

Terry,

Thanks for the response.

To clarify the community areas, I'm still treating these as 2 community rooms albeit completely separate from each other, although the TMO aren't sure exactly what they are doing with the 1st floor room now that they have the ground floor facility.

As it stands at the moment I'm installing smoke detection to operate an AOV in both community rooms, either small standalone systems, or if possible as an addition to the main smoke extract system.

When you refer to the linked fire alarm system, are we talking about an audible system for evacuation or detection only to operate the AOVs?

By all means give me a call to discuss.

Regards

Andy

From: Andy Bridges [mailto:andy@rjelectrics.co.uk]

Sent: 21 December 2015 14:06 **To:** Terry Ashton; Tony Pearson

Cc: alanwhyte@jswright.co.uk; JonathonEarl@jswright.co.uk; 'Steve Blake';

M.Smith@maxfordham.com; 'David Hughes'

Subject: Grenfell Tower

Hello Terry,

<image001.jpg>

We are the electrical contractors on this project. I'm not sure if you've been made aware but there have been some fairly major changes to the lower levels since you issued your last Fire Strategy document, Iss 03.

In summary the estate offices and concierge which occupied the southwest corner of the building (as you look at the drawings) through ground, mezzanine and walkway levels have been omitted in favour of 2 no. additional flats at mezz and walkway and a community facility on the ground floor. I have attached the architects latest backgrounds for your assistance.

This raises 3 questions for you:

1) How is the omission of the concierge going to affect your current document and thinking?

The omission of the concierge doesn't materially affect the fire strategy

2) You originally requested a standalone fire alarm system for the office complex. Now that this is only one level of community space are we still to provide a small standalone fire alarm system to cover? You state that there is only one level of community space but there are two areas: one at ground floor level; and one at mezzanine level. Given that the occupants of the latter would need to know about an outbreak of fire at ground floor level, I believe that a linked fire alarm should be provided to both areas. Additionally, there should be a ventilated lobby (an automatic opening vent (AOV) $0.4m^2$ in area between the community room at ground floor level and the main entrance lobby (or an AOV provided in the external wall of the community room) and a fire detection system will be necessary to activate this AOV)

3) Was there any specific fire strategy for the main building entrance lobby? Our tender drawings from Max Fordham indicated some smoke detection in this area, but it was never clear what system they were attached to or if they were controlling anything.

Provided the entrance hall is maintained as a sterile area, I see no need for the provision of smoke detection in it.

By all means give me a call to discuss

Regards Andy

Andy Bridges R J ELECTRICS LTD

T:

E: andrew.bridges@btconnect.com

E:andy@rjelectrics.co.uk

F:

M:

**The liked image control be a before rooted on the control of th

This email transmission is confidential and is intended solely for the addressee. Should you receive this email in error please advise the sender and destroy this transmission. PLEASE THINK OF THE ENVIRONMENT REFORE PRINTING THIS EMAIL

This transmission may contain information that is privileged, confidential and /or exempt from disclosure under applicable law. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution or use of the information contained herein is STRICTLY PROHIBITED. If you receive this transmission in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Unless stated otherwise, any test results included or attached to this email are provisional, and may be subject to revision at a later stage.

This email is sent on behalf of Exova Group plc or the relevant subsidiary with which you are dealing. Exova Group plc is a company incorporated in England and Wales with registered number 08907086. Its registered office is at 6 Coronet Way, Centenary Park, Eccles, Salford M50 1RE.

Exova is the trading name of Exova Group plc and its subsidiaries.

Exova Warringtonfire Aus Pty Ltd is registered in Australia with its registered office at Unit 2, 409-411 Hammond Road, Dandenong, VIC 3175, Australia,

ABN 81 050 241 524.

Please consider the environment before printing this e-mail and any associated attachments.
This email has been scanned by the Symantec Email Security cloud service. For more information please visit http://www.symanteccloud.com
This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com
This email was scanned by Postini, the leading provider in Managed Email Security. If you have received this email and/or have any questions you can contact the Grove Group on or visit our website www.groveis.com
This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com
<pre><rj293_pl_hub-room.pdf></rj293_pl_hub-room.pdf></pre>

This transmission may contain information that is privileged, confidential and /or exempt from disclosure under applicable law. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution or use of the information contained herein is STRICTLY PROHIBITED. If you receive this transmission in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Unless stated otherwise, any test results included or attached to this email are provisional, and may be subject to revision at a later stage.

This email is sent on behalf of Exova Group plc or the relevant subsidiary with which you are dealing. Exova Group plc is a company incorporated in England and Wales with registered number 08907086. Its registered office is at 6 Coronet Way, Centenary Park, Eccles, Salford M50 1RE.

Exova is the trading name of Exova Group plc and its subsidiaries.

Exova Warringtonfire Aus Pty Ltd is registered in Australia with its registered office at Unit 2, 409-411 Hammond Road, Dandenong, VIC 3175, Australia, ABN 81 050 241 524.

Please consider the environment before printing this e-mail and any associated attachments.
This email was scanned by Postini, the leading provider in Managed Email Security. If you have received this email and/or have any questions you can contact the Grove Group on or visit our website www.groveis.com
This transmission may contain information that is privileged, confidential and /or exempt from disclosure under applicable law. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution or use of the information contained herein is STRICTLY PROHIBITED. If you receive this transmission in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Unless stated otherwise, any test results included or attached to this email are provisional, and may be subject to revision at a later stage.
This email is sent on behalf of Exova Group plc or the relevant subsidiary with which you are dealing. Exova Group plc is a company incorporated in England and Wales with registered number 08907086. Its registered office is at 6 Coronet Way, Centenary Park, Eccles, Salford M50 1RE.
Exova is the trading name of Exova Group plc and its subsidiaries.
Exova Warringtonfire Aus Pty Ltd is registered in Australia with its registered office at Unit 2, 409-411 Hammond Road, Dandenong, VIC 3175, Australia, ABN 81 050 241 524.
Please consider the environment before printing this e-mail and any associated attachments.
This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com
·