

*Dennis* ①

Incident No 076029-14062017.

14/6/17.

Date 14/6/2017 (TOD 0022 hours).

Flat 16. GRENFELL T

LAWCASTER WEST ESTATE WIL ITY

STUART BEALE. A24 Red 22 years [REDACTED] sec.

Location at address A24 Solts.

Dennis to ride A241 WATCH MANAGER.

Burntwood St / Wilmslow Rd/ Bonport Rd / L into Grenfell Rd  
SITUATED ON THE EAST SIDE OF THE TOWER  
WITH VISOR ON THE NORTH SIDE ASWEE.

AS I APPROACHED THE EAST SIDE OF GRENFELL TOWER  
THE R/HAND SECTION WAS ALIGHT FROM THE  
LOWEST FLOOR TO THE 25TH FLR.

THE MIDDLE SECTION THE TOP 3 FLRS WERE ALIGHT.

LEFT HAND SECTION OF THE EAST FACE IMMORT.

My role AT THE INCIDENT AS WATCH MANAGER  
WAS THE OIC IN CHARGE OF SECTOR 4

WHICH LATER DEVOLVED INTO SAFETY OFFICER ROLE.

INITIALLY ON ARRIVAL A245 Solts ALP was  
SITUATED OUTSIDE THE EAST FACE (SECTOR 4)  
& IT HAD NO DEDICATED PUMP OR SECURE WATER  
SUPPLY. I LAN SECTOR 4 DETACHING 2 X MFS

MFS TO GO & OBTAIN A PUMPING APPLIANCE  
& SECURE A WATER SUPPLY TO SUPPLY A245.

MFS [REDACTED] LOUNDED WITH A241 TO SUPPLY A245.

ONCE ALP SHIPPED) DETAILED ALP A245 TO GET  
TO WORK AND GET WATER ON THE BUILDING  
AS EFFECTIVELY AS POSSIBLE WITHIN THE CONSTRAINTS  
OF THE AMBIANCE

DUCE TO THE LAY OF THE EXTERIOR GROUND IT  
WAS NOT POSSIBLE TO GET THE AMBULANCE  
CLOSE TO THE BUILDING (GRASS/TREES/ SLOPING GROUND)  
DENNIS WAS FACING FROM THE BUILDING &  
PEOPLE WERE VISIBLE AT CERTAIN WINDOWS ON  
VARIOUS FLRS.

we were unable to reach any persons at any windows.

The water supply was for the ~~air~~ air was being overrun by the cage monster & was ~~not~~ sustainable.

The fire spread was now from the roof down in the outside & left hand section. As the pressure well decomposing material liquid was running down the face of the external paneling & igniting the fire beams. This process was repeated fit by fit from the roof.

We were unable to get water out of or in the building much above the 2/8th fl.

Second I directed Secondary jets to be laid out to extinguish the fire debris on the east & north side.

The air was not functioning correctly & crew well in danger from the fire debris.

I instructed the crew to run back to a safe position.

I instructed the alliance ground monitor to be laid out & got to work on the N/E corner of the building again water supply was insufficient.


Person started on the east side / left hand section approximately 11-13 hoses w/ ~~the~~ the fire spread was traveling towards this flat & we were unable to get water on. With the air <sup>air</sup> crew forward a plan to spray a hose end jet off of new fire alliance to the unopened cage & to attempt to put water on the building at a higher level.

John Hall (3)

14/6/17

with a unmanned cage on AZUS due to crew safety. Repositioned cage & high pressure hose/reel jet (P plate head). And proceeded to put a water curtain onto the side of the building as close to the visibility trained resident on the left hand side approx 11/13<sup>th</sup> floor. This attempt was successful & was effective in preventing fire spread down the building on the left hand section of the east face (Sector 4). Several attempts were made to communicate with the resident who was out of the shot. At this point I was in charge of this sector & was crew safety with debris issue & possible structural issues. The ABD cage AZUS was trained across the face of the building using spotlights & hand signals & keeping a safety cord in place.

I was then instructed to be safety officer in Sector 4 & informed my crews of this change in role / oversee Sector 4 & crew safety assisting crews as required. I continued in this role until handing Sector 4 over to Surrey fire & rescue services ABD & crew & new site operational commander.



MET00005358\_0004