From:	Simon Lawrence [slawrence@rydon.co.uk]
Sent:	09/03/2015 15:18:52
To:	'M.Smith@maxfordham.com' [M.Smith@maxfordham.com]; David Bradbury [DavidBradbury@jswright.co.uk]
CC:	Alan Whyte [AlanWhyte@jswright.co.uk]; d.campbell@maxfordham.com; 'Claire Williams' [clwilliams@kctmo.org.uk]; Simon O'Connor [SOConnor@rydon.co.uk]; BOOTH Philip [philip.booth@uk.arteliagroup.com]; Neil Crawford [Neil@studioe.co.uk]
Subject:	RE: Grenfell Tower - Lobby bulkhead ventilation

Hi Matt,

Thanks for the reminder. We do plan on installing vents as previously discussed. They've just not be installed yet and you are correct that Floor 14 is a mock up to show everyone what the overall ceiling height etc will be like.

Regards

Simon Lawrence, ACIOB, MInstLM
Contracts Manager
T █████████
M █████████

From: M.Smith@maxfordham.com [mailto:M.Smith@maxfordham.com]
Sent: 09 March 2015 15:07
To: David Bradbury
Cc: Alan Whyte; d.campbell@maxfordham.com; 'Claire Williams'; Simon Lawrence; Simon O'Connor; BOOTH Philip; Neil Crawford
Subject: Grenfell Tower - Lobby bulkhead ventilation

Afternoon Dave

I was at Grenfell this morning and noticed that the bulkheads installed on floor 14 do not have any means of ventilation to the main lobby space to dissipate heat build-up. I realise that this is the 'mock-up' floor and as such may not yet represent what will be installed on the remaining floors, but just wanted to make sure that this hadn't slipped off your radar. As per our tender drawings, we'd also stated that ventilation would be required in the riser cupboard doors/wall for the same reasons.

Kind regards,

Matt

MAX FORDHAM
42-43 Gloucester Crescent
London
NW1 7PE
T █████████
F █████████
maxfordham.com

Max Fordham LLP is a Limited Liability Partnership. Registered in England and Wales Number OC300026

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com