

Message

**From:** Robin Cahalarn [cahalarn@kctmo.org.uk]  
**Sent:** 20/02/2006 10:24:41  
**To:** Steve Ellis [steve@bylcl.co.uk]  
**Subject:** RE: Grenfell Tower

sorry forget that found in file 1 -11.8.05

---

From: Robin Cahalarn  
Sent: 20 February 2006 10:23  
To: 'Steve Ellis'  
Subject: RE: Grenfell Tower

steve, I don't seem to of received items for H091 no copy in file will you please forward

---

From: Steve Ellis [mailto:steve@bylcl.co.uk]  
Sent: 20 February 2006 09:33  
To: Gary Poynter  
Cc: Damian Donnelly; Robin Cahalarn; Sarah Everson  
Subject: Grenfell Tower

Gary,

Please find attached typed up version of items lists which need clearing prior to our meeting on 23rd February. Most are done I'm sure. The O&M's are also required for that date. On my latest visit, Tuesday, I noticed the following:

H090

1. No scrolling messages.
2. Landing floors still not cleaned.
3. Alarm pictogram flashing.

H092

1. Synthesiser volume needs reducing.
2. Ride quality still not quite good enough.
3. Fascia scrape at top landing.
4. No deflector guard to tension frame.
5. Dot matrix indicators are red.
6. No scrolling messages.
7. Sills grubby in middle section.

See you next week.

Regards

Steve Ellis

\*\*\*\*\*

This e-mail and all attachments is CONFIDENTIAL.  
If received in error please delete it. The TMO monitors and records all e-mail that it sends and receives.  
Unless stated explicitly, this message does NOT form a legally binding contract or agreement.

\*\*\*\*\*