From: Claire Williams <clwilliams@kctmo.org.uk>

Sent: 19 October 2015 16:47

To: 'Terry Ashton'

Cc: REED Neil; MALCOLM Andrew

Subject: RE: Grenfell tower - changes to floor layout

Attachments: (08) 101 Rev02 - Fire Strategy.pdf

Terry

This plan shows that we had assumed an AOV within the lobby of the boxing club, ie where it is accessible at walkway level (top right drawing).

Would this suffice? I don't know how you would be able to reach to manually reset one at the top of the stairs here.

Thanks for your help.

Claire Williams Project Manager



t: m:

a: The Network Hub, 292a Kensal Road, London, W10 5BE

Before printing, please think about the environment

From: Terry Ashton [mailto:Terry.Ashton@Exova.com]

Sent: 19 October 2015 13:41

To: Claire Williams

Cc: neil reed (neil.reed@uk.arteliagroup.com); MALCOLM Andrew (andrew.malcolm@uk.arteliagroup.com)

Subject: RE: Grenfell tower - changes to floor layout

Claire

I see no need to change my previous advice that it was not necessary to provide a fire alarm system in the boxing club. However, the lobby between the boxing club and Stair A2 needs to be provided with an automatic opening vent which will open upon detection of smoke in the lobby.

Kind regards

Terry

Terry Ashton: Associate, Fire Engineering (Europe)

Exova Warringtonfire

M:



From: Claire Williams [mailto:clwilliams@kctmo.org.uk]

Sent: 19 October 2015 11:20

To: Terry Ashton

Cc: neil reed (neil.reed@uk.arteliagroup.com); MALCOLM Andrew (andrew.malcolm@uk.arteliagroup.com)

Subject: Grenfell tower - changes to floor layout

Hi Terry

I will ring you once I have done this email.

I am looking at the fire detection arrangement for the whole building, as we have changed the layout – and I don't know if this has come back to you.

I attach the plans of the 4 lower floors, showing:

Ground floor no concierge, community room, nursery this layout is not quite right on the last drawing 'proposed floor plans' rev00.pdf, but is close enough. The staircase at the front of the building going up to the next floor has been removed).

<u>First floor</u> (formerly mezzanine) 4 flats, storage room for use by the TMO <u>Second floor</u> (formerly walkway) boxing club (entrance at ground floor), 1 flat

Third floor (formerly walkway +1) 4 flats

We have effectively removed the concierge, and our housing office – but added ground floor community rooms and facilities. Can you please let me know if this changes your advice as below?

| -1 | | E | |
|----|----|----|--|
| Ιh | an | KS | |

W50 FIRE DETECTION & ALARM

General

New fire detection and alarm systems shall be installed in The Nursery, the Office areas and the Meeting Rooms. These areas shall all be provided with at least a Type "M" system as defined in BS5839-1.

Each system in these areas will be "stand alone".

The Boxing Club does not require a fire alarm system.

Claire Williams
Project Manager



m:

a: The Network Hub, 292a Kensal Road, London, W10 5BE

Before printing, please think about the environment

This e-mail message has been scanned for Viruses and Content and cleared by MailMarshal

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom

they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential

information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent

those of Kensington & Chelsea TMO Ltd Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

This transmission may contain information that is privileged, confidential and /or exempt from disclosure under applicable law. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution or use of the information contained herein is STRICTLY PROHIBITED. If you receive this transmission in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Unless stated otherwise, any test results included or attached to this email are provisional, and may be subject to revision at a later stage.

This email is sent on behalf of Exova Group plc or the relevant subsidiary with which you are dealing. Exova Group plc is a company incorporated in England and Wales with registered number 08907086. Its registered office is at 6 Coronet Way, Centenary Park, Eccles, Salford M50 1RE.

Exova is the trading name of Exova Group plc and its subsidiaries.

Exova Warringtonfire Aus Pty Ltd is registered in Australia with its registered office at Unit 2, 409-411 Hammond Road, Dandenong, VIC 3175, Australia, ABN 81 050 241 524.

Please consider the environment before printing this e-mail and any associated attachments.

This e-mail message has been scanned for Viruses and Content and cleared by MailMarshal

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom

they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential

information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent

those of Kensington & Chelsea TMO Ltd Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.