



**From:** Claire Williams [clwilliams@kctmo.org.uk]  
**Sent:** 9/19/2014 3:51:59 PM  
**To:** BOOTH Philip [/O=ORGARTELIA/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Philip Boothe11]  
**Subject:** FW: Grenfell lightning conductor

Can you please check what is in Rydon's contract for this – we have a fire risk assessment showing that the lightning conductor is not continuous in a couple of places?

**Claire Williams**  
**Project Manager**



 Before printing, please think about the environment


Matt

Our fire risk assessor Carl, recently noticed that the lightning conductor was in poor shape.


Rydon have not done any work on the roof yet, and would usually use our contractor to rectify anything like this. I am getting our contract administrator to check their responsibility, but can you also give me the details of who we would use – as Rydon have been using our service contractors to carry out works.

Thanks

**Claire Williams**  
**Project Manager**



t: [REDACTED]  
m: [REDACTED]  
a: The Network Hub, 292a Kensal Road, London, W10 5BE

 Before printing, please think about the environment

---

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

---

**DISCLAIMER:**

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

Artelia\_00009622

**ART00008691/2**  
ART000000001\_0000