

Message

**From:** Claire Williams [clwilliams@kctmo.org.uk]  
**Sent:** 12/5/2014 5:07:25 PM  
**To:** BOOTH Philip [/O=ORGARTELIA/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Philip Boothe11]  
**CC:** VALENTE Nick [/O=ORGARTELIA/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=VALENTE Nickcc9]  
**Subject:** FW: Grenfell Smoke system  
**Attachments:** image001.jpg; image002.jpg


Philip

I will talk to our in-house people next week, as I need to be reassured that everyone knows how the existing system works.


Meanwhile, can you please confirm that the new system as designed will meet the required standards? Then I will talk to my in house team as to what we do in the interim.

I just had a look thro our tender info, and in the FRA pages 23-25 it does cover some of the system workings.

Claire Williams  
Project Manager



t: [REDACTED]  
m: [REDACTED]  
a: The Network Hub, 292a Kensal Road, London, W10 5BE

 Before printing, please think about the environment

---

**From:** Simon O'Connor [mailto:SOConnor@rydon.co.uk]  
**Sent:** 05 December 2014 16:38  
**To:** Claire Williams  
**Cc:** philip.booth@uk.arteliagroup.com; VALENTE Nick (nick.valente@uk.arteliagroup.com); Simon Lawrence  
**Subject:** Grenfell Smoke system

Afternoon Claire,

Following our conversation earlier and the visit from the fire safety specialist I would like to confirm the following.

The system currently installed appears to be a smoke vent release system and operates with the activation of a smoke detector on the lift lobbies. (This is currently out of operation). This in turn sets off a sounder in the old concierge to alert the duty operative who will then look at the fire panel to see what floor the alarm has gone off on and manually press the button on the Tunstall system to call CAS who alerts the fire brigade. As the concierge is no longer in place, in the event of a fire there is no autodial procedure to alert the Fire brigade at present.

I have requested a report on his findings and will forward this when I receive it.

Should you have any queries regarding the above please let me know.

Artelia\_00009653



ART000008786/1  
ART000000/00\_0001

Regards

Simon O'Connor, ACIOB, M InstLM  
Project Manager

T [REDACTED]  
D [REDACTED]

Rydon Maintenance Ltd



This e-mail (including any attachments) is transmitted subject to Rydon Group e-mail terms as published on its [website](#). If you have received this e-mail in error please e-mail the sender by replying to this message. Details of the Company registration numbers and registered offices to which this e-mail relates are also published on its [website](#).

Please consider the environment before printing this email.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

---

**DISCLAIMER:**

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

Artelia\_00009653

ART000008786/2  
ART000000/00\_0002