M	essage	
1.4.1	COOUSE	

From:	BOOTH Philip [/O=ORGARTELIA/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=PHILIP BOOTHE11]
Sent:	9/24/2014 10:19:35 AM
To:	Simon Lawrence (slawrence@rydon.co.uk) [slawrence@rydon.co.uk]
CC:	BLYTHE Peter [/O=ORGARTELIA/OU=EXCHANGE ADMINISTRATIVE GROUP
	(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=BLYTHE Peter2a1]; VALENTE Nick [/O=ORGARTELIA/OU=EXCHANGE
	ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=VALENTE Nickcc9]
Subject:	FW: grenfell lightning conductor and fire alarm

Simon,

I understand the existing lightening protection is damaged and non functional. When are you planning to repair this as part of your works as the TMO have become concerned that it is non functioning via a recent inspection.

I also understand that there is a fault on the existing fire alarm – do you know what the fault is and if it can be resolved quickly?

Kind regards

Philip



This message and any attachments (the "message") is intended solely for the addressees and is confidential. If you receive this message in error, please delete it immediately and notify the sender. Any use not in accordance with its purpose, any dissemination or disclosure, either whole or partial, is prohibited except with explicit formal approval. The internet cannot guarantee the integrity of this message. ARTELIA (and its subsidiaries) shall not therefore be liable for the message if modified.

ARTELIA PROJECTS UK LTD - Registered Office : The Broadgate Tower 3rd Floor 20 Primrose Street London - EC2A 2RS - Trading as ARTELIA UK

Registered in England and Wales under Company Number 03913368

APPLEYARDS LTD - Registered Office : Tubs Hill House London Road Sevenoaks – TN13 1BL - Trading as ARTELIA UK Registered in England and Wales under Company Number 03935522

Artelia_00009621

ART00008814/1 ART00000014_0001