

Message

From: Kelly, Patrick [/O=GRID/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=PATRICK.KELLY2]
Sent: 21/03/2017 19:53:30
To: Loveday, Martin [Martin.Loveday@triio.co.uk]
BCC: Ryan, Mary X [mary.ryan@nationalgrid.com]
Subject: Grenfell Tower
Attachments: P3211557.JPG; P3211571.JPG; P3211560.JPG; P3211568.JPG; P3211570.JPG; P3211573.JPG; P3211575.JPG

Martin,

As discussed , my understanding is that the holes were over drilled to accommodate the ventilation when the boxing is installed.

You have confirmed that the boxing is in hand, can you confirm the start date so that a site visit can be arranged.



P3211560.JPG



P3211557.JPG



P3211575.JPG



P3211573.JPG



P3211570.JPG



P3211568.JPG



P3211571.JPG

Regards

Patrick Kelly
MOBs Specialists
Construction & Procurement
National Grid Gas Distribution Ltd
Imperial Road , London, SW6 2AN
Office: [REDACTED]
Int : [REDACTED]
Mob : [REDACTED]
E Mail : Patrick.Kelly2@nationalgrid.com