

Message

From: [REDACTED]
Sent: 20/02/2017 10:22:46
To: jwray@kctmo.org.uk
Subject: Fwd: Grenfell Tower - Reinstatement Works

FYI

-----Original Message-----

From: carlstokes [REDACTED]
To: Janice Wray <jwray@kctmo.org.uk>
Sent: Mon, 13 Feb 2017 10:20
Subject: Re: Grenfell Tower - Reinstatement Works

Thanks Janice My comments are in Blue.

1. As structural work is being undertaken within this building as part of this project has a Building Regulations application been made for the work/project?
tRIIO has not been requested to submit a Building Regulations application for these works and this has not previously been requested for our works.

This work is a notifiable Building Control issue who has submitted the Building Regulations application for this work, what does the contract say?

2. All holes in compartment wall must be suitably fire stopped using fire rated materials of a minimum of 90 minutes fire rating.
Once the pipe network is installed we will box in to provide fire protection and seal holes that are not needed to provide a flow of air through the boxed sections.

All holes in any compartment wall lining must be sealed and suitably fire stopped using fire rated materials of a minimum of 90 minutes fire rating. There can be no holes or gaps left where pipes penetrate compartment wall or ceiling linings.

3. Documentation should be provided by the gas contractor showing the fire rated materials used for the fire stopping of the compartment walls and the fire rating of the fire collars used.

On completion of our works we will provide documentation to confirm the fire worthiness of our installation.

Noted

Carl

-----Original Message-----

From: Janice Wray <jwray@kctmo.org.uk>

To: carlstokes [REDACTED]
Sent: Fri, 10 Feb 2017 10:56
Subject: FW: Grenfell Tower - Reinstatement Works

FYI

See below

J

Janice Wray
TMO Health, Safety & Facilities Manager
t: [REDACTED]

w: www.kctmo.org.uk
a: 292a Kensal Road, London, W10 5BE.

Before printing, please think about the environment

From: Charlie Saul
Sent: 10 February 2017 10:46
To: Janice Wray <jwray@kctmo.org.uk>
Subject: FW: Grenfell Tower - Reinstatement Works

Hi Janice,

Please see National Grid response below.

Kind regards,

Charlie

Charlie Saul
Contracts Manager
Assets and Regeneration
Kensington & Chelsea TMO

csaul@kctmo.org.uk
[REDACTED]

www.kctmo.org.uk
0800 137 111
292a Kensal Road, London, W10 5BE
Before printing, please think about the environment

From: Smith, Harvey [<mailto:Harvey.Smith@trio.co.uk>]
Sent: 10 February 2017 10:42
To: Charlie Saul <csaul@kctmo.org.uk>
Cc: Loveday, Martin <Martin.Loveday@trio.co.uk>; Wisken, Martyn <Martyn.Wisken@trio.co.uk>
Subject: RE: Grenfell Tower - Reinstatement Works

Charlie

Please see responses below:-

1. As structural work is being undertaken within this building as part of this project has a Building Regulations application been made for the work/project?
TRIO has not been requested to submit a Building Regulations application for these works and this has not previously been requested for our works.
2. All holes in compartment wall must be suitably fire stopped using fire rated materials of a minimum of 90 minutes fire rating.

Once the pipe network is installed we will box in to provide fire protection and seal holes that are not needed to provide a flow of air through the boxed sections.
3. Documentation should be provided by the gas contractor showing the fire rated materials used for the fire stopping of the compartment walls and the fire rating of the fire collars used.
On completion of our works we will provide documentation to confirm the fire worthiness of our installation.

Regards

Harvey Smith
Operations Support Manager

tRIIO®
National Grid
Albert Road
East Barnet
EN4 9SH
Phone: [REDACTED]
Email: harvey.smith@trio.co.uk

From: Charlie Saul [mailto:csaul@kctmo.org.uk]
Sent: 31 January 2017 14:51
To: Smith, Harvey
Cc: Radley, Andrew
Subject: Grenfell Tower - Reinstatement Works

Good afternoon Harvey,

Please see the report attached from our Fire Risk Assessor.

Could you please provide comments and assurances to the points raised?

Kind regards,

Charlie

Charlie Saul
Contracts Manager
Assets and Regeneration
Kensington & Chelsea TMO

csaul@kctmo.org.uk
[REDACTED]

www.kctmo.org.uk
[REDACTED]

292a Kensal Road, London, W10 5BE
PBefore printing, please think about the environment

This e-mail message has been scanned for Viruses and Content and cleared by MailMarshal

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

CST00001369_0003

CST00001369/3

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

We work safely or not at all

tRIIO® is a joint venture partnership between Morrison Utility Services and Skanska Construction UK. A gas distribution strategic partner.

The information contained in this message is likely to be confidential and may be legally privileged. It is intended solely for the use of the individual or entity to which it is addressed. If you have received this message by mistake, please let us know immediately by replying to this email and then delete all copies of the email from your system. If you are not the intended recipient you must not disclose, distribute, copy, print or rely on this email.

Whilst we have taken reasonable precautions to ensure that this email and any attachments have been checked for viruses we cannot guarantee that they are virus free and we cannot accept liability for any damage sustained as a result of software viruses. We would advise that you carry out your own virus checks especially before opening an attachment.

tRIIO® cannot accept any responsibility for the accuracy or completeness of this email and unless otherwise expressly stated does not authorise any contract to be made by email. tRIIO® may recall, delete and monitor all outgoing and incoming emails.

Morrison Utility Services Limited
Registered Office: Abel Smith House, Gunnels Wood Road, Stevenage, Hertfordshire, SGI 2ST
Registered in England. Company Number 4530602

Skanska Construction UK Limited
Registered Office: Maple Cross House, Denham Way, Maple Cross, Rickmansworth, Hertfordshire WD3 9SW
Registered in England. Company Number 191408

Please consider the environment before printing this email

This e-mail message has been scanned for Viruses and Content and cleared by MailMarshal

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any virus transmitted by this email.