

Message

Sent: 16/07/2015 13:57:54
To: Adrian Bowman [abowman@kctmo.org.uk]
Subject: Re: grenfell tower

Afternoon Adrian.

The holes you see are from the drill/ cutter used to drill the holes through the concrete walls. They do not go all the way through the wall just in a little bit .

The contract says these should all be filled in before the ceiling goes in

Carl

Sent from my HTC

----- Reply message -----

From: "Adrian Bowman" <abowman@kctmo.org.uk>
To: [REDACTED]
Subject: grenfell tower
Date: Thu, Jul 16, 2015 11:23

Carl

Janice asked me to forward this to you as I believe you may have discussed with Rydons?

I was inspecting here yesterday and concerned that many of the flat entrance doors appear to have had extra holes drilled above the door - see example photo attached. I'm not sure why these are there as much of the distribution pipework has been installed. There is a false ceiling being installed to hide the pipe work etc. and concerned that this may go up without the holes being fire stopped. Do we have any assurances from them regarding this?

Thanks

adrian

This e-mail message has been scanned for viruses and Content and cleared by MailMarshal

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any virus transmitted by this email.