
From: Janice Wray <jwray@kctmo.org.uk>
Sent: 20 July 2016 17:02
To: [REDACTED]
Subject: FW: Grenfell FRA 12c: Confirmation of BC instruction to not fit smoke seals to new lift lobby doors @ Grenfell Tower

Scroll down – confirmation from BC ref:12C on action Plan

J

Janice Wray
TMO Health, Safety & Facilities Manager
t: [REDACTED]



w: www.kctmo.org.uk
a: 292a Kensal Road, London, W10 5BE.

Before printing, please think about the environment

From: Claire Williams
Sent: 06 July 2016 09:40
To: Janice Wray <jwray@kctmo.org.uk>
Subject: Grenfell FRA 12c: Confirmation of BC instruction to not fit smoke seals to new lift lobby doors @ Grenfell Tower

Janice

This is one of a couple of emails to evidence info on Carl's FRA.

Once I have sent them all thro I will book you to go thro it – today/tomorrow hopefully.

Claire Williams
Project Manager



t: [REDACTED]
m: [REDACTED]
a: The Network Hub, 292a Kensal Road, London, W10 5BE

Before printing, please think about the environment

From: David Hughes [<mailto:dhughes@rydon.co.uk>]
Sent: 05 July 2016 14:42

To: Claire Williams <clwilliams@kctmo.org.uk>

Subject: FW: Confirmation of BC instruction to not fit smoke seals to new lift lobby doors @ Grenfell Tower

Hi Claire

Confirmation of omission of smoke seals to new lift lobbies as requested in FRA.

Kind regards

Dave

David Hughes
Site Manager

T [REDACTED]
M [REDACTED]

From: David Hughes

Sent: 05 July 2016 14:41

To: 'Paul.Hanson@rbkc.gov.uk'

Cc: John.Hoban@rbkc.gov.uk; Steve Blake

Subject: RE: Confirmation of BC instruction to not fit smoke seals to new lift lobby doors @ Grenfell Tower

Hi Paul

Thank you for your quick reply

I confirm that we have fitted intumescent strips in lieu of the smoke seals

Kind regards

Dave

David Hughes
Site Manager

T [REDACTED]
M [REDACTED]

From: Paul.Hanson@rbkc.gov.uk [<mailto:Paul.Hanson@rbkc.gov.uk>]

Sent: 05 July 2016 14:08

To: David Hughes

Cc: John.Hoban@rbkc.gov.uk; Steve Blake

Subject: RE: Confirmation of BC instruction to not fit smoke seals to new lift lobby doors @ Grenfell Tower

Hi David,

I confirm that due to the need for the powered lobby ventilation system to draw inlet air from the stairway, it is recommended that 'smoke seals' are not included on the doors between the stairway and lobby to enable the system to operate at full efficiency.

Note that this does not refer to any intumescent strips.

Regards.

Paul Hanson
Senior Building Control Surveyor (Fire Regulations)
Royal Borough of Kensington and Chelsea
T. [REDACTED]

M. [REDACTED]
F. [REDACTED]
W. www.rbkc.gov.uk/buildingcontrol

From: David Hughes [<mailto:dhughes@rydon.co.uk>]
Sent: 05 July 2016 12:17
To: Hanson, Paul: CP-Plan <Paul.Hanson@rbkc.gov.uk>
Cc: Hoban, John: CP-Plan <John.Hoban@rbkc.gov.uk>; Steve Blake <SBlake@rydon.co.uk>
Subject: Confirmation of BC instruction to not fit smoke seals to new lift lobby doors @ Grenfell Tower

Hi Paul

Please could you confirm your instruction for us not to fit the smoke seals to the lift lobby doors at Grenfell Tower?

I need to confirm this to our client as their Fire Risk Assessor has raised it an issue on his latest report.

Any questions, please give me a call

Kind regards

Dave

David Hughes
Site Manager

T [REDACTED]
M [REDACTED]

Rydon Maintenance Ltd
Marlborough House, Warrior Square, St Leonards on Sea, East Sussex, TN37 6BG.



This e-mail (including any attachments) is transmitted subject to Rydon Group e-mail terms as published on its [website](#). If you have received this e-mail in error please e-mail the sender by replying to this message. Details of the Company registration numbers and registered offices to which this e-mail relates are also published on its [website](#).

Please consider the environment before printing this email.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

The Royal Borough of Kensington and Chelsea.
This e-mail may contain information which is confidential,
legally privileged and/or copyright protected. This e-mail
is intended for the addressee only. If you receive this in
error, please contact the sender and delete the material
from your computer.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.