

---

**From:** Neil Crawford  
**Sent:** 03 March 2015 14:36  
**To:** Terry Ashton  
**Subject:** FW: Grenfell  
**Attachments:** 855 C1059 GA Model 33 202C (1).pdf; 855 C1059 GA Model 33 201D (1).pdf; 855 C1059 GA Model 33 200I (1).pdf; 855 C1059 GA Model 33 100A (1).pdf; 855 C1059 Grenfell Tower Register Sht 1.pdf; 855 C1059 GA Model 33 305C (1).pdf; 855 C1059 GA Model 33 301E (1).pdf; 1279 SEA (08) 101 Rev 04 - Fire Strategy.dgn.pdf

Hi Terry

Just a quick question relating to Grenfell Tower. As part of the re-clad we are we have added fire breaks around the apartments as per the email below. Can you comment on the level of protection (90+ 30) as to whether this is suitable. My only query might be that we have different levels of party wall at the lower levels- see attached fire plan with some 60 some 120 walls.

Regards  
Neil

---

**From:** Kevin Lamb [<mailto:KevinLamb@harleycw.co.uk>]  
**Sent:** 03 March 2015 12:58  
**To:** [slawrence@rydon.co.uk](mailto:slawrence@rydon.co.uk)  
**Cc:** Neil Crawford; Bruce Sounes; Daniel Anketell-Jones; Mark Stapley; Rob Maxwell; Ben Bailey  
**Subject:** Grenfell

Simon,

Please find attached drawings now showing the fire breaks, both horizontal and vertical.

We assume a requirement of 90min integrity & 30min insulation is sufficient, if not please advise.

The vertical breaks are not on all columns, just party walls.

Regards

Kevin Lamb  
Project Designer



T- [REDACTED]  
F- [REDACTED]  
W- [www.harleycurtainwall.com](http://www.harleycurtainwall.com)

**Head Office**  
Harley House, Brooklands Park  
Farningham Road, Crowborough  
East Sussex, TN6 2JD

**Email Disclaimer:**

This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where

the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.