

From: Terry Ashton
Sent: 20 October 2015 08:15
To: Claire Williams
Cc: neil reed (neil.reed@uk.arteliagroup.com); MALCOLM Andrew (andrew.malcolm@uk.arteliagroup.com)
Subject: RE: Grenfell tower - changes to floor layout
Attachments: Grenfell Tower.pdf

I think we may be at cross purposes. See the attached. The AOV that I was referring to is the one you mentioned

Terry

T: [REDACTED] M: [REDACTED]



From: Claire Williams [mailto:clwilliams@kctmo.org.uk]
Sent: 19 October 2015 16:47
To: Terry Ashton
Cc: neil reed (neil.reed@uk.arteliagroup.com); MALCOLM Andrew (andrew.malcolm@uk.arteliagroup.com)
Subject: RE: Grenfell tower - changes to floor layout

This plan shows that we had assumed an AOV within the lobby of the boxing club, ie where it is accessible at walkway level (top right drawing).

Thanks for your help.

Claire Williams
Project Manager



t: [REDACTED]
m: [REDACTED]

a: The Network Hub, 292a Kensal Road, London, W10 5BE

Before printing, please think about the environment

From: Terry Ashton [<mailto:Terry.Ashton@Exova.com>]

Sent: 19 October 2015 13:41

To: Claire Williams

Cc: neil reed (neil.reed@uk.arteliagroup.com); MALCOLM Andrew (andrew.malcolm@uk.arteliagroup.com)

Subject: RE: Grenfell tower - changes to floor layout

Claire

I see no need to change my previous advice that it was not necessary to provide a fire alarm system in the boxing club. However, the lobby between the boxing club and Stair A2 needs to be provided with an automatic opening vent which will open upon detection of smoke in the lobby.

Kind regards

Terry

Terry Ashton: Associate, Fire Engineering (Europe)

Exova Warringtonfire

T: [REDACTED] M: [REDACTED]



From: Claire Williams [<mailto:clwilliams@kctmo.org.uk>]

Sent: 19 October 2015 11:20

To: Terry Ashton

Cc: neil reed (neil.reed@uk.arteliagroup.com); MALCOLM Andrew (andrew.malcolm@uk.arteliagroup.com)

Subject: Grenfell tower - changes to floor layout

Hi Terry

I will ring you once I have done this email.

I am looking at the fire detection arrangement for the whole building, as we have changed the layout – and I don't know if this has come back to you.

I attach the plans of the 4 lower floors, showing:

Ground floor no concierge, community room, nursery this layout is not quite right on the last drawing 'proposed floor plans' rev00.pdf, but is close enough. The staircase at the front of the building going up to the next floor has been removed).

4 flats, storage room for use by the TMO

boxing club (entrance at ground floor), 1 flat

4 flats

Thanks _____

General:


Each system in these areas will be “stand alone”.

The Boxing Club does not require a fire alarm system.



114

1. *Journal of the American Medical Association*, 1997; 278: 1019-1024.

 Before printing, please think about the environment

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

