From: Ben BaileyHCW Sent: 02 April 2015 16:20

To: Ricky Kay

Cc: Mark StapleyHCW

Subject: Re: Grenfell Tower Fire Stopping

Attachments: image001.png; image002.png; image003.png; image004.jpg; image005.jpg;

Appendix 6a - Grenfell Traffic Management Plan.pdf; PO9219-037 - Siderise -

Horizontal & Vertical Fire Breaks.pdf; Fire Break Call Off - Grenfell.pdf

Hi Ricky,

Please see order and relevant information attached. If possible can you arrange to have the fixing spikes sent to site ASAP so we can get on with fixing them please,

Best Regards,

Ben



Ben Bailey | Project Manager

| benbailey@harleycw.co.uk

Harley Curtain Wall Ltd | Office: Fax: Harley House, Brooklands Park, Crowborough, East Sussex, TN6 2JD harleycurtainwall.com



This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.

From: Ricky Kay <<u>ricky.kay@siderise.com</u>> **Date:** Thursday, 2 April 2015 15:56

To: Ben Bailey < benbailey@harleycw.co.uk > Subject: RE: Grenfell Tower Fire Stopping

Afternoon Ben,

Glad that's all sorted! Ping the order over to me with the note to supply 400mm long brackets and I will get it sorted for you. If I don't speak to you then have a great weekend.

Cheers

Kind regards

Ricky Kay

National Façades Manager

M:
E: ricky.kay@siderise.com

**The held image corol to dedend: The filt may have been record, recurred, or defined, when the help point to the corol file and beddend:

Siderise Group, Forge Industrial Estate, Maesteg, Bridgend CF34 0AY

F: - | W: www.siderise.com



I guess not! Thanks for the help guys, I'll get going on the order,



Ben Bailey | Project Manager benbailey@harleycw.co.uk

Harley Curtain Wall Ltd | Office: | Fax: Harley House, Brooklands Park, Crowborough, East Sussex, TN6 2JD harleycurtainwall.com



This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.

From: "Chris C. Mort" <chris.mort@siderise.com>

Date: Thursday, 2 April 2015 11:20

To: Ben Bailey <benbailey@harleycw.co.uk>, Ricky Kay <ricky.kay@siderise.com>

Subject: RE: Grenfell Tower Fire Stopping

Hi Ben,

Sense at last from the BCO, so I take it the meeting for Tuesday is not needed, if you need any further assistance in the future please do not hesitate in contacting us.

Kind regards

Chris Mort

Technical Officer Fire

M: DDI:

chris.mort@siderise.com



Siderise Group, Forge Industrial Estate, Maesteg, Bridgend CF34 0AY

W: www.siderise.com

Connect to us:



From: Ben Bailey [mailto:Benbailey@harleycw.co.uk]

Sent: 02 April 2015 09:55

To: Ricky Kay

Cc: Chris C. Mort

Subject: FW: Grenfell Tower Fire Stopping

Morning Ricky,

As discussed please see drawing attached showing the placement of the firebreak at the head of the window. The BCO has agreed to the definition of a cavity so I believe that the 30/15 equivalent product can be used?

Best Regards,

Ben



Ben Bailey | Project Manager

| benbailey@harleycw.co.uk

Harley Curtain Wall Ltd | Office: | Fax: Harley House, Brooklands Park, Crowborough, East Sussex, TN6 2JD harleycurtainwall.com



This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.

From: Simon Lawrence <slawrence@rydon.co.uk>

Date: Wednesday, 1 April 2015 15:46

To: Ben Bailey < benbailey@harleycw.co.uk>, Ray Bailey < Raybailey@harleycw.co.uk> Cc: Neil Crawford < neil@studioe.co.uk>, Simon O'Connor < SOConnor@rydon.co.uk>

Subject: FW: Grenfell Tower Fire Stopping

Gents,

The Building Control officer is now in agreement with the fire protection in the cladding being a 'cavity barrier' rather a fire stop as first thought.

Good news Regards

Simon Lawrence, ACIOB, MInstLM

Contracts Manager

T M

From: John. Hoban@rbkc.gov.uk [mailto: John. Hoban@rbkc.gov.uk]

Sent: 01 April 2015 09:57

To: Neil Crawford

Cc: slawrence@rydon.co.uk

Subject: RE: Grenfell Tower Fire Stopping

Dear Neil,

The Building Regulations 2010 (as amended)

Grenfell Tower, Grenfell Road, Refurbishment Project.

Thank you for your email and for the attached drawing, showing typical cladding details. The matter has now become more clearer.

I would advise you that I have no adverse comments to make on the proposals shown on your drawing 1279 (06) 110 rev. 00, with regards to compliance with Parts B2 and B3 in Schedule 1 of the building regulations.

I would be grateful if you would forward to me the drawings for the external walls to the boxing club floor, the mezzanine floor and the mezzanine plus one floor, as it my impression that the cladding / floor junction detail for those particular floors defer from that shown on drawing 1279 (06) 110 rev. 00. I would like to review them prior to giving further comments on the cladding.

I look forward to receiving the details in due course.

Best regards.

John

John Hoban

Senior Building Control Surveyor

john.hoban@rbkc.gov.uk

This e-mail may contain information which is confidential, legally privileged and/or copyright. This e-mail is intended for the addressee only. If you receive this in error, please contact the sender and delete the material from your computer.

From: Neil Crawford [mailto:Neil@studioe.co.uk]

Sent: 31 March 2015 12:00 **To:** Hoban, John: PC-Plan **Cc:** slawrence@rydon.co.uk

Subject: RE: Grenfell Tower Fire Stopping

Hi John

Unfortunately this problem is not going away.

The subject of fire barriers is raising a lot of concern on site not least because of program and cost. I have forwarded a copy of diagram 33 and the typical floor detail and we are all miffed as to why this detail is not a cavity barrier in this location- please see attached. The relationship between the back of slab and cladding remains the same as the original cladding (concrete) is retained and therefore the integrity of this relationship at floor level has not been affected. The new cladding constitutes an additional layer applied on top not a new floor slab interface and therefore the interpretation is that this constitutes a cavity barrier and not a fire stop. This has now become something of an issue on site due to program bottle neck and so your earliest response to this would be appreciated...

Regards Neil

From: John. Hoban@rbkc.gov.uk [mailto: John. Hoban@rbkc.gov.uk]

Sent: 30 March 2015 14:22

To: <u>sue.sheppard@siderise.com</u>; <u>ricky.kay@siderise.com</u>; <u>benbailey@harleycw.co.uk</u>; <u>KevinLamb@harleycw.co.uk</u>; Neil Crawford; <u>mark@harleycw.co.uk</u>; <u>SOConnor@rydon.co.uk</u>; <u>slawrence@rydon.co.uk</u>; <u>Terry.Ashton@Exova.com</u>

Subject: FW: Grenfell Tower Fire Stopping

Dear All,

The Building Regulations 2010 (as amended)

Grenfell Tower, Grenfell Road, Refurbishment.

Please find detailed below a copy of an email sent to various persons on the 20th of March 2015, concerning the topic relating fire stopping of the compartment floors to the building. I would advise you that it is my interpretation of diagram 33 of Approved Document B is that the detail between compartment floors and external cladding is not a cavity barrier, therefore it must be fire stopped to at least the standard of the existing compartment floor [120 minutes]. Therefore the methods described in clause 9.13 would not be appropriate in this particular case

In the meantime should you wish to discuss any other aspects of the project, then please do not hesitate to call me, my direct line contact number is

Best regards, John Hoban John Hoban

Senior Building Control Surveyor

john.hoban@rbkc.gov.uk

This e-mail may contain information which is confidential, legally privileged and/or copyright. This e-mail is intended for the addressee only. If you receive this in error, please contact the sender and delete the material from your computer.

From: Hoban, John: PC-Plan Sent: 20 March 2015 13:22

To: 'Neil Crawford'; Hanson, Paul: PC-Plan

Cc: slawrence@rydon.co.uk; Kevin Lamb (KevinLamb@harleycw.co.uk); Simon O'Connor

(SOConnor@rydon.co.uk); Jason North (jnorth@rydon.co.uk)

Subject: RE: Grenfell

Dear Neil,

The Building Regulations 2010 (as amended)
Grenfell Tower, Grenfell Road, Refurbishment.
Thank you for returning my call this morning.

Further to my conversation with you today, I would confirm that the *fire time* for the new *Elements of Structure* [new columns, beams, sections of compartment floor etc.] in Grenfell Tower is 120 minutes, as specified in section 1a of Table A2, Appendix A of Approved Document B.

I would also draw your attention to diagram 33 of Approved Document B and highlight the detail between compartment floors and external cladding. In the meantime should you wish to discuss any other aspects of the project Neil, then please do not hesitate to call me, my direct line contact number is

Best regards, John Hoban John Hoban

Senior Building Control Surveyor

john.hoban@rbkc.gov.uk

This e-mail may contain information which is confidential, legally privileged and/or copyright. This e-mail is intended for the addressee only. If you receive this in error, please contact the sender and delete the material from your computer.

From: Neil Crawford [mailto:Neil@studioe.co.uk]

Sent: 30 March 2015 12:49 **To:** Hoban, John: PC-Plan

Subject: RE: Grenfell Tower Fire Barriers

Hi John

Ben Bailey from Harley's is who you might ask for. His phone number is

Regards Neil

From: Neil Crawford
Sent: 27 March 2015 10:53
To: john.hoban@rbkc.gov.uk

Cc: Terry.Ashton@Exova.com; Paul.Hanson@rbkc.gov.uk

Subject: Grenfell Tower Fire Barriers

Hi John

There has been a lot of conversation on site about the cavity fire barrier requirements to be fitted between the existing concrete external wall panels and the new external rain screen aluminium cassettes.

Can you please see the proposal by the cladding contractor below and confirm if this is acceptable to you.

Regards

Neil

cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.

From: Ricky Kay <<u>ricky.kay@siderise.com</u>>
Date: Thursday, 26 March 2015 13:42
To: Ben Bailey <<u>benbailey@harleycw.co.uk</u>>

Cc: Kevin Lamb < KevinLamb@harleycw.co.uk >, Mark Stapley >, Sue Sheppard < sue.sheppard@siderise.com >

Subject: RE: Grenfell Tower Fire Barriers

Hi Ben,

Apologies for the delay...

Please find below extract from the Approved Document B of the Building Regulations.

PERFORMANCE OF MATERIALS, PRODUCTS AND STRUCTURES Table A1 continued Part of building Minimum provisions when tested to the relevant part of BS 476 ⁽ⁿ⁾ (minutes) Method of Minimum exposure provisions when tested Loadbearing Insulation to the relevant capacity a European standard (minutes) 15. Cavity barrier Not applicable 15 E 30 and El 15 Each side 30 Here you can see that it clearly states that 30 minutes fire integrity and 15 minutes insulation is all that is required from a cavity fire barrier. This is reference to rainscreen cladding applications where the cavity barrier is deemed to be on the outside of the building. Our RH25-90/30 will offer 90 minutes fire integrity and 30 minutes fire insulation, therefore exceeds minimum requirements. 120 minute fire rating is generally the industry standard for curtain wall to concrete slab edge firestopping where the firestop is located on the inside of a building and is considered to be a continuation of the floor slab. Please get in touch if you need anything else from us to enable you to progress with your order, many thanks Kind regards Ricky Kay National Façades Manager M: E: ricky.kay@siderise.com Siderise Group, Forge Industrial Estate, Maesteg, Bridgend CF34 0AY | W: www.siderise.com Connect to us: ease consider the environment before printing this e-mail This email has been scanned by the Symantec Email Security cloud service. For more information please visit http://www.symanteccloud.com This email has been scanned by the Symantec Email Security cloud service. For more information please visit http://www.symanteccloud.com Right Royal Ride Saturday 25 April Enjoy a leisurely cycle through the Royal Borough and raise money for local charities. Have fun at the post cycle celebration in Holland Park – it's the perfect family event.

Register at http://www.bikeminded.org/whats-on/

Are you registered to vote? The deadline to register to vote for the UK Parliamentary election is Monday 20 April 2015.

You can register to vote at http://www.gov.uk/registertovote

The Royal Borough of Kensington and Chelsea.
This e-mail may contain information which is confidential,
legally privileged and/or copyright protected. This e-mail
is intended for the addressee only. If you receive this in
error, please contact the sender and delete the material
from your computer.

Right Royal Ride Saturday 25 April
Enjoy a leisurely cycle through the Royal Borough and raise money for local charities.
Have fun at the post cycle celebration in Holland Park – it's the perfect family event.
Register at http://www.bikeminded.org/whats-on/
Are you registered to vote? The deadline to register to vote for the UK Parliamentary election is Monday 20 April 2015.
You can register to vote at http://www.gov.uk/registertovote

The Royal Borough of Kensington and Chelsea.
This e-mail may contain information which is confidential,
legally privileged and/or copyright protected. This e-mail
is intended for the addressee only. If you receive this in
error, please contact the sender and delete the material
from your computer.

This email has been scanned by the Symantec Email Security cloud service.
For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com