

Paragraph Number	BSR Reference	Inquiry URN	Description
		{IWS00001573}	Phase 2 Witness Statement of Daniel Brendan Griffin
24	DG/1	{IWS00001579}	Exhibit DG/1 - Bedroom ceiling after sampling
25, 28, 30	DG/2	{IWS00001576}	Exhibit DG/2 - Email chain dated 16 January 2017 between Cllr Blakeman & KCTMO re Daniel Griffin's complaint about his flat affected by a flood and other repairs issues which have not been resolved by KCTMO
26	DG/5	{IWS00001569}	Exhibit DG/5 - Email from Catherine Dack to Daniel Griffin responding to his stage one complaint about KCTMO's failure and delay to carry out repairs in Flat 31 following a flood and complaint upheld and left open until repairs are completed, and letter from Catherine Dack to Daniel Griffin with a holding response to his stage 2 complaint
27	DG/3	{IWS00001570}	Exhibit DG/3 - 'No unauthorised persons beyond this point' sign on Daniel Griffin's bedroom door
	DG/4	{IWS00001578}	Exhibit DG/4 - Photographs of bedroom and hallway ceiling of Flat 31
35	DG/6	{IWS00001583}	Exhibit DG/6 - Certificate for identification of asbestos fibres for Flat 31
36	DG/7	{IWS00001581}	Exhibit DG/7 -Email chain between KCTMO Repairs Direct and Express Environmental Solutions Ltd regarding asbestos found in Flat 31