

Paragraph Number	BSR Reference	Inquiry URN	Description
		{IWS00002065}	Phase 2 Witness Statement of Samuel Daniels
13	MAS00000027	{MAS00000027}	Letter from TMO to Manse Masterdor Ltd regarding fire door replacement programme 2011-2012
	SD/01	{IWS00002066}	Exhibit SD/01 - KCTMO repairs log for Flat 135
15	SD/02	{IWS00002067}	Exhibit SD/02 - KCTMO repairs log for Flat 135 regarding front door not closing
	SD/03	{IWS00002068}	Exhibit SD/03 - KCTMO dashboard snapshot of front door repair at Flat 135 stating "overhaul complete UPVC front door"
	SD/04	{IWS00002069}	Exhibit SD/04 - KCTMO dashboard snapshot of the repairs log for Fat 135 regarding front door repair
	SD/05	{IWS00002070}	Exhibit SD/05 - KCTMO dashboard snapshot to renew front door
19	SD/06	{IWS00002071}	Exhibit SD/06 - Floor plan of Flat 135
21	RYD00093596	{RYD00093596}	Rydon- Grenfell Tower Handover Form Flat 135
	RYD00056126	{RYD00056126}	Email from Rydon to SD Plastering regarding window restrictor and trim in flat 135
	RYD00057500	{RYD00057500}	Email from Rydon to SD Plastering regarding vertical trim to living room window being too close to the window, flat 135.
22	SD/07	{IWS00001983}	Exhibit SD/07 - Photographs of exposed copper pipes in Flat 135
	TMO10011314	{TMO10011314}	Rydon Snagging Inspection Sheet for Flat 135 Grenfell Tower.
23	RYD00059521	{RYD00059521}	Electrical installation works certificate flat 135

25	SD/08	{IWS00002048}	Exhibit SD/08 - Picture of Grenfell Tower in the 1970s.
33	RYD00025356	{RYD00025356}	Email between Rydon and Artelia re Show Flat 145 Heating Layout, Windows and the Boxing Club at Grenfell Tower
38	SD/06	{IWS00002071}	Exhibit SD/06 - Floor plan of Flat 135
41	SD/09	{IWS00002049}	Exhibit SD/09 - Photograph of exposed copper pipes next to the boiler in Flat 135
46	EX000001489	{EX000001489}	Picture of Dry Riser, Fire Panel, lifts and lobby
55	TMOH00024715	{TMOH00024715}	KCTMO Neighbourhood Support Officer Referral Form re Flat 135
69	INQ00000445	{INQ00000445}	01-38-40 Cam 1 (Samuel Daniels exits).jpg