





THE GRENFELL TOWER INQUIRY

EXHIBIT TNG/7

This is the Exhibit marked “TNG/7”
referred to in the witness statement
of Tobias Neville Guise

Grenfell Tower 9497						GREEN HIGHLIGHT - VERY GOOD STANDARD	YELLOW HIGHLIGHT - NOT YET ACTIONED							CALL OUT RISK			POTENTIAL COST OF CALL			DATE RECTIFIED	
No of Inspections	Item Number	DATE OF INSPECTION	BLOCK / FLOOR / PLOT	LOCATION	ISSUE DESCRIPTION / STANDARD	PICTURE	JSW / SUB CONTRACTOR	Underlining Issue	SNAGGED Y / N	COMMISSIONED	HANDED OVER	GOOD PRACTICE	LOW	MEDIUM	HIGH	LOW	MEDIUM	HIGH			
9	1	17/11/2015	Flat 44	Hall way	22mm pipework at high level is not in the clips		Stanley Mec	Pipework poor	N	N	N			1			1				
9	2	17/11/2015	Flat 16	Lounge	Radiator has very sharp strips of metal sticking out the top of the radiator which looks like swarf, radiator needs changing		JSW	Manufacture	N	N	N				1		1				
9	3	17/11/2015	Boxing gym	Boxing gym	Radiator has very sharp strips of metal sticking out the top of the radiator which looks like swarf, radiator needs changing		JSW	Manufacture	N	N	N				1		1				
9	4	17/11/2015	Boxing Gym	Shower room	Heating circulating pump does not have isolation valves, the system would have to be drained to change pump if required please install valves each side of the pump		JSW	Hlu	N	N	N		1				1				
9		17/11/2015	Summary									0	1	1	2	0	4	0			
		Item 1&2 please ensure all radiators are checked closely for this manufacturing defect																			