

Outgoing Email

from

CN=Matt
Smith/O=MaxFordham

on
20/06/2016 16:38

Create Mail Reply

File Ref 1 Main Contractor

File Ref 2

File Ref 3

To: "dhughes@rydon.co.uk" <dhughes@rydon.co.uk>

cc: "Claire Williams" (clwilliams@kctmo.org.uk) <clwilliams@kctmo.org.uk>;
"d.campbell@maxfordham.com" <d.campbell@maxfordham.com>; "Batty, Tony"
<tbatty@silcockdawson.co.uk>; "Steve Blake" <SBlake@rydon.co.uk>; "David
Bradbury" <DavidBradbury@jswright.co.uk>; "Jason North"
<jnorth@rydon.co.uk>; "MALCOLM Andrew"
<andrew.malcolm@uk.arteliagroup.com>; "Niel Reed"
<neil.reed@uk.arteliagroup.com>

Subject: Re: FW: Linking Environmental AOV's to smoke extract system @ Grenfell
Tower

Associated Documents

created by: **Matt Smith** on 20-Jun-16

Afternoon Dave

Could you explain the reasoning for this proposed change? My understanding from reviewing the design and witnessing the operation of the system is that these louvres are not required for the correct operation of the smoke extract system. In addition to this, if they were to be installed then the lobby area of Grenfell Tower would be susceptible to low temperatures and drafts during the cooler months, undermining the valuable work undertaken so far in improving the air tightness and insulation of the building.

Perhaps PSB could prepare a more detailed response for Building Control in order to avoid having to install these louvres?

Thanks to Tony for highlighting this issue.

Kind regards,

Matt

MAX FORDHAM / 50

42-43 Gloucester Crescent

London

NW1 7PE

T

maxfordham.com

@maxfordhamLLP

Max Fordham LLP is a Limited Liability Partnership. Registered in England and Wales Number OC300026

MAX00006346/1
MAX00006346/1

"Batty, Tony"

Matt/Duncan, Before these works are auctioned,...

15/06/2016 15:41:41

From: "Batty, Tony" <tbatty@silcockdawson.co.uk>
To: "M.Smith@maxfordham.com" <M.Smith@maxfordham.com>
Cc: "d.campbell@maxfordham.com" <d.campbell@maxfordham.com>, "Claire Williams" <clwilliams@kctmo.org.uk> <clwilliams@kctmo.org.uk>
Date: 15/06/2016 15:41
Subject: FW: Linking Environmental AOV's to smoke extract system @ Grenfell Tower

Matt/Duncan,

Before these works are auctioned, are they required??? YOUR EARLY REPLY WOULD BE APPRECIATED

Regards, TonyB.

From: David Hughes [mailto:dhughes@rydon.co.uk]
Sent: 15 June 2016 15:42
To: 'Claire Williams' (clwilliams@kctmo.org.uk); Batty,Tony
Cc: Steve Blake; Jason North
Subject: FW: Linking Environmental AOV's to smoke extract system @ Grenfell Tower

Hi Claire & Tony

Following our discussion on site, below is the e-mail from JSW/PSB specifying the necessary free air requirement – 1m2

As agreed, we will remove the two central windows above the main entrance door and change them to permanently open louvres.

Any questions, please give me a call

Kind regards

Dave

David Hughes
Site Manager
T
M

From: David Bradbury [<mailto:DavidBradbury@jswright.co.uk>]
Sent: 09 June 2016 08:46
To: Steve Blake; David Hughes; Alan Whyte
Cc: Jonathon Earl; David Cook; JSW > John Heggs
Subject: RE: Linking Environmental AOV's to smoke extract system @ Grenfell Tower

Steve, Following our telephone conversation:

We have received a response from PSB and I've just spoken to them for further clarification. PSB have stated their commissioning results show that the system is achieving the design requirement without an AOV on the ground floor, therefore they are satisfied with the set up. however from speaking with Paul at building control I understand their concern is that leakage around doors and opening doors may not always satisfy the make-up air, therefore PSB have suggested that an opening / free area of 1m^2 is allowed for in the ground floor entrance lobby area to atmosphere.

Kind regards,

Dave Bradbury
Design Manager
Head Office



From: Steve Blake [<mailto:SBlake@rydon.co.uk>]

Sent: 09 June 2016 07:37

To: David Bradbury <DavidBradbury@jswright.co.uk>; David Hughes <dhughes@rydon.co.uk>; Alan Whyte <AlanWhyte@jswright.co.uk>

Cc: Jonathon Earl <JonathonEarl@jswright.co.uk>; David Cook <davidcook@jswright.co.uk>; John Heggs <JohnHeggs@jswright.co.uk>

Subject: Re: Linking Environmental AOV's to smoke extract system @ Grenfell Tower

Dave,

Where are we with this?

Jon,

Today Steve Butler will be contacting you to get a list of those components that need regular Maintenance by statute and guarantee.

Please accommodate as we can then get the job signed off.

Call if unsure.

Thanks

Stephen Blake

Director

Rydon Maintenance Ltd.

D
M

----- Original message -----

From: Steve Blake <SBlake@rydon.co.uk>

Date: 08/06/2016 07:16 (GMT+00:00)

To: David Bradbury <DavidBradbury@jswright.co.uk>, David Hughes <dhughes@rydon.co.uk>, Alan Whyte <AlanWhyte@jswright.co.uk>

Cc: Jonathon Earl <JonathonEarl@jswright.co.uk>, David Cook <davidcook@jswright.co.uk>, "JSW > John Heggs" <JohnHeggs@jswright.co.uk>

Subject: Re: Linking Environmental AOV's to smoke extract system @ Grenfell Tower
Dave,

What is the timescale here to get resolution and are you saying alterations are required? If you are relying on PSB then that can only be a concern.

In addition,

I have not seen any communication between yourselves and Max Fordham with respect to the interrogation of Wilson Energy 's hot water delivery records or the commissioning carried out last Thursday.

Meeting Jon at 8.30 and Client team later today.

Stephen Blake

Director

Rydon Maintenance Ltd.

D
M

----- Original message -----

From: David Bradbury <DavidBradbury@jswright.co.uk>

Date: 07/06/2016 16:04 (GMT+00:00)

To: David Hughes <dhughes@rydon.co.uk>, Alan Whyte <AlanWhyte@jswright.co.uk>

Cc: Jonathon Earl <JonathonEarl@jswright.co.uk>, David Cook <davidcook@jswright.co.uk>, Steve Blake <SBlake@rydon.co.uk>, "JSW > John Heggs" <JohnHeggs@jswright.co.uk>, Steve Blake <SBlake@rydon.co.uk>

Subject: RE: Linking Environmental AOV's to smoke extract system @ Grenfell Tower
Hi Dave,

Following our conversation, I've spoken to Paul Hanson about item 5 regarding make up air to the bottom floors, as there appears to be a slight difference of opinion from our specialist. I've asked PSB to comment on the attached and to confirm the volume of make-up air as requested by building control.

Also from our discussion and from talks with Alan, the suggested solution would be to either hold open one of the high level windows (pending confirmation of volume from PSB) or high level louvre linked to a grille in the ceiling. This will only be required to the main entrance lobby.

I'll come back to you with confirmation of volume / size of vent required once PSB get back to us.

Kind regards,

Dave Bradbury

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This e-mail has been scanned for all viruses by Claranet. The service is powered by MessageLabs. For more information on a proactive anti-virus service working around the clock, around the globe, visit: <http://www.claranet.co.uk>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email was scanned by Postini, the leading provider in Managed Email Security. If you have received this email and/or have any questions you can contact the Grove Group on +44 [REDACTED] or visit our website www.groveis.com[attachment "image001.jpg" deleted by Matt Smith/MaxFordham]