

# Appendix 5.

## General main safety stats

### Risers and Flats

- (a) 1 Installation was identified as having a ruptured gas riser.
- (b) 26 Installations were found with emergency control valve (ECV) in the ON or partially ON position with an open end of above installations in (b) identified with melted or had holed regulators
- (c) 18 Others found with ECV, meter or regulator removed
- (d) 8

Q (a)

Floor	Flat
14	5
T	1

Q (b)

Floor	Flat
5	6
7	6
8	5
8	6
10	4
12	2
13	2
14	3
14	6
16	1
16	3
16	5
16	6
17	6
18	3
18	4
19	1
19	4
19	5
20	4
20	5
20	6
22	5
22	6
23	4
23	6
T	26

Q (c)

Floor	Flat
5	6
7	6
8	6
14	3
14	6
16	1
16	3
16	5
16	6
17	6
18	3
18	4
19	1
20	5
20	6
22	6
23	4
23	6
T	18

Q (d)

Floor	Flat
8	5
10	4
12	2
13	2
19	4
19	5
20	4
22	5
T	8