

Service Visit Report



Job Number	PD807175	Customer Order Number					
Unit Number	PD807175	Parts Used					
Site Address	Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference	H091						
Date of Service Visit Report	05/01/2017						
Visit Type	S						
Works Completed		Observations					
<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top Shaft Equipment</p>		<p>full shaft cleandown, deep clean in motor room and on car top strongly required when builders have finished works. door operator needs setting up once builders have finished works. hanger rollers in car at ground and 2nd specifically need to be changed car hanger rollers changed fan wiring should be separate from car lighting pit ladders required for both lifts and barriers lg1 nov visit dec visit</p>					
		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:30%;">Total Time on Site</td> <td>2.00</td> </tr> <tr> <td>Total Travel to Site</td> <td>0.00</td> </tr> </table>		Total Time on Site	2.00	Total Travel to Site	0.00
Total Time on Site	2.00						
Total Travel to Site	0.00						
		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:30%;">Customer Name</td> <td rowspan="2" style="text-align: center; vertical-align: middle;">Customer Unavailable For Signature</td> </tr> <tr> <td>Signed Date & Time</td> </tr> </table>		Customer Name	Customer Unavailable For Signature	Signed Date & Time	
Customer Name	Customer Unavailable For Signature						
Signed Date & Time							
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:30%;">Signature Declined</td> <td>N</td> </tr> <tr> <td>Decline Reason</td> <td></td> </tr> </table>		Signature Declined	N	Decline Reason			
Signature Declined	N						
Decline Reason							
Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
D Smalley (55029)	05/01/17	10:00	12:00	2.00	0.00	N/A	

Service Visit Report



PDERS

EXPRESS
L.A.T.

Job Number	PD807175	Customer Order Number				
Unit Number	PD807175	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	18/01/2017					
Visit Type	M2					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top Shaft Equipment</p>					
Observations	<p>full shaft cleandown, deep clean in motor room and on car top strongly required when builders have finished works. door operator needs setting up once builders have finished works. hanger rollers in car at ground and 2nd specifically need to be changed car hanger rollers changed fan wiring should be separate from car lighting pit ladders required for both lifts and barriers lg1 nov visit dec visit</p>					
Total Time on Site	1.45					
Total Travel to Site	0.15					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Signature Declined	N					
Decline Reason						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	18/01/17	11:15	13:00	1.45	0.15	N/A

Service Visit Report



Job Number	PD807175	Customer Order Number				
Unit Number	PD807175	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	20/02/2017					
Visit Type	S					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top Shaft Equipment</p>					
Observations	<p>full shaft cleandown, deep clean in motor room and on car top strongly required when builders have finished works. door operator needs setting up once builders have finished works. hanger rollers in car at ground and 2nd specifically need to be changed car hanger rollers changed fan wiring should be separate from car lighting pit ladders required for both lifts and barriers lg1 visit</p>					
Total Time on Site	2.00					
Total Travel to Site	0.00					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Signature Declined	N					
Decline Reason						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	30/11/16	14:00	16:00	2.00	0.00	N/A

Service Visit Report



Job Number	PD807175
Unit Number	PD807175
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H091
Date of Service Visit Report	08/03/2017
Visit Type	M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

- Car Enclosure and COP
- Emergency Alarm System
- Indicators and Call Buttons
- Floor Levels and Selector
- Machine and Brake
- Operation of Car Doors
- Car Top
- Shaft Equipment
- Pit and Underside of Car

Signature Declined	N
Decline Reason	

Customer Order Number	
Parts Used	

Observations

full shaft cleandown, deep clean in motor room and on car top strongly required when builders have finished works. door operator needs setting up once builders have finished works. hanger rollers in car at ground and 2nd specifically need to be changed car hanger rollers changed fan wiring should be separate from car lighting pit ladders required for both lifts and barriers lg1 visit

Total Time on Site	2.00
--------------------	------

Total Travel to Site	0.00
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	08/03/17	10:00	12:00	2.00	0.00	N/A

Service Visit Report



Job Number	PD807175	Customer Order Number				
Unit Number	PD807175	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	20/03/2017					
Visit Type	M2					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car</p>					
Observations						
Total Time on Site	1.30					
Total Travel to Site	0.00					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Signature Declined	N					
Decline Reason						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
T Parker (58461)	11/02/17	09:30	11:00	1.30	0.00	N/A

Service Visit Report



Job Number	PD807175	Customer Order Number				
Unit Number	PD807175	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	27/04/2017					
Visit Type	M2					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <ul style="list-style-type: none"> Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car 					
Observations	<p>door operator needs setting up once builders have finished works. changed fan wiring should be separate from car lighting pit ladders required for both lifts and barriers lg1 visit</p>					
Total Time on Site	2.00					
Total Travel to Site	0.00					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Signature Declined	N					
Decline Reason						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	12/04/17	12:00	14:00	2.00	0.00	N/A

EXPRESS

Lifts Alliance
Group

Service Visit Report



PDERS

EXPRESS
LIFTS ALLIANCE

Job Number	PD807175	Customer Order Number				
Unit Number	PD807175	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	31/05/2017					
Visit Type	S					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car</p>					
Observations	<p>. changed fan wiring should be separate from car lighting pit ladders required for both lifts and barriers</p>					
Total Time on Site	2.00					
Total Travel to Site	0.00					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Signature Declined	N					
Decline Reason						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	09/05/17	15:00	17:00	2.00	0.00	N/A

