

Service Visit Report



Job Number	PD807174	Customer Order Number	
Unit Number	PD807174	Parts Used	
Site Address	Grenfell Tower Grenfell Road London W11 1TG		
Unit Reference	H090		
Date of Service Visit Report	05/01/2017		
Visit Type	S		

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

- Car Enclosure and COP
- Emergency Alarm System
- Indicators and Call Buttons
- Floor Levels and Selector
- Machine and Brake
- Operation of Car Doors
- Car Top
- Shaft Equipment

Observations

full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2 unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

Signature Declined	N
Decline Reason	

Total Time on Site	2.00
Total Travel to Site	0.00
Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
D Smalley (55029)	05/01/17	08:00	10:00	2.00	0.00		N/A

Service Visit Report



Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	18/01/2017
Visit Type	M2

Customer Order Number	
Parts Used	

<p>Works Completed</p> <p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top</p>
--

<p>Observations</p> <p>full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit</p>

Signature Declined	N
Decline Reason	

Total Time on Site	1.45
Total Travel to Site	0.15
Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Attending Engineer(s)							Customer Signoffs
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site		
D Smalley (55029)	18/01/17	08:15	10:00	1.45	0.15		N/A

Service Visit Report



Job Number	PD807174	Customer Order Number				
Unit Number	PD807174	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H090					
Date of Service Visit Report	20/02/2017					
Visit Type	S					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top Shaft Equipment</p>					
Signature Declined	N					
Decline Reason						
Observations	<p>full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit</p>					
Total Time on Site	1.45					
Total Travel to Site	0.15					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	30/11/16	12:15	14:00	1.45	0.15	N/A

Service Visit Report



Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	08/03/2017
Visit Type	M2

Customer Order Number	
Parts Used	

Works Completed As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable : Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top Shaft Equipment Pit and Underside of Car
--

Observations full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit
--

Total Time on Site	2.00
--------------------	------

Total Travel to Site	0.00
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	08/03/17	08:00	10:00	2.00	0.00	N/A

Service Visit Report



Job Number	PD807174	Customer Order Number				
Unit Number	PD807174	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H090					
Date of Service Visit Report	20/03/2017					
Visit Type	M2					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <ul style="list-style-type: none"> Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car 					
Signature Declined	N					
Decline Reason						
Observations						
Total Time on Site	1.30					
Total Travel to Site	0.00					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
T Parker (58461)	11/02/17	08:00	09:30	1.30	0.00	N/A

Service Visit Report



Job Number	PD807174	Customer Order Number				
Unit Number	PD807174	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H090					
Date of Service Visit Report	27/04/2017					
Visit Type	M2					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car</p>					
Signature Declined	N					
Decline Reason						
Observations	<p>seals leaking slightly on gear. door operator needs setting up once builders have completed works. contractors have glued display plate to wall and will create damage to wall. customer action recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit. unit requires pit ladder</p>					
Total Time on Site	2.00					
Total Travel to Site	0.00					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	12/04/17	10:00	12:00	2.00	0.00	N/A

Service Visit Report



Job Number	PD807174	Customer Order Number				
Unit Number	PD807174	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H090					
Date of Service Visit Report	31/05/2017					
Visit Type	S					
Works Completed	<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <ul style="list-style-type: none"> Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car 					
Observations	<p>seals leaking slightly on gear. door operator needs setting up once builders have completed works. contractors have glued display plate to wall and will create damage to wall. customer action recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit. unit requires pit ladder</p>					
Total Time on Site	2.00					
Total Travel to Site	0.00					
Customer Name	Customer Unavailable For Signature					
Signed Date & Time						
Signature Declined	N					
Decline Reason						
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	09/05/17	13:00	15:00	2.00	0.00	N/A