

Richard Yeadon

From: Richard Yeadon
Sent: 31 July 2015 13:53
To: Hugh Mahoney (hm@psbuk.com)
Cc: David Harrison
Subject: RE: Grenfell Tower - AOV

Tracking:	Recipient	Delivery
	Hugh Mahoney (hm@psbuk.com)	
	David Harrison	Delivered: 31/07/2015 13:53
	Hugh Mahoney	Delivered: 31/07/2015 13:53

Hugh,

Do you know if the revised drawing (E75015-800 Rev D) and cause and effect was issued to J S Wrights for Grenfell Tower?

Best Regards

Richard Yeadon

From: Richard Midgley
Sent: 16 July 2015 11:12
To: Hugh Mahoney <hm@psbuk.com>; Richard Yeadon <ry@psbuk.com>; Tim Haigh <Tim.Haigh@psbuk.com>; Bob Hill <Bob.Hill@psbuk.com>; Michal Glowacki <michal.glowacki@psbuk.com>
Subject: RE: Grenfell Tower - AOV

Hi Hugh

Just to confirm with everyone after our telephone conversation.

The ground floor requires 2 dampers, 1 fireman's override switch, 1 smoke detector and 1 pressure switch.

I have Michal updating the 800 drawing to show these items and where they are required to be wired back to. We will also update the cause and effect.

They will be wired back to the master control panel as this has the capacity to take these extra's at no extra cost.

The only extra cost to ourselves will be the pressure switch and fireman's override £163.00.

From: Hugh Mahoney
Sent: 16 July 2015 10:12
To: Richard Yeadon; Richard Midgley; Tim Haigh; Bob Hill
Subject: RE: Grenfell Tower - AOV

Hi All,

Can you please note that it has just been brought to my attention that I have dropped one.

There is a vent on the ground floor which I have missed.

Can you amend the drawing and order the additional control components for this level.

Plus amend the cause and effect

I have advised the customer that as a gesture of good faith that we will absorb the cost of these additional items as the error was mine.

Sorry for the additional work this puts the team to, I owe you all a pint.