

Message

From: David Hughes [dhughes@rydon.co.uk]
Sent: 12/05/2016 14:56:20
To: Hoban, John: CP-Plan [john.hoban@rbkc.gov.uk]
CC: Steve Blake [sblake@rydon.co.uk]; Keith Miller [kmiller@rydon.co.uk]; Jason North [jnorth@rydon.co.uk]; Jack Sullivan [jsullivan@rydon.co.uk]
Subject: Building Control - Findings from todays visit to Grenfell Tower.

Hi John

Thanks for visiting today.

To confirm the works that still need to be done:

3rd floor - OK

Boxing Club -Smoke seals to front door and gym door
 -'Fire Door – Keep Shut' signs to all fire doors
 -Coat Hooks to DAB toilet/shower room
 -Grab rails not at correct height – 680mm above FFL to top of rail

1st Floor -Smoke seals to front doors and office door
 -Change lobby door to FD 30 (site office)

Community Room -Grab rails not at correct height
 -Coat hooks to DAB toilet
 -Change access step to ramp

Entrance Lobby - Fit coloured rubber protection to low head height from 1st floor steps

Ground Floor - Fenestration required to all clear full height glazing panels – Nursery, Community Room & Entrance Lobby

Nursery -Coat Hooks to DAB toilet/shower room
 -Grab rails not at correct height – 680mm above FFL to top of rail
NOTE – you'll check lock specification and slope to fire exit door

As requested, I'll forward the necessary certification to you ASAP.

See you at 9am on Thursday 26th May

Any questions or comments, please give me a call


Kind regards

Dave

David Hughes
Site Manager

T
M [REDACTED]
Rydon Maintenance Ltd
Marlborough House, Warrior Square, St Leonards on Sea, East Sussex, TN37 6BG.


www.rydon.co.uk



This e-mail (including any attachments) is transmitted subject to Rydon Group e-mail terms as published on its [website](#). If you have received this e-mail in error please e-mail the sender by replying to this message. Details of the Company registration numbers and registered offices to which this e-mail relates are also published on its [website](#).

Please consider the environment before printing this email.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>
