
From: Neil Crawford <Neil@studioe.co.uk>
Sent: 22 September 2014 10:03
To: Simon Lawrence
Cc: Simon O'Connor; KALC
Subject: RE: Grenfell Tower Regeneration Project Fire Strategy Drawings- Minor revisions

Hi Simon

Thanks for the heads up on the Exova position. Ahead of tomorrow's DTM (tomorrow at 9.00 [or was it 10.00?]) just want to flag up the importance of getting John Hoban and Paul Hanson round a table to agree the fire approach to eliminate package risk re fire ratings/ AOV's etc.

Regards
Neil

From: Simon Lawrence [mailto:slawrence@rydon.co.uk]
Sent: 19 September 2014 14:25
To: Neil Crawford
Cc: Simon O'Connor
Subject: RE: Grenfell Tower Regeneration Project Fire Strategy Drawings- Minor revisions

Hi Neil,

I'm just catching up on emails, particularly around design and have noticed Exova in the chain. I know that they provided information in the tender for KCTMO but I don't know if they are still working for them. I know that we haven't employed them. So if you are getting some free advice then great otherwise we will need to look at this.

Regards

Simon Lawrence, ACIOB, MInstLM
Contracts Manager

T
M

From: Neil Crawford [mailto:Neil@studioe.co.uk]
Sent: 19 September 2014 12:32
To: Terry.Ashton@Exova.com
Cc: Simon Lawrence; Simon O'Connor; 1279 Grenfell Tower
Subject: Grenfell Tower Regeneration Project Fire Strategy Drawings- Minor revisions

Terry

Please see attached revised Fire Strategy plans for Grenfell Tower Regeneration Project. These reflect some recently proposed changes concerning the re-planning of the concierge and office areas on the Ground, Mezzanine and Walkway levels. I have included the old set and the new set (labelled B) so you can compare them. The principal differences are;

- Ground Floor; Concierge meeting rooms and internal stair have gone and been replaced by a community room (for which I have assumed an occupancy of 30) with a number of support rooms.
- Mezzanine Floor; Office rooms and internal stair gone replaced by 2 bed apartment served from main core
- Walkway Level; Office room and internal stair gone replaced by 2 bed apartment served from main core. Secondary means of escape from boxing club moved to different location exiting to the North of the main core.

Can you confirm that my escape distance, wall and door ratings assumptions are correct? As the internal connecting stair in the office area has been removed I have assumed that there are no AOV requirements at ground and top of the stair as in the previous scheme. There may be some minor tweaks yet on the ground floor but wanted to establish any implications from the main changes.

Regards
Neil

Neil Crawford
Associate

For and on behalf of
STUDIO E LTD

Unit 310 Linton House, 164/180 Union Street, London, SE1 0LH
T [REDACTED] | www.studioe.co.uk



Queen's Award for Enterprise: Sustainable Development 2010
BCSE Award School Architect of the Year 2008 & 2010
BCSE Award Inspiring Design Primary School 2008 & Academy 2010
BSF Award Excellence in Student Engagement 2009
Sustainable City Award 2009



Please consider the environment before printing this email.

ELECTRONIC INFORMATION TRANSFER DISCLAIMER

This email and any files transmitted with it are sent for and on behalf of Studio E LLP and are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the sender. All attached files are copyright and may only be used for the purpose stated in the drawing status box. In the event that the files are altered in anyway, it is a condition of use that the Studio E name and logo be removed from the modified file, unless prior written agreement has been obtained. Studio E will assume no responsibility for the accuracy, adequacy, and integrity of the files, and recommends that the files be thoroughly screened for viruses prior to installation. Opinions, conclusions and other information expressed in this message are not given or endorsed by Studio E LLP unless otherwise indicated by an authorised representative independent of this message.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>
