wiessage	
From:	Neil Crawford [/O=STUDIO E/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=NEIL]
Sent:	18/09/2014 12:08:35
То:	slawrence@rydon.co.uk
CC:	1279 Grenfell Tower [1279_Grenfell_Tower@studioe.co.uk]
Subject:	Building Control
Attachments:	RBKC MOE Plan Grenfell Tower, Grenfell Road (1279_SEA_(08) 101) P2.pdf; RBKC MOE Plan Grenfell Tower, Grenfell
	Road Ground floor (1279 SEA (08) 100) P2.pdf

Simon

Maccago

Not sure if you are aware of these building control preliminary observations that were made at the end of last year (attached).

They raise a number of concerns in relation to additional doors/ specification fire ratings/ venting. They will also have ironmongery implications.

Based on our experience at KALC where the process dragged on over a long period I am keen to sit with John and Paul and go through these issues and clarify them all in order to eliminate risk.

Before doing this I think it would be good to re-appraise the Fire Access Plans with revised drawings, but to do this it would be useful to know whether there had been any further clarity on the last proposals to EMB office area?

Regards Neil

Neil Crawford Associate

For and on behalf of **STUDIO E LTD**



THE QUEEN'S AWARDS FOR ENTERPRISE: SUISTAINABLE DEVELOPMENT 2000

Queen's Award for Enterprise: Sustainable Development 2010 BCSE Award School Architect of the Year 2008 & 2010 BCSE Award Inspiring Design Primary School 2008 & Academy 2010 BSF Award Excellence in Student Engagement 2009 Sustainable City Award 2009

Unit 310 Linton House, 164/180 Union Street, London, SE1 0LH

www.studioe.co.uk



Please consider the environment before printing this email.

ELECTRONIC INFORMATION TRANSFER DISCLAIMER This email and any files transmitted with it are sent for and on behalf of Studio E LLP and are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the sender. All attached files are copyright and may only be used for the purpose stated in the drawing status box. In the event that the files are altered in anyway, it is a condition of use that the Studio E name and logo be removed from the modified file, unless prior writem agreement has been obtained. Studio E will assume no responsibility for the accuracy, adequacy, and integrity of the files, and recommends that the files be thoroughly screened for viruses prior to installation. Opinions, conclusions and other information expressed in this message are not given or endorsed by Studio E LLP unless otherwise indicated by an authorised representative independent of this message.

SEA00011707_0001

SEA00011707_0002

SEA00011707/2