
From: Neil Crawford
Sent: 18 September 2014 16:07
To: Terry.Ashton@Exova.com
Subject: FW: Grenfell Tower Cavity Fire barriers
Attachments: rainscreen-cladding_product-datasheet_aug14.pdf

Terry

Is this interpretation correct (see below)?

Regards
Neil

From: Daniel Anketell-Jones [mailto:Daniel@harleycw.co.uk]
Sent: 18 September 2014 16:03
To: Neil Crawford
Cc: slawrence@rydon.co.uk; Simon O'Connor (SOConnor@rydon.co.uk); 1279 Grenfell Tower; Kevin Lamb
Subject: RE: Grenfell Tower Cavity Fire barriers

Neil,

Thankyou for your response.

The insulation is class 0. Therefore after reading the correspondence below; I believe that the fire barrier in these locations, will not be necessary.

Can you confirm that this is acceptable?

Kind Regards

Daniel Anketell-Jones
Design Manager



T- [REDACTED]
F- [REDACTED]
W- www.harleycurtainwall.com

From: Neil Crawford [mailto:Neil@studioe.co.uk]
Sent: 18 September 2014 15:50
To: Daniel Anketell-Jones
Cc: slawrence@rydon.co.uk; Simon O'Connor (SOConnor@rydon.co.uk); 1279 Grenfell Tower; Kevin Lamb
Subject: FW: Grenfell Tower Cavity Fire barriers

Daniel

Please see correspondence relating to RFI 001/ Cavity Barrier requirement below.

Regards
Neil

From: Terry Ashton [<mailto:Terry.Ashton@Exova.com>]
Sent: 18 September 2014 15:32
To: Neil Crawford
Subject: RE: Grenfell Tower Cavity Fire barriers

Neil

If the insulation in the cavities behind the rainscreen cladding is combustible you will need to provide cavity barrier as shown on your drawing (number 1279 (06) 120) in order to prevent fire from spreading from one flat to the one above even if there isn't a continuous cavity from the top to the bottom of the building.

Kind regards

Terry

Terry Ashton: *Associate, Fire Engineering (Europe)*
Exova Warringtonfire
T: [REDACTED] M: [REDACTED]
Exova



From: Neil Crawford [<mailto:Neil@studioe.co.uk>]
Sent: 18 September 2014 12:18
To: Terry Ashton
Cc: 1279 Grenfell Tower
Subject: RE: Grenfell Tower Cavity Fire barriers

Hi Terry

Please see attached our sections and the initial drawings set we have had from Harleys. The initial drawings from Harleys are fairly limited but they attempt to establish the basic approach.

Regards
Neil

From: Terry Ashton [<mailto:Terry.Ashton@Exova.com>]
Sent: 18 September 2014 11:33
To: Neil Crawford
Subject: RE: Grenfell Tower Cavity Fire barriers

Neil

I've never seen details of what you're doing to the external walls. Do you have any cross sections/elevations?

Kind regards

Terry

Terry Ashton: *Associate, Fire Engineering (Europe)*
Exova Warringtonfire
T: [REDACTED] M: [REDACTED]

Exova



From: Neil Crawford [<mailto:Neil@studioe.co.uk>]

Sent: 18 September 2014 11:08

To: Terry Ashton

Cc: slawrence@rydon.co.uk; Simon O'Connor (SOConnor@rydon.co.uk); 1279 Grenfell Tower

Subject: FW: Grenfell Tower Cavity Fire barriers

Hi Terry

I am working on the Grenfell Tower regeneration project from the Studio E end. The following RFI has come in relating to horizontal fire breaks within the cladding areas.

Can you comment on the RFI attached and whether you believe this interpretation in relation to stack effect is correct?

Regards

Neil

From: Daniel Anketell-Jones [<mailto:Daniel@harleycw.co.uk>]

Sent: 17 September 2014 14:23

To: Simon Lawrence; Simon O'Connor; Neil Crawford; Bruce Sounes

Cc: Kevin Lamb

Subject: Grenfell Tower Cavity Fire barriers

Simon,

Please find attached RFI001 which relates to the requirement of firebreaks. This may be something that has already been decided, or may need confirmation from the local fire officer, as the opinion tends to vary.

Kind Regards

Daniel Anketell-Jones

Design Manager



T- [REDACTED]
F- [REDACTED]

W- www.harleycurtainwall.com

Head Office

Harley House, Brooklands Park
Farningham Road, Crowborough
East Sussex, TN6 2JD

Email Disclaimer:

This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.

This transmission may contain information that is privileged, confidential and /or exempt from disclosure under applicable law. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution or use of the information contained herein is **STRICTLY PROHIBITED**. If you receive this transmission in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Unless stated otherwise, any test results included or attached to this email are provisional, and may be subject to revision at a later stage.

This email is sent on behalf of Exova Group pic or the relevant subsidiary with which you are dealing. Exova Group pic is a company incorporated in England and Wales with registered number 08907086. Its registered office is at 6 Coronet Way, Centenary Park, Eccles, Salford M50 1RE.

Exova is the trading name of Exova Group pic and its subsidiaries.

Exova Warringtonfire Aus Pty Ltd is registered in Australia with its registered office at Unit 2, 409-411 Hammond Road, Dandenong, VIC 3175, Australia, ABN 81 050 241 524.

Please consider the environment before printing this e-mail and any associated attachments.

This transmission may contain information that is privileged, confidential and /or exempt from disclosure under applicable law. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution or use of the information contained herein is **STRICTLY PROHIBITED**. If you receive this transmission in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Unless stated otherwise, any test results included or attached to this email are provisional, and may be subject to revision at a later stage.

This email is sent on behalf of Exova Group pic or the relevant subsidiary with which you are dealing. Exova Group pic is a company incorporated in England and Wales with registered number 08907086. Its registered office is at 6 Coronet Way, Centenary Park, Eccles, Salford M50 1RE.

Exova is the trading name of Exova Group pic and its subsidiaries.

Exova Warringtonfire Aus Pty Ltd is registered in Australia with its registered office at Unit 2, 409-411 Hammond Road, Dandenong, VIC 3175, Australia, ABN 81 050 241 524.

Please consider the environment before printing this e-mail and any associated attachments.
