
From: Bruce Sounes
Sent: 22 September 2014 22:55
To: 'Kevin Lamb'; 'slawrence@rydon.co.uk'
Cc: 'Daniel Anketell-Jones'; Neil Crawford
Subject: RE: Grenfell Tower

Categories: 1279 Grenfell

Dear all,

I will discuss with Neil in the morning but briefly:

300/01 & 301/01 & 302/01 Increased cladding depths and encroachment on glazed area to retain frames has generated a very different looking building to that shown to the Planners. Deeper reveals, smaller windows etc.
200 – Is there an opportunity to put the trickle vent in the frame rather than the sash? Unfortunate.
200 – Opportunity to reduce height of louver for kitchen extract?
305/01 – Infill angles do not align with back face of horizontal joint above/below. Alternative option?
606/01 – Horiz joint width on pilaster corner.

Regards

Bruce Sounes

For and on behalf of

STUDIO E ARCHITECTS LTD

310 Linton House, 164/180 Union Street, London SE1 0LH
T [REDACTED] | M [REDACTED] | www.studioe.co.uk

From: Kevin Lamb [<mailto:KevinLamb@harleycw.co.uk>]
Sent: 22 September 2014 16:08
To: slawrence@rydon.co.uk
Cc: Daniel Anketell-Jones; Neil Crawford; Bruce Sounes
Subject: Grenfell Tower

Simon,

Please find attached drawings as raised in issue for final approval, based upon the Architects comments and discussions at our last meeting.

We shall shortly issue further details, for consideration.

Regards

Kevin Lamb
Project Designer



T- [Redacted]
F- [Redacted]
W- www.harleycurtainwall.com

Head Office
Harley House, Brooklands Park
Farningham Road, Crowborough
East Sussex, TN6 2JD

Email Disclaimer:
This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.

Regards
Kevin Lamb

If you have any queries regarding this email, please do not hesitate to contact us:

Bespoke Design
[Redacted]
Tel [Redacted]