From: Neil Crawford

Sent: 12 February 2015 17:58

To:Simon LawrenceCc:Simon O'Connor

Subject: RE: Grenfell Midle bay windows east and west facades

Attachments: C1059-200 additional comments.pdf; 1279 East West Elevation Centre Window

Study.pdf; IMG_2356.JPG

Simon

Please see attached. Firstly Harley's marked up sketch and then my plan cartoon showing Harleys proposed window in red and with the symmetry restored (blue). Because of the way the way the window frames come together (photograph of mock up for reference) the space between the two opening frames is only about 10mm. This is not a problem when the wall is cut away as a hatch but would not work if a tenant wants to take the wall right up to the frame....

Regards Neil

From: Simon Lawrence [mailto:slawrence@rydon.co.uk]

Sent: 12 February 2015 12:14

To: Neil Crawford **Cc:** Simon O'Connor

Subject: FW: Grenfell Midle bay windows east and west facades

Importance: High

Neil,

Let's review the window tomorrow once you are back in office. It doesn't look like it is too late or costly in the scheme of life to change. We also need to review the kitchen/lounge partition location behind the window to ensure this works. I know we've discussed this previously but it still concerns me that we may end up installing a window which can't open because the wall obstructs it. Harley haven't surveyed or looked at this at all.

Regards

Simon Lawrence, ACIOB, MInstLM

Contract Manager

T A

From: Simon Lawrence **Sent:** 12 February 2015 12:10 **To:** 'Neil Crawford'; Kevin Lamb

Cc: Mark Stapley; Rob Maxwel; Daniel Anketell-Jones; 'Ben Bailey'; Simon O'Connor; Ray Bailey

Subject: RE: Grenfell Midle bay windows east and west facades

Importance: High

Dear All,

Following my conversation with several of yourselves today. The following is a list of actions that we need to do in order to finalise the window design issues.

- Mark Will contact CEP to put all Type 10 (east & west middle bay windows) on hold and confirm what Type 10 windows have actually be fabricated.
- Neil Will review the Type 10 window layout and confirm the requirements by close of play tomorrow.
- Kevin Make design alterations if required to Type 10 and corresponding lower floor bays following response from Neil as above.
- Ben Find out the window restrictor options for the smaller side hung windows so they are in line with clients requirements (100mm restriction) and report back

Any queries please call.

Regards

Simon Lawrence, ACIOB, MInstLM

Contract Manager

M

From: Neil Crawford [mailto:Neil@studioe.co.uk]

Sent: 11 February 2015 18:04 **To:** Kevin Lamb; Simon Lawrence

Cc: Alan Grint; Mark Stapley; Rob Maxwel; Daniel Anketell-Jones **Subject:** RE: Grenfell Midle bay windows east and west facades

Importance: High

All

I do think this issue may have planning implications ie. the central widow should be symmetrical- with the trickle vent requirement gone there is no reason not to keep the two side windows the same size can this be reviewed as a matter of urgency?

Regards

Neil

From: Neil Crawford

Sent: 11 February 2015 13:20

To: 'Kevin Lamb'; 'slawrence@rydon.co.uk'

Cc: 'agrint@rydon.co.uk'; 'Mark Stapley'; 'Rob Maxwel'; 'Daniel Anketell-Jones'

Subject: RE: Grenfell Midle bay windows east and west facades

Hi Kevin

As per telephone conversation, I think we need to make this move as indicated. With the trickle vents no longer required the symmetry to the middle window is not in line with the planning drawings and it is better to return to this position. (Opening in wall at kitchen so alignment with wall is less critical behind).

Regards

Neil

From: Neil Crawford

Sent: 26 January 2015 11:29

To: 'Kevin Lamb'; slawrence@rydon.co.uk

Cc: agrint@rydon.co.uk; Mark Stapley; Rob Maxwel; Daniel Anketell-Jones

Subject: RE: Grenfell

Hi Kevin

Please see attached comments

Regards Neil

From: Kevin Lamb [mailto:KevinLamb@harleycw.co.uk]

Sent: 23 January 2015 17:19 **To:** slawrence@rydon.co.uk

Cc: Neil Crawford; Bruce Sounes; agrint@rydon.co.uk; Mark Stapley; Rob Maxwel; Daniel Anketell-Jones

Subject: Grenfell

Simon,

Please find attached specification on the upper 20 floors for clarity / approval.

We shall add to this as we reissue the lower elements.

Regards

Kevin Lamb Project Designer



T-F-

W- www.harleycurtainwall.com

Head Office

Harley House, Brooklands Park Farningham Road, Crowborough East Sussex, TN6 2JD

Email Disclaimer:

This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.

This email has been scanned by the Symantec Email Security cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com