

Message

**From:** Suleyman Ekingen [Suleyman.Ekingen@curtins.com]  
**Sent:** 20/02/2015 19:10:20  
**To:** Jason North (jnorth@rydon.co.uk) [jnorth@rydon.co.uk]  
**CC:** 'soconnor@rydon.co.uk' [soconnor@rydon.co.uk]; Simon Lawrence (slawrence@rydon.co.uk) [slawrence@rydon.co.uk]; Stefano Strazzullo [Stefano.Strazzullo@curtins.com]; Niall McDonagh [Niall.McDonagh@curtins.com]; Edgar Ferenzena [Edgar.Ferenzena@curtins.com]; Neil Crawford [Neil@studioe.co.uk]  
**Subject:** LO1212 - Grenfell Tower: Remedial work at mezzanine floor  
**Attachments:** SK\_20-22 Proposed remedial works for mezzanine floor beams.pdf

Hi Jason,

Further to our discussion at my site visit on Wednesday 18<sup>th</sup> of February, we have reviewed and we confirm that we have to provide 2 no. of PFC acting as lintel over the door to support the mezzanine floor beam. Please find attached sketches no. SK/21&22.

We have also reviewed the remedial work for connection as there is no rc wall over the floor level, please find attached SK/22.

We have asked couple of times earlier and please confirm if our calculations have been forwarded on to Building Control for their consideration and approval.

Should you have any queries please do not hesitate to call.

Regards,

Curtins are attending MIPIM 2015  
**mipim** 25  
The world's property market  
[click here to view our attendees](#)

Suleyman Ekingen  
Project Engineer  
T. [REDACTED]  
[suleyman.ekingeng@curtins.com](mailto:suleyman.ekingeng@curtins.com)

Units 5/6  
40 Compton Street  
London EC1V 0BD



STRUCTURES • TRANSPORT PLANNING • ENVIRONMENTAL • CIVILS & INFRASTRUCTURE • EXPERT ADVICE • SUSTAINABILITY • STAKEHOLDER ENGAGEMENT  
Birmingham • Bristol • Cardiff • Douglas • Edinburgh • Kendal • Leeds • Liverpool • London • Manchester • Nottingham

Follow us on Twitter

[www.curtins.com](http://www.curtins.com)

This e-mail is confidential and intended solely for the addressee. The dissemination or copying of its contents by any other person is prohibited.  
If you receive this e-mail in error, please notify us by telephone and delete it from your computer.  
Curtins nor the sender accepts any responsibility for viruses and it is your responsibility to scan any attachments.  
No contracts may be concluded on behalf of Curtins by means of e-mail communications.

SEA00012779\_0001

SEA00012779/1