

Message

From: Janice Wray [jwray@kctmo.org.uk]
Sent: 06/10/2014 14:03:58
To: Claire Williams [clwilliams@kctmo.org.uk]; Claire Williams ["/O=KC TMO/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Clwilliams"]
Subject: RE: Grenfell smoke vents
Attachments: image001.jpg

Hi Claire

Did they advise of any steps they can take to even partially reinstate the ventilation /extraction system in the short term before it is refurbished?

Please advise

Thanks

Janice

Janice Wray
TMO Health, Safety & Facilities Manager
t: [REDACTED]
w: www.kctmo.org.uk
a: : The Network Hub, 300 Kensal Road, W10 5BE
P Before printing, please think about the environment

From: Claire Williams
Sent: 06 October 2014 12:46
To: Janice Wray
Cc: Alex Bosman
Subject: Grenfell smoke vents

Janice

I spoke to Rydon.

They were aware of our discussion with the fire brigade, ie the smoke vent system is not working while it is being worked on – and that by Christmas they hope to have the smoke vent system in some sort of order. However the new extractor fans in the roof plant room will probably not be fitted as it is likely they will still be awaiting Building Regs approval.

They have no programme for these works yet, but have a design team meeting tomorrow at which they hope to progress this further. I asked for a programme of the above works, but that is not yet in place.

So this is an interim update, until we have further firm information.

Claire Williams
Project Manager

t: [REDACTED]
m: [REDACTED]

a: The Network Hub, 292a Kensal Road, London, W10 5BE

P Before printing, please think about the environment