

Message

From: Andy Webster [andy.webster@masterdor.co.uk]
Sent: 26/07/2011 09:12:41
To: Abigail Acosta [aacosta@kctmo.org.uk]
CC: 'Natasha Brown' [natasha.brown@masterdor.co.uk]; 'Graham Pollard' [graham.pollard@masterdor.co.uk]
Subject: RE: New Doors at Grenfell Tower

Abi

The factory fitted the screws recommended by the manufacturers but when in situ it has been highlighted these were not sufficient. This in mind I spoke to the factory directly and they increased the size of the fixing.

The original fixings are not guaranteed to fail, but the remedial works being undertaken are a precautionary measure.

Thanks

Andy

From: Abigail Acosta [mailto:aacosta@kctmo.org.uk]
Sent: 26 July 2011 09:51
To: 'Andy Webster'
Cc: 'Natasha Brown'; 'Graham Pollard'
Subject: RE: New Doors at Grenfell Tower

Andy hi

Thanks for your response, could you confirm what the actual problem was so we can prevent for future installations

Thanks

Abigail Acosta
Project Manager of Assets, Investment & Engineering



✉: aacosta@kctmo.org.uk 🌐 www.kctmo.org.uk

✉: The Network Hub, Units 102-108 , 292A Kensal Road, London W10 5BE

🌱 Before printing, please think about the environment

From: Andy Webster [mailto:andy.webster@masterdor.co.uk]
Sent: 26 July 2011 09:49
To: Abigail Acosta
Cc: 'Natasha Brown'; 'Graham Pollard'
Subject: RE: New Doors at Grenfell Tower

Abi

We are aware there was a problem and we started last Thursday going through the block changing the fixings if necessary. We will inform you when we have completed the exercise on both blocks.

Thanks

Andy

From: Abigail Acosta [mailto:aacosta@kctmo.org.uk]
Sent: 26 July 2011 08:49
To: 'Andy Webster'
Subject: FW: New Doors at Grenfell Tower

Andy hi

Could you look into the below as a matter of urgency.

Kind regards,


Abigail Acosta
Project Manager of Assets, Investment & Engineering
 



✉: aacosta@kctmo.org.uk www.kctmo.org.uk

✉: The Network Hub, Units 102-108 , 292A Kensal Road, London W10 5BE

 Before printing, please think about the environment

From: 
Sent: 25 July 2011 19:23

To: Abigail Acosta
Subject: Re: New Doors at Grenfell Tower

As far as I can tell and remember from the King Charles House door the screws securing/holding the closer into the door are very short.

Carl

-----Original Message-----

From: Abigail Acosta <aacosta@kctmo.org.uk>

To: [REDACTED]

Sent: Mon, 25 Jul 2011 12:28

Subject: RE: New Doors at Grenfell Tower

Carl hi

No I am not, thanks for bringing to my attention

I will raise as concern at our next site meeting, I will send you invite, if you wish to attend.

Do you know why this may be happening (manufacturing issue, or plan incompetence by the installer . . . ?)

Thanks

Abigail Acosta
Project Manager of Assets, Investment & Engineering



✉: aacosta@kctmo.org.uk www.kctmo.org.uk

✉: The Network Hub, Units 102-108 , 292A Kensal Road, London W10 5BE

Before printing, please think about the environment

From: [REDACTED]
Sent: 21 July 2011 10:48
To: Abigail Acosta
Subject: New Doors at Grenfell Tower

Abi Good morning

On Tuesday I was at Lancaster West and was informed that the self closing device on 3 of the new flat entrance doors have come away from the door, this is the same problem as in King Charles House. Are you aware of this reoccurring fault ?

Carl Stokes

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

++++ Message Scanning REF:634-avs2-1311666525 +++++

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not

disseminate, distribute
or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

++++ Message Scanning REF:328-avs3-1311670251 +++++