

---

**From:** Janice Wray <IMCEAEX-\_O=KC+20TMO\_OU=FIRST+20ADMINISTRATIVE+20GROUP\_CN=RECIPIENTS\_CN=JWRAY@GBRP123.PROD.OUTLOOK.COM>  
**Sent:** 19 March 2015 12:02  
**To:** John Tatham  
**Cc:** Claire Williams; Siobhan Rumble  
**Subject:** RE: FW: Urgent !

Thanks - grateful

Janice

---

**From:** John Tatham  
**Sent:** 19 March 2015 12:01  
**To:** Janice Wray  
**Cc:** Claire Williams; Siobhan Rumble  
**Subject:** Re: FW: Urgent !

Janice,

Further to our conversation I have instructed the contractor not to install smoke seals to the doors as instructed.

Regards

John

On 19 Mar 2015 09:50, Janice Wray <[jwray@kctmo.org.uk](mailto:jwray@kctmo.org.uk)> wrote:  
Hi John

Please see below. Would this be the contractor you engaged to progress the FRA actions? Grateful if you could please confirm and contact them urgently to investigate

Please advise

Thanks

Janice


**Janice Wray**  
**TMO Health, Safety & Facilities Manager**

t: [REDACTED]



w: [www.kctmo.org.uk](http://www.kctmo.org.uk)

a: : The Network Hub, 300 Kensal Road, W10 5BE

 Before printing, please think about the environment

---

**From:** Claire Williams

**Sent:** 19 March 2015 09:46

**To:** Janice Wray

**Cc:** CARL STOKES [REDACTED] Siobhan Rumble

**Subject:** FW: Urgent !

Janice

Please see below about poor work at Grenfell to the fire doors.

Who would be doing this?

I don't think the doors should have smoke seals from what Carl has said previously.


**Claire Williams**  
**Project Manager**



t: [REDACTED]

m: [REDACTED]

a: The Network Hub, 292a Kensal Road, London, W10 5BE

 Before printing, please think about the environment

---

**From:** Siobhan Rumble

**Sent:** 19 March 2015 09:45

**To:** 'Simon O'Connor'; Claire Williams

**Cc:** Simon Lawrence

**Subject:** RE: Urgent !

Who's doing this work

**Siobhan Rumble**

**Neighbourhood Manager Lancaster West**

**Income Manager TMO**



---

**From:** Simon O'Connor [<mailto:SOConnor@rydon.co.uk>]

**Sent:** 19 March 2015 09:40

**To:** Claire Williams

**Cc:** Siobhan Rumble; Simon Lawrence

**Subject:** Urgent !

Claire,

We have this morning found someone working on the 15 floor installing smoke seals to staircase doors.

The manner in which they are working is totally unacceptable, please see pictures attached.

The tools you see in the picture are plugged in and fire escape blocked, This presents a huge health and safety risk to the public, We were there for 10 minutes and there was nobody present to discuss this with.

As I'm sure you are aware the residents will automatically presume this is how Rydon work and will only add fuel to the fire.

I would suggest in the future that if you have works of this nature being carried out on the floors Rydon are informed.

Regards

Simon O'Connor, ACIOB, M InstLM  
**Project Manager**

T [REDACTED]  
D [REDACTED]

**Rydon Maintenance Ltd**



This e-mail (including any attachments) is transmitted subject to Rydon Group e-mail terms as published on its [website](#). If you have received this e-mail in error please e-mail the sender by replying to this message. Details of the Company registration numbers and registered offices to which this e-mail relates are also published on its [website](#).

 Please consider the environment before printing this email.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---