James Rudge From: Sent: 21 July 2017 14:37 Janice Wray To:

Subject: FW: Lancaster West Estate.

**Attachments:** 

19098 Allied Hurstway Walk Core 8 JULY 2016.rtf; 19099 Allied Hurstway Walk Core 9 JULY 2016.rtf; 19100 Allied Hurstway Walk Core 10 JULY 2016.rtf; 19101 Allied Hurstway Walk Core 11 JULY 2016.rtf; 19102 ALLIED Hurstway Walk @ Riser 8 HYD AI July 16.doc; 19103 ALLIED Hurstway Walk @ Riser 9 HYD AI July 16.doc; 19104 ALLIED Hurstway Walk @ Riser 10 HYD AI July 16.doc; 19105 ALLIED

Hurstway Walk @ Riser 11 HYD AI July 16.doc; 19098 Allied Hurstway Walk Core 8 JULY 2016.rtf; 19113 Allied Testerton Walk Core 5 JULY 2016.rtf; 19114 Allied Testerton Walk Core 6 JULY 2016.rtf; 19115 Allied Testerton Walk Core 7 JULY 2016.rtf; 19116 ALLIED Testerton Walk @ Riser 6 HYD AI July 16.doc; 19117 ALLIED Testerton Walk @ Riser 7 HYD AI July 16.doc; 19118 ALLIED Barandon Walk @ Riser 2 HYD AI July 16.doc; 19119 Allied Barandon Walk Core 1 JULY 2016.rtf; 19120 Allied Barandon Walk Core 2 JULY 2016.rtf; 19121 Allied Barandon Walk Core 3 JULY 2016.rtf; 19122 Allied Barandon Walk Core 4 JULY 2016.rtf;

20170614161346190.pdf

Further Information. Some may be duplicated, apologies.

James Rudge **Head of Contract Management** Assets and Regeneration Kensington & Chelsea TMO

jrudge@kctmo.org.uk



## www.kctmo.org.uk

292a Kensal Road, London, W10 5BE



Before printing, please think about the environment

From: Mark Mathers [mailto:Mark.Mathers@Alliedprotection.co.uk]

Sent: 21 July 2017 13:48

To: James Rudge < irudge@kctmo.org.uk> Subject: FW: Lancaster West Estate.

Hi James,

As requested,

**Dry Riser, Hydrant** 

I have attached the last sheets we have as they have only been tested again yesterday and I have not received the latest certificates yet.

# **Lightning Protection**

Not provided by us previously (I believe RMA have been completing). We had booked a test for our LP company on the 12<sup>th</sup> of July but had to abort due to access issues, I am awaiting a date for the return visit

### AOV

I have attached the last sheets, as awaiting full information from the last visit by Colt.

#### **Fixed Electrical**

Not provided by us at this point (I believe RMA have been completing).

#### **EML**

We are doing a full test today of all three blocks, as we had to abort testing twice before Waites took over the running of the site. Our Engineer is now inducted to access the controlled end so will be completed in full 21-07-2017.

I believe you are aware that we were overdue on the EML testing at the time of the Grenfell Fire and the Hurstway AOV,, I have also attached the full certificates that were provided by Andy for the complete site including Grenfell in case they are also required, they are the last PDF attachment on this email.

Best regards

Mark Mathers Area Contracts Manager





Allied Protection Ltd Network Hub, 292a Kensal Road, Wandsworth London,,, W10 5BE Tel:

Mob:

www.alliedprotection.co.uk

Disclaimer added by **CodeTwo Exchange Rules 2010** www.codetwo.com

From: Gay Sharman [mailto:gay@firecs.co.uk]

**Sent:** 10 July 2017 12:33

To: Mark Mathers

Subject: Lancaster West Estate.

Hi Mark,

As requested please find attached reports for the above premises,

Regards,

John

Kind Regards

**Gay Sharman** Fire Control Services (UK) Ltd Office Manager

Office:

Email: gay@firecs.co.uk Web: www.firecs.co.uk

Lakehouse Contracts Ltd. Registered in England No. 2603357 Lakehouse Design & Build Ltd. Registered in England No. 4658096



Please don't print this e-mail unless you really need to.