

Message


From: Ryan, Mary X [Mary.Ryan@nationalgrid.com]
Sent: 21/03/2017 12:18:19
To: Johnson, Stephen [/O=AWGPLC/OU=First Administrative Group/cn=Recipients/cn=Johnson, Stephen]
CC: Dolan, Matthew [/O=AWGPLC/OU=First Administrative Group/cn=Recipients/cn=Dolan, Matthew]
Subject: Grenfell Tower
Attachments: 182 Grenfell tower.
Importance: High

Stephen

As we discussed on Friday, Pat has visited Grenfell this morning to review the works completed, paying particular attention to the flats where Holland Gas have undertaken Internal Works.

Flat 182

Fire Escape



Message


From: Ryan, Mary X [Mary.Ryan@nationalgrid.com]
Sent: 21/03/2017 12:18:19
To: Johnson, Stephen [/O=AWGPLC/OU=First Administrative Group/cn=Recipients/cn=Johnson, Stephen]
CC: Dolan, Matthew [/O=AWGPLC/OU=First Administrative Group/cn=Recipients/cn=Dolan, Matthew]
Subject: Grenfell Tower
Attachments: 182 Grenfell tower.
Importance: High

Stephen

As we discussed on Friday, Pat has visited Grenfell this morning to review the works completed, paying particular attention to the flats where Holland Gas have undertaken Internal Works.

Flat 182

Fire Escape



The agreement with the LA was to install the new supply in the fire exit stairwell and box in to meet their evacuation requirements. This has not been completed, although there are ventilation holes throughout the stairwell, which if a fire incident did occur would create a more unsafe situation.

Customers

Pat spoke to all three customers (I think not sure if it is actually six as per Martin's e-mail yesterday) still awaiting restoration of supply, they all complained of the number of broken appointments and length of time off gas – 7 months. He will discuss all of the above with Martin and I think the most appropriate course of action would be for Pat to arrange a tri-partite meeting with the HA at site to walk through the outstanding works and agree timescale for completion.

I don't want to appear overly critical, however, this was all observed over 2 hours this morning but I have not received positive assurance that no other asbestos panels have been drilled at this location to satisfy the HSE. In addition, it further highlights the weakness in the site management and CDM controls.

If I can provide any support, please advise.

Many Thanks

Mary

Mary Ryan

Interface Manager
CMAC
National Grid
London
Mobile: [REDACTED]
E-mail: Mary.Ryan@nationalgrid.com

This e-mail, and any attachments are strictly confidential and intended for the addressee(s) only. The content may also contain legal, professional or other privileged information. If you are not the intended recipient, please notify the sender immediately and then delete the e-mail and any attachments. You should not disclose, copy or take any action in reliance on this transmission.

You may report the matter by contacting us via our [UK Contacts Page](#) or our [US Contacts Page](#) (accessed by clicking on the appropriate link)

The agreement with the LA was to install the new supply in the fire exit stairwell and box in to meet their evacuation requirements. This has not been completed, although there are ventilation holes throughout the stairwell, which if a fire incident did occur would create a more unsafe situation.

Customers

Pat spoke to all three customers (I think not sure if it is actually six as per Martin's e-mail yesterday) still awaiting restoration of supply, they all complained of the number of broken appointments and length of time off gas – 7 months. He will discuss all of the above with Martin and I think the most appropriate course of action would be for Pat to arrange a tri-partite meeting with the HA at site to walk through the outstanding works and agree timescale for completion.

I don't want to appear overly critical, however, this was all observed over 2 hours this morning but I have not received positive assurance that no other asbestos panels have been drilled at this location to satisfy the HSE. In addition, it further highlights the weakness in the site management and CDM controls.

If I can provide any support, please advise.

Many Thanks

Mary

Mary Ryan

Interface Manager
CMAC
National Grid
London
Mobile: [REDACTED]
E-mail: Mary.Ryan@nationalgrid.com

This e-mail, and any attachments are strictly confidential and intended for the addressee(s) only. The content may also contain legal, professional or other privileged information. If you are not the intended recipient, please notify the sender immediately and then delete the e-mail and any attachments. You should not disclose, copy or take any action in reliance on this transmission.

You may report the matter by contacting us via our [UK Contacts Page](#) or our [US Contacts Page](#) (accessed by clicking on the appropriate link)

Please ensure you have adequate virus protection before you open or detach any documents from this transmission.
National Grid plc and its affiliates do not accept any liability for viruses. An e-mail reply to this address may be subject to monitoring for operational reasons or lawful business practices.

For the registered information on the UK operating companies within the National Grid group please use the attached link: <http://www.nationalgrid.com/corporate/legal/registeredoffices.htm>

Please ensure you have adequate virus protection before you open or detach any documents from this transmission.
National Grid plc and its affiliates do not accept any liability for viruses. An e-mail reply to this address may be subject to monitoring for operational reasons or lawful business practices.

For the registered information on the UK operating companies within the National Grid group please use the attached link: <http://www.nationalgrid.com/corporate/legal/registeredoffices.htm>