Message

From: Ray Murray [/O=APEXLIFTS/OU=FIRST ADMINISTRATIVE GROUP/CN=RECIPIENTS/CN=RAYMURRAY]

Sent: 01/07/2015 08:12:37

To: Gary Ager [GaryA@apexlifts.com]

Subject: FW: lift gongs GRENFELL TOWER

Attachments: mfdu50-3hv switches.pdf; Certification

Gary

Sounds like it's the DIL switches, what do you want me to do?

Ray

From: R Leech [mailto:richard@stentorgate.co.uk]

Sent: 29 June 2015 12:25

To: Ray Murray

Subject: RE: lift gongs GRENFELL TOWER

Hi Ray

Thanks for the info.

Not sure what's happening, but it sounds as though the LPI DIL switches need checking. I've attached a sheet showing the settings for this type of indicator. Hope it helps.

Kind regards

Richard Leech

·Stentorgate Ltd







DISCLAIMER: This e-mail is confidential and may contain legally privileged information. If you are not the addressee you must not read, use, distribute, copy or rely on this e-mail. If you have received this communication in error please notify us immediately by replying to this e-mail or by telephone on 01274 560600. The content of this e-mail does not constitute a commitment by Stentorgate Limited. All pricing information contained within e-mails, or attachments are for quotation purposes only. E&OE. Stentorgate Limited believes that this e-mail and any attachments do not contain viruses. However, it is the responsibility of the recipient to ensure it is virus scanned and Stentorgate Limited does not accept any responsibility for any loss or damage that may arise from the use of this e-mail or its contents.

From: Ray Murray [mailto:RayM@apexlifts.com]

Sent: 29 June 2015 10:21

To: R Leech **Cc:** Gary Ager

Subject: RE: lift gongs GRENFELL TOWER

Hi Richard,

Our PO number would be GA 58380 dated 20/4/15

Kind Regards

Ray Murray Repair Sales Consultant















Registered Office: Apex Lifts, ART's House, Banks Lane, Bexleyheath, Kent, DA6 7BH

Telephone No:

Fax No: Mobile No:

Email: raym@apexlifts.com Website: www.apexlifts.com



Disclaimer - June 29, 2015

This e-mail is for the use of the addressee only, and is confidential. Opinions and views presented in this email are solely those of the author and do not necessarily represent those of Apex Lifts. Any distribution, copying or other unauthorised use without prior permission is strictly prohibited. If you receive this message in error please notify Apex Lifts immediately on info@apex-lifts.co.uk
An attachment to this e-mail may contain viruses. Please check before opening the file. The Company will not accept liability for loss or damage that may occur as a result of viruses.



Consider the environment. Please don't print this e-mail unless you really need to

From: R Leech [mailto:richard@stentorgate.co.uk]

Sent: 29 June 2015 10:16

To: Ray Murray

Subject: RE: lift gongs GRENFELL TOWER

Morning Ray

I'd guess it's just the DIL switches that need to be re-set on the LPI's, but I need to trace the job to give you a definite answer.

I can't find a record of the job. Do you have an original p/o and p/o date, please?

Kind regards Richard Leech

Stentorgate Ltd

TEL: www.stentorgate.co.uk









DISCLAIMER: This e-mail is confidential and may contain legally privileged information. If you are not the addressee you must not read, use, distribute, copy or rely on this e-mail. If you have received this communication in error please notify us immediately by replying to this e-mail or by telephone on 01274 560600. The content of this e-mail does not constitute a commitment by Stentorgate Limited. All pricing information contained within e-mails, or attachments are for quotation purposes only. E&OE. Stentorgate Limited believes that this e-mail and any attachments do not contain viruses. However, it is the responsibility of the recipient to ensure it is virus scanned and Stentorgate Limited does not accept any responsibility for any loss or damage that may arise from the use of this e-mail or its contents.

From: Ray Murray [mailto:RayM@apexlifts.com]

Sent: 29 June 2015 09:29

To: R Leech

Subject: FW: lift gongs GRENFELL TOWER

Hi Richard,

Please see email below regarding the lift arrival gongs. Would this be a software issue or just a simple case of setting the dipswitches?

Kind Regards

Ray

Ray Murray Repair Sales Consultant















Registered Office: Apex Lifts, ART's House, Banks Lane, Bexleyheath, Kent, DA6 7BH

Telephone No:

Fax No: Mobile No: Email: raym@apexlifts.com Website: www.apexlifts.com



Disclaimer - June 29, 2015

This e-mail is for the use of the addressee only, and is confidential. Opinions and views presented in this email are solely those of the author and do not necessarily represent those of Apex Lifts. Any distribution, copying or other unauthorised use without prior permission is strictly prohibited. If you receive this message in error please notify Apex Lifts immediately on info@apex-lifts.co.uk An attachment to this e-mail may contain viruses. Please check before opening the file. The Company will not accept liability for loss or damage that may occur as a result of viruses.



Consider the environment. Please don't print this e-mail unless you really need to

From: Simon O'Connor [mailto:SOConnor@rydon.co.uk]

Sent: 29 June 2015 09:23

To: Ray Murray

Cc: Gary Poynter; Gary Ager Subject: RE: lift gongs

Morning Ray,

Do you have any further information on this.

Regards

Simon O'Connor, ACIOB, M InstLM **Project Manager**



From: Gary Ager [mailto:GaryA@apexlifts.com]

Sent: 22 June 2015 08:16

To: Ray Murray

Cc: Simon O'Connor; Gary Poynter

Subject: RE: lift gongs

Ray,

Can you forward the necessary info to Simon please

Many thanks

Gary

Gary Ager **Project Manager**















Registered Office: Apex Lifts, ART's House, Banks Lane, Bexleyheath, Kent, DA6 7BH

Telephone No:

Fax No:

Mobile No:

Email: garya@apexlifts.com Website: www.apexlifts.com



Disclaimer - June 22, 2015

This e-mail is for the use of the addressee only, and is confidential. Opinions and views presented in this email are solely those of the author and do not necessarily represent those of Apex Lifts. Any distribution, copying or other unauthorised use without prior permission is strictly prohibited. If you receive this message in error please notify Apex Lifts immediately on info@apex-lifts.co.uk An attachment to this e-mail may contain viruses. Please check before opening the file. The Company will not accept liability for loss or damage that may occur as a result of viruses.



Consider the environment. Please don't print this e-mail unless you really need to

From: Simon O'Connor [mailto:SOConnor@rydon.co.uk]

Sent: 17 June 2015 14:35

To: Gary Ager Subject: lift gongs

Gary,

Following the works carried out to the lifts at Grenfell the gongs are going off 3 levels below where the lift is arriving as we have added 3 new floors.

Can you please give me a cost for correcting this as it is causing confusion to residents.

Thanks & Regards.

Simon O'Connor, ACIOB, M InstLM



Project Manager



Rydon Group Ltd

Grenfell Tower, Grenfell Road, Notting Barns, W11 1TQ.













This e-mail (including any attachments) is transmitted subject to Rydon Group e-mail terms as published on its <u>website</u>. If you have received this e-mail in error please e-mail the sender by replying to this message. Details of the Company registration numbers and registered offices to which this e-mail relates are also published on its <u>website</u>.

A Please consider the environment before printing this email.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

No virus found in this message.

Checked by AVG - www.avg.com

Version: 2012.0.2250 / Virus Database: 4365/9619 - Release Date: 06/29/15

No virus found in this message. Checked by AVG - www.avg.com

Version: 2012.0.2250 / Virus Database: 4365/9619 - Release Date: 06/29/15