

Message

From: Roome, Jonathan [/o=SGMAIL/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=Roome, Jonathanbb2]
on behalf of Roome, Jonathan [/o=sgmail/ou=exchange administrative group (fydibohf23spdlt)/cn=recipients/cn=roome, jonathanbb2]
Sent: 22/10/2014 23:03:19
To: DL-UK-Celotex SalesTeam [dl-uk-celotexsalesteam@saint-gobain.com]
CC: Berger, Debbie (dberger@celotex.co.uk) [dberger@celotex.co.uk]; Evans, Paul [pevans@celotex.co.uk]
Subject: RS5000 - NHBC & BBA Argumentation
Importance: High

Hi Team,

If any of you find yourself in conversations regarding a need for a BBA certificate for use of RS5000 on NHBC jobs you may want to be made aware of the following;

The NHBC (in their own guidance notes on Curtain Wall & Cladding) Part 6, Chapter 6.9 (PAGE 6) state that;

Rainscreen cladding

CERTIFICATION

6.9 - D7 Rainscreen cladding systems shall be designed and certificated in accordance with appropriate Standards

"Rainscreen cladding systems, including panels, should have current certification confirming satisfactory assessment by an appropriate independent technical approvals authority accepted by NHBC, including: British Board of Agrément (BBA) **or Building Research Establishment (BRE) Certification.**"

- I have attached a copy of the NHBC Chapter 6 Guidance on Curtain Wall & Cladding.

RS5000 is not classed as a whole system but neither would any other individual component. As far as I know, no one company manufactures a complete rainscreen system.

I hope that you can reference to this document to help counter the argument for the need of a BBA for RS5000 on NHBC projects.

Kind regards,
Jonathan

Jonathan Roome

Major Projects and Specification Manager

jroome@celotex.co.uk

Mob: [REDACTED]

Celotex. Reaching new heights



Celotex Limited, Lady Lane Industrial Estate, Hadleigh, Ipswich, Suffolk, IP7 6BA
Celotex Limited is registered in England with Company number 2183896.
Registered Office: Saint-Gobain House, Binley Business Park, Coventry, CV3 2TT.

celotex.co.uk

 **@Celotex**



Please consider the environment before printing this email