

Harley Curtain Wall

Envelope Package

Schedule of Information

- Specifications

- Grenfell Tower BREEAM Pre-assessment Report rev C
- Section A Preliminaries
- Section B Specification and Design requirements
- KCTMO Code of Conduct
- Appendix A - Part L Building Regulations

- Architect Drawings

- 1279 SEA (00) 011
- 1279 SEA (00) 012
- 1279 SEA (00) 100
- 1279 SEA (02) 010
- 1279 SEA (02) 030
- 1279 SEA (02) 031
- 1279 SEA (02) 040
- 1279 SEA (02) 041
- 1279 SEA (04) 100
- 1279 SEA (04) 101
- 1279 SEA (04) 102
- 1279 SEA (04) 103
- 1279 SEA (04) 104
- 1279 SEA (04) 105
- 1279 SEA (04) 108
- 1279 SEA (04) 109
- 1279 SEA (04) 120
- 1279 SEA (04) 121
- 1279 SEA (04) 122
- 1279 SEA (04) 123
- 1279 SEA (04) 124
- 1279 SEA (04) 200
- 1279 SEA (04) 201
- 1279 SEA (04) 202
- 1279 SEA (04) 203
- 1279 SEA (04) 204
- 1279 SEA (04) 205
- 1279 SEA (05) 100
- 1279 SEA (05) 101
- 1279 SEA (05) 102
- 1279 SEA (05) 103
- 1279 SEA (05) 110
- 1279 SEA (05) 111
- 1279 SEA (05) 112

1279	SEA	(05)	113
1279	SEA	(05)	114
1279	SEA	(05)	115
1279	SEA	(05)	116
1279	SEA	(05)	117
1279	SEA	(05)	118
1279	SEA	(05)	200
1279	SEA	(05)	210
1279	SEA	(05)	211
1279	SEA	(06)	100
1279	SEA	(06)	101
1279	SEA	(06)	103
1279	SEA	(06)	104
1279	SEA	(06)	105
1279	SEA	(06)	110
1279	SEA	(06)	112
1279	SEA	(06)	113
1279	SEA	(06)	120
1279	SEA	(06)	121
1279	SEA	(06)	122
1279	SEA	(08)	100
1279	SEA	(08)	101
1279	SEA	(22)	100
1279	SEA	(32)	100
1279	SEA	(32)	101
1279	SEA	(32)	102
1279	SEA	(32)	Door schedule
1279	SEA	(34)	100
1279	SEA	(35)	101
1279	SEA	(35)	102
1279	SEA	(35)	103
1279	SEA	(35)	104
1279	SEA	(35)	105
1279	SEA	(42)	100
1279	SEA	(42)	200
1279	SEA	(43)	100
1279	SEA	(43)	101
1279	SEA	(43)	110
1279	SEA	(72)	100
1279	SEA	(72)	101
1279	SEA	(72)	102
1279	SEA	(72)	104
1279	SEA	(72)	105
1279	SEA	(74)	
1279	SEA	(79)	100

- Engineers Drawings

DC	001	Structural Design Criteria
L01212	002	
L01212	003	
L01212	005	

L01212 006  
L01212 009  
L01212 012  
L01212 SPEC 002  
L01212 SPEC 003  
L01212 SPEC 004  
L01212 SPEC 005  
L01212 SPEC 001  
L01212 DR01

- Asbestos surveys
  - Asbestos report Grenfell Tower 29.05.12
  - Asbestos Survey 145 Grenfell
  - Communal management survey Grenfell Tower jul 11
  - Grenfell nursery
  - Grenfell Tower social services complex
  - Dale Youth Boxing club
  - Grenfell Tower social services complex
  - ST30902-91 Grenfell tower
  
- CAN Concrete Testing J3L2685-GREN-RP01
  
- Microfiche Survey Drawings
  - Clifford Wearden 1971
  - Floyd Slaski 1992
  - RBKC 1979
  
- RSK Intrusive investigation report 285438-01 Grenfell Tower
  
  
- ZM email with attachments to Mark Harris of Harley dated 18/06/14
  - Appendix 6a - Grenfell Traffic Management plan
  - Appendix B - RML Standard Terms
  - Appendix C -The Rydon Way
  - Appendix D - Pre Contract interview
  - Appendix H - Payment schedule
  - Subcontractor questionnaire and declaration

Drawings:

  - DWG W1 Scaffold and Mast Climber
  - DWG E1 Scaffold and Mast Climber
  - DWG N1 Scaffold and Mast Climber
  - DWG S1 Scaffold and Mast Climber
  - DWG P1 (REV 20.1.14) Scaffold and Mast Climber