Message	
From:	Mark Harris [/O=FIRST ORGANIZATION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MARKH]
Sent:	18/06/2014 16:00:53
То:	Simon Lawrence [slawrence@rydon.co.uk]
CC:	Mike Albiston [/O=FIRST ORGANIZATION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MikeAlbiston]
Subject:	RE: Grenfell Tower

Thanks Simon

Once we've spoken with Tom, I'll provide some feedback on what was said.

Regards

From: Simon Lawrence [slawrence@rydon.co.uk] Sent: 18 June 2014 15:28 To: Mark Harris Subject: FW: Grenfell Tower

Hi Mark,

Following our discussion about Green Deal installers etc I've had a conversation with Tom Elliott of Rockwool (see bottom email) and given him your details to discuss products and how it will fit within the grant funding. He seems very helpful, as you would expect when trying to sell a product, but also knows about grant funding. We may need to get a relationship with him and Reynobond if any grant funding is to be achieved.

He could also be a very good contact for all of us in the future as he only deals with the occupied tower block works so will know probably before any of us who's getting work done.

Regards

Simon Lawrence, ACIOB, MInstLM Contracts Manager



From: Claire Williams [mailto:clwilliams@kctmo.org.uk] Sent: 16 June 2014 09:17 To: Simon Lawrence Subject: FW: Grenfell Tower

Simon

Just had contact from the below. FYI.

Claire Williams Project Manager

HAR00005834_0001

HAR00005834/1



t: m: a: The Network Hub, 292a Kensal Road, London, W10 5BE Before printing, please think about the environment

From: Tom Elliott (RW-UK/G) [mailto:Tom.Elliott@rockwool.com] Sent: 16 June 2014 08:50 To: Claire Williams Subject: Grenfell Tower

Good morning Claire,

Hope you are well. David Ring from Just Energy Solutions has passed me your details, further to a meeting we had last week.

I work within Rockwool's Refurbishment & Regeneration team which is focused on supporting in the delivery of new build and external thermal refurbishment schemes through the application of stone wool insulation systems, and we have developed a product suite so that we are able to offer a whole building solution including external wall insulation and rain-screen cladding systems.

All stone wool insulation comes with a euro class fire rating of A1, and therefore our systems are particularly suited to high-rise refurbishment in accordance with BR 135. I was hoping to enquire whether any specification had yet been set for the insulated rainscreen being installed on the Grenfell Tower refurbishment.

Our systems have been used on the Edward Wood Estate next to Westfield in Shepherd's Bush, and our London office is in Hammersmith so I would welcome the opportunity to meet and discuss further.

Any information would be much appreciated.

Best regards, Tom

Tom Elliott

Business Development Manager

ROCKWOOL

M: tom.elliott@rockwool.com

www.rockwoolsolutions.co.uk

26-28 Hammersmith Grove | London | W6 7HA | UK

HAR00005834_0002



A Please consider the environment before printing out this email.

This e-mail message has been scanned for Viruses and Content and cleared by MailMarshal

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential

information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute

or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent

those of Kensington & Chelsea TMO Ltd Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

HAR00005834_0003

HAR00005834/3