

GRENFELL TOWER INQUIRY

EXHIBIT SM/06 TO WITNESS STATEMENT OF SENER MACIT

Repair No.	UPRN	Address Line 1	Address Line 2	Address Line 3	Postcode	Property Type Code	Location code	Current Stage	Current Stage Name	Logged Date	Stage 35 date (on site completion)	Admin complete date	Priority code	Reptype code	Workfor ce code	Workfor ce Name	Cancel reason	Original commitment £	Current commitment £	Repair description
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVED	12/05/2017	12/05/2017	12/05/2017	OH	WORK	ISP	KCTMO REPAIRS DIRECT		£90	£68	18E 12 05 17 17:04 P 17 21 WC CISTERN LEAK
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	NOTE	5	TICKET PRINTED	24/03/2017			2	WORK	SOCI	SOCI ALPHATRA JOLLIU		£77	£77	REPAIR COMMUNAL TV AERIAL
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	19	APPOINTMENT BOOKED	15/05/2016			U	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	07824904558 - REMEDY LEAKING PIPE UNDER WHB
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVED	31/08/2016	13/02/2016	13/10/2016	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	07804942175 - LEAKING HOT WATER TAP IN WHB
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	99	FULLY PAY APPROVED	20/08/2016	20/08/2016	09/09/2016	OH	WORK	ISP	KCTMO REPAIRS DIRECT		£68	£58	OOH 650 200816 20/08/16 @ 16.29 LEAKING PIPE
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	1	RECORD CREATED	05/05/2016				COMP						EMAIL SENT TO PARKING
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVED	28/04/2016	10/05/2016	06/06/2016	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	BROKEN SINK TO BASE UNIT UNDER THE KITCHEN SINK
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	99	FULLY PAY APPROVED	03/02/2016	29/02/2016	21/03/2016	N	WORK	ISP	KCTMO REPAIRS DIRECT		£87	£487	DECORATION TO BATHROOM AND SEPERATE WC
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVED	27/11/2015	07/12/2015	14/01/2016	N	WORK	ISP	KCTMO REPAIRS DIRECT		£11	£189	TENANT REPORTS COLD TAP IS DRIPPING VALVE MIGHT NOT BE ABLE
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	NOTE	85	FULLY ABANDONED	06/11/2015		22/03/2016	N	WORK	ISP	KCTMO REPAIRS DIRECT	OTHR	£163	£153	FOLLOWING WORKS TAKING PLACE BATHROOM CEILING NEEDS PAINTING
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	BED	1	RECORD CREATED	04/11/2015				COMP						OOH 21686894 30/10/15 @ 22.28 RAD IN BEDROOM NOT WORKING
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	59	FULLY PAY APPROVED	02/11/2015	06/11/2015	21/01/2016	N	WORK	ISP	KCTMO REPAIRS DIRECT		£0	£50	RECALL TO 201535975 - KITCHEN TAP STILL LEAKING
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	85	FULLY ABANDONED	02/11/2015		31/04/2016	N	WORK	ISP	KCTMO REPAIRS DIRECT	C40R	£0	£0	RECALL TO 201535975 - KITCHEN TAPS STILL LEAKING
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	13	NO ACCESS	19/10/2015			N	WORK	ISP	KCTMO REPAIRS DIRECT		£163	£163	FOLLOWING WORKS TAKING PLACE BATHROOM CEILING NEEDS PAINTING
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	39	FULLY PAY APPROVED	19/10/2015	23/10/2015	09/11/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	KITCHEN SEAL NEAR TAP HAS A LEAK MAY NEED NEW RUBBER OR
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	59	FULLY PAY APPROVED	16/10/2015	22/10/2015	10/11/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£154	WC HANDLE IS BROKEN OFF PLS FIX AND TAKE PICS OF CISTERN TINT
2.02E+08	U217012770233	FLAT 133 GREENFELL TOWER	LANCASTER WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVED	03/07/2015	08/07/2015	22/07/2015	J	WORK	ISP	KCTMO REPAIRS DIRECT		£56	£129	RENEW TAPS IN WHB, SEE PREVIOUS JOB 201514237

2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	13/06/2015	03/07/2015	20/07/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£56	£56	THE WR TAPS WILL NEED TO BE REPLACED IN THE BATH-ROOM AS
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVE D	13/06/2015	18/06/2015	10/07/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	LOW WATER PRESSURE IN KITCHEN & BATHROOM PLS INVESTIGATE
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BOIL	5	TICKET PRINTED	02/06/2015			E	WORK	UTIL	EMER (COFELY)		£0	£0	UNCONTAINABLE PIPE LEAK FROM BOILER
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	NOTE	99	FULLY PAY APPROVE D	02/06/2015	05/06/2015	25/06/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	BATH TAPS ARE NOT WORKING PROPERLY
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	10	SENT VIA CONT 1	20/05/2015			E	WORK	KTH-S	R & T HEATING SERVICES LTD		£0	£0	LEAKING FROM HEATING PIPES IS CAUSING RUSTING TO TANK
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	NOTE	99	FULLY PAY APPROVE D	07/05/2015	19/05/2015	03/06/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	NEW BALL VALVE IS NEEDED REPORTED BY FLAT 133
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	NOTE	99	FULLY PAY APPROVE D	30/04/2015	07/05/2015	27/05/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£64	KITCHEN UNIT'S CUPBOARDS: (CUPBOARD; CUPBOARD DAMAGED); BASE U
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	NOTE	99	FULLY PAY APPROVE D	20/04/2015	07/05/2015	27/05/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£168	KITCHEN TAP IS CONTINUOUSLY DROPPING
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	27/04/2015	05/05/2015	27/05/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£93	REPLACE BATH PANEL AFTER LEAK AS SWOLLEN
2.02E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRL	1	RECORD CREATED	27/04/2015				COMP						PEST CONTROL (INSECTS UNKNOWN)
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	13/03/2015	13/03/2015	22/04/2015	E	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£72	BATHS WASTE LEAKING, UNCONTAINABLE; FAIR WEAR AND TEAR (OR
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	FDOO	99	FULLY PAY APPROVE D	26/01/2015	02/02/2015	17/03/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£57	ELECTRIC POWER: DOOR BELL: MAINS WIRED; FAIR WEAR AND TEAR (
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	FDOO	99	FULLY PAY APPROVE D	25/01/2015	19/03/2015	23/04/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£266	FRONT DOOR LOCK HANDLE DOESNT LIFT TO LOCK
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	23/01/2015	27/01/2015	11/02/2015	N	WORK	ISP	KCTMO REPAIRS DIRECT		£71	£184	BROKEN HOT WATER BATH TAP
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVE D	08/01/2015	08/01/2015	13/02/2015	E	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£143	KITCHEN AND BATHROOM LIGHTS ARE NOT WORKING
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	COM	99	FULLY PAY APPROVE D	30/09/2014		22/12/2014	P3	WORK	RHAS	R & PA STEWART LTD		£72	£145	REPAIR 4 COMMUNAL LIGHTS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	COM	99	FULLY PAY APPROVE D	30/09/2014		09/12/2014	P3	WORK	RHAS	R & PA STEWART LTD		£16	£43	LIGHT BETWEEN FLAT 24 AND 25 IS OUT

2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	30/09/2014	01/10/2014	17/10/2014	F	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	ELECTRIC LIGHTING: INTERNAL LIGHTING; FLOURESCBENT LIGHT FLIC
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	16/08/2014	24/08/2014	17/08/2014	U	WORK	ISP	KCTMO REPAIRS DIRECT		£61	£79	BLOCKED STACK AFFECTING KITCHEN
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	22/04/2014	22/04/2014	10/05/2014	E	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£155	PIPES: PIPES, LEAKING; UNCONTAINABLE; WATER SUPPLY; FAIR WEA
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	13/01/2014	14/02/2014	20/03/2014	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£626	FLOORS: FLOOR TILES; KITCHEN ; VINYL SHEETING; FAIR WEAR AND
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	URM	99	FULLY PAY APPROVE D	23/11/2013	31/12/2013	06/02/2014	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£30	ILLU RUC LIGHTING: INTERNAL LIGHTING; FLOURESCBENT LIGHT FLIC
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		1	RECORD CREATED	10/11/2013				COMP						INSPECT THE FLOORING THE KITCHEN .20YEARS OLD
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	NOTE	99	FULLY PAY APPROVE D	15/11/2013	18/11/2013	03/02/2014	CH	WORK	ISP	KCTMO REPAIRS DIRECT		£68	£67	DO-H CALL NO. 1504119 15/11/2013 047:00
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITC	99	FULLY PAY APPROVE D	17/10/2013	16/12/2013	07/03/2014	N	INSP	ISP	KCTMO REPAIRS DIRECT		£730	£1,840	DISREPAIR TO KITCHEN CABINETS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	HALL	99	FULLY PAY APPROVE D	25/09/2013	01/10/2013	18/01/2014	N	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	ELECTRIC LIGHTING: INTERNAL LIGHTING; LAMPHOLDER LOOSE OR BR
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	21/09/2013	21/09/2013	12/12/2013	CH	WORK	ISP	KCTMO REPAIRS DIRECT		£50	£50	DO-H:1682792 LEAKING TOILET
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	HALL	85	FULLY ABANDON ED	06/09/2013		04/07/2014	N	WORK	ISP	KCTMO REPAIRS DIRECT	CBRO	£50	£50	ELECTRIC LIGHTING: INTERNAL LIGHTING; LAMPHOLDER LOOSE OR BR
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	HALL	99	FULLY PAY APPROVE D	06/09/2013		06/09/2013	N	WVTO	ISP	KCTMO REPAIRS DIRECT		£50	£50	ELECTRIC LIGHTING: INTERNAL LIGHTING; LAMPHOLDER LOOSE OR BR
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	15/07/2013	12/07/2013		CH	WORK	WOP	WILL NOT T DIXON PARTNERS HQS:LT		£14	£14	DO-H:1661769 REPAIR LEAK TO WC PAN SOIL AND FLUSH PIPE
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		1	RECORD CREATED	05/12/2012				COMP						INTERNAL DOOR COMING OFF - HINGES - TENANTS RESPONSIBILITY
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	EXT	1	RECORD CREATED	12/06/2012				COMP						NEWLY FITTED DOOR HAVE NOT BEEN FITTED PROPERLY
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	06/06/2012	11/06/2012		N	WORK	WORK	MORRISON FACILITIES SERVICES		£15	£61	INSPECT FOR BLOCKAGE TO BASIN

2.01E+06	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	01/03/2012	09/03/2012	21/03/2012	N	WORK	MORR	MORRISO N FACILIT S SERVICES		E11	E67	REPAIR LEAK TO WC PAN SOIL AND FLUSH PIPE
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	22/02/2012	28/02/2012	01/03/2012	N	WORK	MORR	MORRISO N FACILIT S SERVICES		E6	E57	EASE AND ADJUST INTERNAL DOOR
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	1	RECORD CREATED	12/12/2011			2	WORK	BNWH	E - ENVIRON MENTAL HEALTH BROOK		E9	E9	PEST CONTROL TREATMENT
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVE D	23/11/2011	09/12/2011	18/01/2012	U	WORK	MORR	MORRISO N FACILIT S SERVICES		E13	E24	FULLY OVERHAUL AND REPAIR A PAIR OF TAPS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	15/11/2011	17/11/2011	08/12/2011	N	WORK	MORR	MORRISO N FACILIT S SERVICES		E14	E14	OVERHAUL REPAIR REFIX ADJUST OR RENEW ALL CISTERN PARTS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	17/10/2011	24/10/2011	26/10/2011	N	WORK	MORR	MORRISO N FACILIT S SERVICES		E31	E42	TAKE OUT AND REPLACE BATH PANEL
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	1	RECORD CREATED	25/05/2011			2	WORK	BNWH	E - ENVIRON MENTAL HEALTH BROOK		E0	E6	PEST CONTROL TREATMENT - BED BUGS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	28/04/2010	29/04/2010	24/02/2011	U	WORK	MORR	MORRISO N FACILIT S SERVICES		E13	E13	OVERHAUL REPAIR REFIX ADJUST OR RENEW ALL CISTERN PARTS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		5	TICKET PRINTED	05/01/2010			1	WORK	UTEL	ENGIE (COFFEY)		E3	E0	RADIATORS IN HALLWAY AND BATHROOM NOT WORKING
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	20/11/2009		22/01/2010	C	WORK	ABWN	CONNAUG HT PLC (NORTH)		E51	E51	OVERHAUL CISTERN HANDLE IS BROKEN
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	08/09/2008		12/02/2009	A	WORK	ABWN	CONNAUG HT PLC (NORTH)		E51	E165/E27	OVERHAUL REPAIR REFIX ADJUST OR RENEW ALL CISTERN PARTS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	65	FULLY ABANDON ED	08/09/2008		08/09/2008	B	WORK	LWHM	LANCASTE R WEST HANDYMA N	CADR	E0	E0	OVERHAUL REPAIR REFIX ADJUST OR RENEW ALL CISTERN PARTS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	04/09/2008		24/12/2008	E	WORK	ABWN	CONNAUG HT PLC (NORTH)		E44	E44	INSPECT FOR BLOCKAGE TO BASIN

2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	08/01/2008	11/04/2008	19/05/2008	A	WORK	AEWN	CONNAUG HT PLC (NORTH)		£60	£60	ORDER FOR CALLOUT 28.03.08 LEAKING WC
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVE D	13/12/2007		01/02/2008	D	WORK	AEWN	CONNAUG HT PLC (NORTH)		£167	£167	REPAIRS TO KITCHEN WORK TOP & BASE UNITS AS INSP BY CONTRACT
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVE D	06/12/2007		23/02/2010	JN	UNSP	LWHM	LANCASTER R WEST HANDYMAN				INSPECT TILES NEXT TO KITCHEN SINK
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	17/05/2007		05/07/2007	E4	WORK	UTTL	ENGIE (CORPSEY)		£68	£73	E PRIORITY OUTSIDE NORMAL WORKING HOURS TOILET, OR PARTIAL
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	07/03/2007		23/02/2010	D	WORK	LWHM	LANCASTER R WEST HANDYMAN		£0	£0	INSPECT FOR LEAK TO SINK
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	21/02/2007		23/02/2010	D	WORK	LWHM	LANCASTER R WEST HANDYMAN		£0	£0	TO RENEW CYLINDER TO EXISTING CYLINDER LOCK. PROVIDE 2 KEYS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	24/01/2007	30/01/2007	20/02/2007	D	WORK	AEWN	CONNAUG HT PLC (NORTH)		£601	£601	TO REPLACE BATHROOM AND KITCHEN PANEL
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	18/09/2006		12/10/2006	C	WORK	AEWN	CONNAUG HT PLC (NORTH)		£35	£51	AS CODE BLE002 TO RESPOND AND MAKE SAFE WITHIN 4 HOURS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	05/12/2005	06/12/2005	04/01/2006	D	WORK	AEWN	CONNAUG HT PLC (NORTH)		£51	£51	OVERHAUL. REPAIR REFLEX ADJUST OR RENEW ALL CISTERN PARTS
2.01E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	14/07/2005	26/07/2005	03/10/2005	B	WORK	AEWN	CONNAUG HT PLC (NORTH)		£35	£35	AS CODE BLE002 TO RESPOND AND MAKE SAFE WITHIN 4 HOURS
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVE D	13/12/2004	30/12/2004	28/01/2005	B	WORK	AEWN	CONNAUG HT PLC (NORTH)		£35	£35	AS CODE BLE002 TO RESPOND AND MAKE SAFE WITHIN 4 HOURS
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	99	FULLY PAY APPROVE D	08/11/2004	15/11/2004	17/12/2004	B	WORK	AEWN	CONNAUG HT PLC (NORTH)		£35	£35	LIGHT PULL IN BATH ROOM NEEDS RENEWING
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	KITCH	99	FULLY PAY APPROVE D	24/09/2004	12/10/2004	11/11/2004	B	WORK	AEWN	CONNAUG HT PLC (NORTH)		£65	£65	RENEW A PAIR OF TAPS IN KITCHEN
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	99	FULLY PAY APPROVE D	08/09/2004		20/10/2004	E	WORK	IMPR	IMP (NORTHERN) LTD		£0	£56	E CALL OUT 0930-1700 EXCL BANK HOLIDAYS TOTAL OR PARTIAL
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	1	RECORD CREATED	07/09/2004				COMP						HANDY PERSON LEAK ON WHB
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	10/02/2004	19/02/2004	11/03/2004	1	WORK	AEWN	CONNAUG HT PLC (ORIGINAL)		£50	£60	REMOVE CABINET THEN REPAIR FOR TWP
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA		99	FULLY PAY APPROVE D	23/12/2003	06/01/2004	06/02/2004	E	WORK	AEWN	CONNAUG HT PLC (ORIGINAL)		£51	£61	LOCATE LEAK ON SUPPLY REPAIR OR RENEW PIPE REMAKE JOINTS

2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	99	FULLY PAY APPROVE D	15/12/2003	22/03/2004	31/03/2004	E4	WORK	ABWI	CONNAUG HT PLC (ORIGINAL 1)		£60	£60	CONCEALED LEAK IN FLAT EMERGENCY CALL OUT ROB/PAUL
2E+09	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	99	FULLY PAY APPROVE D	02/10/2003		03/11/2005	1	WORK	RDUN	R DUNHAM UK LTD		£26	£89	ELECTRIC SOCKETS BROKEN IN 3 ROOMS
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	THRU	99	FULLY PAY APPROVE D	02/10/2003	16/12/2003	05/01/2004	2	WORK	ABWI	CONNAUG HT PLC (ORIGINAL 1)		£65	£133	2 WINDOW LOCKS NEED REPLACING BEDROOM AND LIVING ROOM
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	BATH	98	FULLY PAY APPROVE D	29/09/2003		03/10/2003	1	WORK	ABWI	CONNAUG HT PLC (ORIGINAL 1)		£25	£28	REFER TO INVOICE K2142881 SL5.02 COMPLETED
2E+08	U2170127 70233	FLAT 133 GRENFELL TOWER	LANCASTER R WEST ESTATE	LONDON	W11 1TQ	DFLA	EXT	99	FULLY PAY APPROVE D	07/05/2003		25/07/2003	1	WORK	ABWI	CONNAUG HT PLC (ORIGINAL 1)		£119	£119	RENEW ASSA LOCK TO PED