

**Incoming Email**  
from

dhughes@rydon.co.uk

on  
24/03/2016 11:13

Create Mail Reply

File Ref 1 Email filing exercise

File Ref 2

File Ref 3

To: "Batty,Tony (tbatty@silcockdawson.co.uk)" <tbatty@silcockdawson.co.uk>

cc: "M.Smith@maxfordham.com" <M.Smith@maxfordham.com>; "Jon White" (jwhite@jrp.co.uk) <jwhite@jrp.co.uk>; "alanwhyte@jswright.co.uk" <alanwhyte@jswright.co.uk>; "andy@rjelectrics.co.uk" <andy@rjelectrics.co.uk>

Subject: FW: Grenfell Tower- Building Control Sie inspection 24th March 2016

**Associated Documents**

created by: **Michael McMillan** on 24-Mar-16

Hi Tony

Please see e-mail below from Building Control regarding fire detection in the hub room

I will still try to get a response from Terry Ashton at Exova

Kind regards

Dave

-----Original Message-----

From: John.Allen@rbkc.gov.uk [mailto:John.Allen@rbkc.gov.uk]

Sent: 24 March 2016 11:09

To: David Hughes

Cc: John.Hoban@rbkc.gov.uk

Subject: RE: Grenfell Tower- Building Control Sie inspection 24th March 2016

David, under the Building Regulations we will not require a detector within the electrical cupboard that you pointed out. This was off the lobby to the ground floor community room.

John Allen

Building Control Manager

The Royal Borough of Kensington and Chelsea The Town Hall, Hornton Street, London W8 7NX

Tel: [REDACTED] | Mob: [REDACTED]

Email: john.allen@rbkc.gov.uk | Website: www.rbkc.gov.uk

-----Original Message-----

From: David Hughes [mailto:dhughes@rydon.co.uk]

Sent: 24 March 2016 10:05

To: Allen, John: CP-Plan

Cc: Hoban, John: CP-Plan

Subject: RE: Grenfell Tower- Building Control Sie inspection 24th March 2016

Hi John





delete the material from your computer.

\*\*\*\*\*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---