

Sent: Wed, 23 Oct 2013 15:09:21 +0100
From: Bruce Sounes <bruce@studioe.co.uk>
To: Claire Williams <clwilliams@kctmo.org.uk>, BOOTH Philip <philip.booth@uk.arteliagroup.com>, Chweecheen Lim <chweecheen.lim@appleyards.co.uk>
Cc: "M.Smith@maxfordham.com" <m.smith@maxfordham.com>, "r.marshall@davidbonnett.co.uk" <r.marshall@davidbonnett.co.uk>, "a.pottinger@davidbonnett.co.uk" <a.pottinger@davidbonnett.co.uk>, "Tom Ashton (Tom.Ashton@curtins.com)" <tom.ashton@curtins.com>, Grenfell <grenfell@studioe.co.uk>
Subject: Grenfell - Updated Layouts.

[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)
[.png](#)

Dear All,

Further to the numerous conversations on the layouts please see attached our current set of plans as PDF and dwg.

Claire,

- Contrary to my previous understanding Exova are cautious about taking the main fire escape through the entrance lobby. Perhaps the external door shown could be on a fail-safe magnetic lock with intercom and fob access? This is subject to Building Control.
- Proposed locations for dry risers shown at Mezz and Walkway.

· The proposal is not to offer the Mezzanine tenants access to the chute.
A complicated hopper and additional mech vent would be required. See attached
SK096 (pse ignore mezz plan - this was sent to Hardall for comment.)

· Existing escape stair retained.

· I'm awaiting feedback from Bonnetts on the boxing club accessible
change.

Regards

Bruce Sounes

For and on behalf of

STUDIO E LLP

Palace Wharf, Rainville Road, London W6 9HN

T [REDACTED] | F [REDACTED] | www.studioe.co.uk

